

Estates (1970s-2000s)

Ref: EST

University Archives, Special Collections

University Library, Cambridge Road, Portsmouth, PO1 2ST

Collection deposited directly by the Estates and Campus Services Department. It has been catalogued as a separate collection for ease of access and because the material originates from both Portsmouth Polytechnic and the University of Portsmouth.

Contents:

Location	Title	Date	Pages
EST/1	Photographs, negatives and slides	1970 - 2000s	3 - 221
	<u>1/1</u> <u>Alphabetical Files of Site Photographs</u>	<u>1990s - [2002]</u>	3-142
	1. Alexandra House to Eldon Site	1990s - [2000]	
	2. Frewen Library to Lion Gate	1990s	
	3. Mercantile House to Purbeck Street	1990s	
	4. Ravelin Site to Wiltshire	1990s - [2002]	
	5. Miscellaneous and Environmental	1990s	
	<u>1/2</u> <u>Series of Photographic Prints</u>	<u>1970 - 2001</u>	143-193
	1. King Henry Building under Construction	1970 - 1971	
	2. Portsmouth Building Society [later University House]	1986	
	3. Park Building Upper Hall	1999	
	4. Park Building Galleon Weathervane	1980s	
	5. Park Building stonework	1970s?	
	6. St Michael's Building and Burnaby Building	1980s	
	7. St Michael's Building	1996	
	8. Rees Hall (Old)	[1995]	

Reference	Description	Date	Shelf Mark
9.	Rees Hall (New)	[1996]	
10.	Various University of Portsmouth Buildings 1	1990s?	
11.	Eldon Building	[2000]	
12.	Burnaby Building fire damage	2000	
13.	Portland, University of Portsmouth Bus and Langstone Campus	1990s	
14.	Langstone playing fields	1997	
15.	Environment [Ravelin Park meadow, planting and University of Portsmouth Bus]	1997-[2001]	
16.	Various Portsmouth Polytechnic buildings	1980s	
17.	Bikeabout scheme?	1990s?	
18.	Various University of Portsmouth buildings 2	1997-1998	
<u>1/3</u>	<u>Albums</u>	<u>1990s</u>	194-197
<u>1/4</u>	<u>Miscellaneous Loose Photographic Prints</u>	<u>1970s-1990s</u>	198-208
<u>1/5</u>	<u>Slides</u>	<u>1990s</u>	209-220
<u>1/6</u>	<u>Photocopies</u>		221
EST/2	Architectural plans and drawings	[To be catalogued]	

Reference	Description	Date	Shelf Mark
EST/1	Photographs, negatives and slides	1970s – 2000s	
EST/1/1	Alphabetical files of site photographs	1990s – [2002]	
	These photographs were originally stored in files, and each file had a title. The titles of the files have been retained e.g. 'Alexandra Hse to Eldon site'. Within each file, photographs were divided into series. The titles each series have also been kept e.g. 'Anglesea Refurbishment mid 90s' as well as the original order of the photographs.		
EST/1/1/1	'Alexandra Hse to Eldon site'	1990s-[2000]	
<i>Anglesea Refurbishment mid 90s</i>			
EST/1/1/1/1	Photograph of side exterior of Anglesea Building with man in cherry picker looking at building Undated 550mmx760mm (1 photograph)	1990s	BM01-RRB1
EST/1/1/1/2	Photograph of front exterior of Anglesea Building with two cars and van parked outside – view from Anglesea Road pavement Undated 550mmx760mm (1 photograph)	1990s	BM01-RRB1
EST/1/1/1/3	Photograph of front exterior of Anglesea Building with three vehicles parked outside Undated 550mmx760mm (1 photograph)	1990s	BM01-RRB1
EST/1/1/1/4	Photograph of interior hallway in Anglesea Building with three men working Undated 550mmx760mm (1 photograph)	1990s	BM01-RRB1
EST/1/1/1/5	Photograph of interior hallway in Anglesea Building with three men working at the end of the hallway Undated 550mmx760mm (1 photograph)	1990s	BM01-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/1/6	Photograph of side exterior of Anglesea Building with scaffolding and two people walking away from camera Undated 550mmx760mm (1 photograph)	1990s	BM01-RRB1
EST/1/1/1/7	Photograph of side exterior of Anglesea Building with scaffolding and building materials Undated 550mmx760mm (1 photograph)	1990s	BM01-RRB1
EST/1/1/1/8	Photograph of [rear?] exterior of Anglesea Building with building materials Undated 550mmx760mm (1 photograph)	1990s	BM01-RRB1
EST/1/1/1/9	Photograph of interior room in Anglesea Building [canteen?] with tables and chairs Undated 550mmx760mm (1 photograph)	1990s	BM01-RRB1
EST/1/1/1/10	Photograph of front exterior of Anglesea Building with man putting material in skip Undated 400mmx460mm (1 photograph)	1990s	BM01-RRB1
EST/1/1/1/11	Photograph of [rear?] exterior of Anglesea Building taken from steps Undated 550mmx760mm (1 photograph)	1990s	BM01-RRB1
EST/1/1/1/12	Photograph of interior room in Anglesea Building. with silver pipes and fridge Undated 400mmx460mm (1 photograph)	1990s	BM01-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/1/13	Photograph of [side?] exterior of Anglesea Building with scaffolding Undated 400mmx460mm (1 photograph)	1990s	BM01-RRB1
EST/1/1/1/14	Photograph of side exterior of Anglesea Building with skip Undated 400mmx460mm (1 photograph)	1990s	BM01-RRB1
EST/1/1/1/15	Photograph of interior room in Anglesea Building with stepladder and a sheet covering [furniture?] Undated 400mmx460mm (1 photograph)	1990s	BM01-RRB1
EST/1/1/1/16	Photograph of interior hallway in Anglesea Building Undated 400mmx460mm (1 photograph)	1990s	BM01-RRB1
EST/1/1/1/17	Photograph of room in Anglesea Building - empty except for two metal storage units Undated 400mmx460mm (1 photograph)	1990s	BM01-RRB1
EST/1/1/1/18	Photograph of interior room in Anglesea Building - sheets covering computers equipment and furniture Undated 400mmx460mm (1 photograph)	1990s	BM01-RRB1
EST/1/1/1/19	Photograph of interior hallway in Anglesea Building with lockers along left wall Undated 400mmx460mm (1 photograph)	1990s	BM01-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/1/20	Photograph of interior hallway in Anglesea Building with double doors being installed Undated 400mmx460mm (1 photograph)	1990s	BM01-RRB1
EST/1/1/1/21	Photograph of interior hallway in Anglesea Building with two planks of wood leaning against left wall Undated 400mmx460mm (1 photograph)	1990s	BM01-RRB1
EST/1/1/1/22	Photograph of interior room in Anglesea Building with red pipes and ladder leaning against wall Undated 400mmx460mm (1 photograph)	1990s	BM01-RRB1
EST/1/1/1/23	Photograph of interior room in Anglesea Building with red pipes running up left wall and along ceiling Undated 400mmx460mm (1 photograph)	1990s	BM01-RRB1
EST/1/1/1/24	Photograph of interior hallway in Anglesea Building during refurbishment with two men at the far end of the hallway Undated 400mmx460mm (1 photograph)	1990s	BM01-RRB1
EST/1/1/1/25	Photograph of interior hallway in Anglesea Building during refurbishment with sheeting tied to pipes on upper wall Undated 400mmx460mm (1 photograph)	1990s	BM01-RRB1
EST/1/1/1/26	Photograph of room in Anglesea Building with sheeting covering furniture and pipes exposed Undated 400mmx460mm (1 photograph)	1990s	BM01-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/1/27	Photograph of floor of hallway in Anglesea Building [metal?] floor coverings painted white Undated 400mmx460mm (1 photograph)	1990s	BM01-RRB1
EST/1/1/1/28	Photograph of hallway in Anglesea Building with building tools and black metal pipes on floor Undated 400mmx460mm (1 photograph)	1990s	BM01-RRB1
EST/1/1/1/29	Photograph of interior room in Anglesea Building [plant?] room with silver pipes leading out Undated 400mmx460mm (1 photograph)	1990s	BM01-RRB1
EST/1/1/1/30	Photograph of interior hallway in Anglesea Building with red and white cones surrounding blue door Undated 400mmx460mm (1 photograph)	1990s	BM01-RRB1
EST/1/1/1/31	Photograph of interior room in Anglesea Building left wall showing copper piping and open blue door Undated 400mmx460mm (1 photograph)	1990s	BM01-RRB1
EST/1/1/1/32	Photograph of side exterior of Anglesea Building partially covered in scaffolding with van parked outside Undated 400mmx460mm (1 photograph)	1990s	BM01-RRB1
EST/1/1/1/33	Photograph of roof of Anglesea Building with a man walking and looking at camera Undated 400mmx460mm (1 photograph)	1990s	BM01-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/1/34	Photograph of side exterior and roof of Anglesea Building partially covered in scaffolding Undated 400mmx460mm (1 photograph)	1990s	BM01-RRB1
EST/1/1/1/35	Photograph of roof of Anglesea Building with two men working Undated 400mmx460mm (1 photograph)	1990s	BM01-RRB1
EST/1/1/1/36	Photograph of side exterior of Anglesea Building with green van and skip filled with materials Undated 400mmx460mm (1 photograph)	1990s	BM01-RRB1
EST/1/1/1/37	Photograph of exterior roof of Anglesea Building with three men working on right Undated 400mmx460mm (1 photograph)	1990s	BM01-RRB1
EST/1/1/1/38	Photograph of exterior roof of Anglesea Building with one man working on left Undated 400mmx460mm (1 photograph)	1990s	BM01-RRB1
EST/1/1/1/39	Photograph of exterior roof of Anglesea Building with red fuel tanks and sheeting covering wood Undated 400mmx460mm (1 photograph)	1990s	BM01-RRB1
EST/1/1/1/40	Photograph of side exterior of Anglesea Building with one man visible on roof Undated 400mmx460mm (1 photograph)	1990s	BM01-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/1/41	Photograph taken from roof of Anglesea Building looking towards Burnaby Building Undated 570mmx830mm (2 copies of the photograph)	1990s	BM01-RRB1
EST/1/1/1/42	Photograph taken from roof of Anglesea Building looking towards Park Building and Guildhall clock Undated 570mmx830mm (2 copies of the photograph)	1990s	BM01-RRB1
EST/1/1/1/43	Photograph of roof of Anglesea Building [side of air ventilation system?] Undated 570mmx830mm (3 copies of the photograph)	1990s	BM01-RRB1
EST/1/1/1/44	Photograph of exterior roof of Anglesea Building [air ventilation system?] Undated 570mmx830mm (1 photograph)	1990s	BM01-RRB1
EST/1/1/1/45	Photograph of exterior roof of Anglesea Building [rear view of air ventilation system?] Undated 570mmx830mm (1 photograph)	1990s	BM01-RRB1
EST/1/1/1/46	Photograph taken from roof of Anglesea Building with Zurich Building in background Undated 570mmx830mm (1 photograph)	1990s	BM01-RRB1
EST/1/1/1/47	Photograph of exterior roof of Anglesea Building with the A3 on the right side looking towards the dockyard Undated 570mmx830mm (1 photograph)	1990s	BM01-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/1/48	Photograph of exterior roof of Anglesea Building facing building with rounded front Undated 570mmx830mm (1 photograph)	1990s	BM01-RRB1
EST/1/1/1/49	Photograph of exterior roof of Anglesea Building with Zurich Building in the background Undated 570mmx830mm (1 photograph)	1990s	BM01-RRB1
EST/1/1/1/50	Photograph of side exterior of Anglesea Building with cars parked outside. Undated 570mmx830mm (1 photograph)	1990s	BM01-RRB1
EST/1/1/1/51	Photograph of exterior roof of Anglesea Building with Sarah Robinson House visible in the background Undated 570mmx830mm (1 photograph)	1990s	BM01-RRB1
EST/1/1/1/52	Photograph of exterior roof of Anglesea Building with one man working at the far end of the roof Undated 570mmx830mm (1 photograph)	1990s	BM01-RRB1
EST/1/1/1/53	Photograph of the exterior roof of Anglesea Building with the top of Burnaby Building and Sarah Robinson House visible Undated 570mmx830mm (1 photograph)	1990s	BM01-RRB1
EST/1/1/1/54	Photograph of interior lecture theatre in Anglesea building with red seating Undated 400mmx470mm (1 photograph)	1990s	BM01-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/1/55	Photograph of interior lecture theatre in Anglesea building during refurbishment with a man working on stairs Undated 400mmx470mm (1 photograph)	1990s	BM01-RRB1
EST/1/1/1/56	Photograph of interior lecture theatre in Anglesea Building with red seating Undated 400mmx470mm (1 photograph)	1990s	BM01-RRB1
EST/1/1/1/57	Photograph of a lecture theatre in Anglesea Building during refurbishment with a man crouched writing in centre Undated 400mmx470mm (1 photograph)	1990s	BM01-RRB1
EST/1/1/1/58	Photograph of interior hallway in Anglesea Building during refurbishment - view towards front entrance- with a man measuring flooring? Undated 400mmx470mm (1 photograph)	1990s	BM01-RRB1
EST/1/1/1/59	Photograph of a lecture theatre in Anglesea Building with green seating – view from side Undated 400mmx470mm (1 photograph)	1990s	BM01-RRB1
EST/1/1/1/60	Photograph of a lecture theatre in Anglesea Building with green seating – view from side towards lectern, television monitors and blackboards at front Undated 400mmx470mm (1 photograph)	1990s	BM01-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/1/61	<p>Photograph of a lecture theatre in Anglesea building under construction with three men installing green seating</p> <p>Undated</p> <p>400mmx470mm</p> <p>(1 photograph)</p>	1990s	BM01-RRB1
EST/1/1/1/62	<p>Photograph of a lecture theatre in Anglesea Building during refurbishment with two men installing green seating</p> <p>Undated</p> <p>400mmx470mm</p> <p>(1 photograph)</p>	1990s	BM01-RRB1
EST/1/1/1/63	<p>Photograph of a lecture theatre in Anglesea Building during refurbishment with a man on a ladder working on the ceiling</p> <p>Undated</p> <p>400mmx470mm</p> <p>(1 photograph)</p>	1990s	BM01-RRB1
EST/1/1/1/64	<p>Photograph of a lecture theatre in Anglesea Building with green seating</p> <p>Undated</p> <p>400mmx470mm</p> <p>(1 photograph)</p>	1990s	BM01-RRB1
EST/1/1/1/65	<p>Photograph of a lecture theatre in Anglesea Building with two men on scaffolding working on the ceiling</p> <p>Undated</p> <p>400mmx470mm</p> <p>(1 photograph)</p>	1990s	BM01-RRB1
EST/1/1/1/66	<p>Photograph of interior hallway in Anglesea Building with a man crouched working on flooring</p> <p>Undated</p> <p>400mmx470mm</p> <p>(1 photograph)</p>	1990s	BM01-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/1/67	Photograph of a lecture theatre in Anglesea Building under construction with one man installing green seating Undated 400mmx470mm (1 photograph)	1990s	BM01-RRB1
EST/1/1/1/68	Photograph of a lecture theatre in Anglesea Building during refurbishment with a man writing and another looking at windows Undated 400mmx470mm (1 photograph)	1990s	BM01-RRB1
EST/1/1/1/69	Photograph of exterior side of Anglesea Building with green netting across top scaffolding Undated 400mmx470mm (1 photograph)	1990s	BM01-RRB1
EST/1/1/1/70	Photograph of exterior side of Anglesea Building covered in scaffolding with two men working on roof Undated 400mmx470mm (1 photograph)	1990s	BM01-RRB1
EST/1/1/1/71	Photograph of interior room of Anglesea Building with coat hooks along wall during refurbishment Undated 400mmx470mm (1 photograph)	1990s	BM01-RRB1
EST/1/1/1/72	Photograph of interior hallway of Anglesea Building with lockers on left wall and student walking away from the camera Undated 400mmx470mm (1 photograph)	1990s	BM01-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/1/73	Photograph of exterior rear of Anglesea Building covered in scaffolding with three vehicles parked Undated 400mmx470mm (1 photograph)	1990s	BM01-RRB1
EST/1/1/1/74	Photograph of exterior rear of Anglesea Building with two men working on scaffolding installing windows Undated 400mmx470mm (1 photograph)	1990s	BM01-RRB1
EST/1/1/1/75	Photograph of exterior rear of Anglesea Building with a man wearing lab coat walking away from the camera Undated 400mmx470mm (1 photograph)	1990s	BM01-RRB1
EST/1/1/1/76	Photograph of exterior front of Anglesea Building In close up with a group of students near entrance Undated 400mmx470mm (1 photograph)	1990s	BM01-RRB1
EST/1/1/1/77	Photograph of exterior front and side of Anglesea building with students stood outside - view from pavement in Anglesea Road Undated 400mmx470mm (1 photograph)	1990s	BM01-RRB1
EST/1/1/1/78	Photograph of exterior rear of Anglesea Building with scaffolding and ladder leaning against building Undated 400mmx470mm (1 photograph)	1990s	BM01-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/1/79	Photograph of an office in Anglesea Building [ground floor?] with staff working at computers Undated 400mmx470mm (1 photograph)	1990s	BM01-RRB1
EST/1/1/1/80	Photograph of interior room in Anglesea Building with a wooden ramp next to some steps Undated 400mmx470mm (1 photograph)	1990s	BM01-RRB1
EST/1/1/1/81	Photograph of interior hallway in Anglesea Building with a broom propped against lockers on the left wall and a man carrying a white container Undated 400mmx470mm (1 photograph)	1990s	BM01-RRB1
EST/1/1/1/82	Photograph of exterior [side?] of Anglesea Building Undated 400mmx470mm (1 photograph)	1990s	BM01-RRB1
EST/1/1/1/83	Photograph of exterior side of Anglesea Building Undated 400mmx470mm (1 photograph)	1990s	BM01-RRB1
EST/1/1/1/84	Photograph of interior hallway of Anglesea Building with lockers on the left wall Undated 400mmx470mm (1 photograph)	1990s	BM01-RRB1
EST/1/1/1/85	Photograph of exterior front of Anglesea Building green netting covering all scaffolding and two people standing outside Undated 400mmx470mm (1 photograph)	1990s	BM01-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/1/86	<p>Photograph of interior room in Anglesea Building during refurbishment, scaffolding and black chair at end of room</p> <p>Undated</p> <p>400mmx470mm</p> <p>(1 photograph)</p>	1990s	BM01-RRB1
EST/1/1/1/87	<p>Photograph of interior room in Anglesea Building [canteen?] green mop in middle of photograph</p> <p>Undated</p> <p>400mmx470mm</p> <p>(1 photograph)</p>	1990s	BM01-RRB1
EST/1/1/1/88	<p>Photograph of interior room in Anglesea Building silver ladder leaning against wall with copper pipes exposed</p> <p>Undated</p> <p>400mmx470mm</p> <p>(1 photograph)</p>	1990s	BM01-RRB1
EST/1/1/1/89	<p>Photograph of interior room in Anglesea Building blue door with fridge on the right marked 'Dark Room Do Not Enter' and piping exposed</p> <p>Undated</p> <p>400mmx470mm</p> <p>(1 photograph)</p>	1990s	BM01-RRB1
EST/1/1/1/90	<p>Photograph of interior hallway in Anglesea Building with two red cones and two planks on the stairs</p> <p>Undated</p> <p>400mmx470mm</p> <p>(1 photograph)</p>	1990s	BM01-RRB1
EST/1/1/1/91	<p>Photograph of exterior [side?] of Anglesea Building with blue car parked on the right and low scaffolding in centre</p> <p>Undated</p> <p>400mmx470mm</p> <p>(1 photograph)</p>	1990s	BM01-RRB1
EST/1/1/1/92	<p>Photograph of interior room in Anglesea Building with man in red coat using machinery</p> <p>Undated</p> <p>400mmx470mm</p> <p>(1 photograph)</p>	1990s	BM01-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/1/93	<p>Photograph of interior room in Anglesea Building during refurbishment with grey chair on the right</p> <p>Undated</p> <p>400mmx470mm</p> <p>(1 photograph)</p>	1990s	BM01-RRB1
EST/1/1/1/94	<p>Photograph of exterior roof of Anglesea Building with wood and plastic and tarpaulin on the floor</p> <p>Undated</p> <p>400mmx470mm</p> <p>(1 photograph)</p>	1990s	BM01-RRB1
EST/1/1/1/95	<p>Photograph of exterior [side?] of Anglesea Building with red van parked on the left and skip in the centre</p> <p>Undated</p> <p>400mmx470mm</p> <p>(1 photograph)</p>	1990s	BM01-RRB1
EST/1/1/1/96	<p>Photograph of interior hallway of Anglesea Building with building equipment in the centre marked off by red tape</p> <p>Undated</p> <p>400mmx470mm</p> <p>(1 photograph)</p>	1990s	BM01-RRB1
EST/1/1/1/97	<p>Photograph of interior hallway of Anglesea Building with lockers along the left wall and three cones on the floor</p> <p>Undated</p> <p>400mmx470mm</p> <p>(1 photograph)</p>	1990s	BM01-RRB1
EST/1/1/1/98	<p>Photograph of exterior front of Anglesea Building with two skips and three men standing outside</p> <p>Undated</p> <p>400mmx470mm</p> <p>(1 photograph)</p>	1990s	BM01-RRB1
EST/1/1/1/99	<p>Photograph of interior hallway in Anglesea Building with wooden pallet propped on the left and lockers along the right wall</p> <p>Undated</p> <p>400mmx470mm</p> <p>(1 photograph)</p>	1990s	BM01-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/1/100	<p>Photograph of interior hallway of Anglesea Building with lockers on the left wall and building equipment on the right</p> <p>Undated</p> <p>400mmx470mm</p> <p>(1 photograph)</p>	1990s	BM01-RRB1
EST/1/1/1/101	<p>Photograph of exterior side of Anglesea Building with two skips and two vans outside</p> <p>Undated</p> <p>400mmx470mm</p> <p>(1 photograph)</p>	1990s	BM01-RRB1
EST/1/1/1/102	<p>Photograph of exterior roof of Anglesea Building</p> <p>Ventilation system partially constructed</p> <p>Undated</p> <p>400mmx470mm</p> <p>(1 photograph)</p>	1990s	BM01-RRB1
EST/1/1/1/103	<p>Photograph of a lecture theatre in Anglesea building with red seating</p> <p>Undated</p> <p>400mmx470mm</p> <p>(1 photograph)</p>	1990s	BM01-RRB1
EST/1/1/1/104	<p>Photograph of exterior roof of Anglesea Building with red fuel tank and blue tarpaulin covering materials</p> <p>Undated</p> <p>400mmx470mm</p> <p>(1 photograph)</p>	1990s	BM01-RRB1
EST/1/1/1/105	<p>Photograph of a lecture theatre in Anglesea Building during refurbishment, two ladders and men working in room</p> <p>Undated</p> <p>400mmx470mm</p> <p>(1 photograph)</p>	1990s	BM01-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/1/106	Photograph of a lecture theatre in Anglesea Building during refurbishment one man crouched on floor and rolled up carpet on stairs Undated 400mmx470mm (1 photograph)	1990s	BM01-RRB1
EST/1/1/1/107	Photograph of a lecture theatre in Anglesea Building during refurbishment with two men working Undated 400mmx470mm (1 photograph)	1990s	BM01-RRB1
EST/1/1/1/108	Photograph of a lecture theatre in Anglesea Building with red seating - view from front Undated 400mmx470mm (1 photograph)	1990s	BM01-RRB1

Reference	Description	Date	Shelf Mark
<i>Buckingham Building Demolition of Huts</i>			
EST/1/1/1/109	Photograph of side exterior of Burnaby Building with demolition vehicle on cleared site of huts Undated 130mmx190mm (1 photograph)	[2000]	BM01-RRB1
EST/1/1/1/110	Photograph of side exterior of Burnaby Building with demolition vehicle on cleared site of huts Undated 400mmx470mm (1 photograph)	[2000]	BM01-RRB1
EST/1/1/1/111	Photograph of side and rear exterior Burnaby Building with demolition vehicle on cleared site of huts Undated 400mmx470mm (1 photograph)	[2000]	BM01-RRB1
EST/1/1/1/112	Photograph of rear exterior of Burnaby Building with demolition vehicle on cleared site of huts Undated 400mmx470mm (1 photograph)	[2000]	BM01-RRB1
EST/1/1/1/113	Photograph of side and rear exterior Burnaby Building with demolition vehicle on cleared site of huts Undated 400mmx470mm (1 photograph)	[2000]	BM01-RRB1
EST/1/1/1/114	Photograph of side exterior of Burnaby Building with demolition vehicle on cleared site of huts Undated 400mmx470mm (1 photograph)	[2000]	BM01-RRB1

Reference	Description	Date	Shelf Mark
<i>Burnaby Demolition J Huts</i>			
EST/1/1/1/115	Photograph of huts under demolition by Hughes and Salvidge demolition vehicle with back of Anglesea Building visible in back ground Undated 127mmx180mm (1 photograph)	[1999]	BM01-RRB1
EST/1/1/1/116	Photograph of huts under demolition by Hughes and Salvidge demolition vehicle with back of Anglesea Building visible in back ground Undated 127mmx180mm (1 photograph)	[1999]	BM01-RRB1
EST/1/1/1/117	Photograph of huts under demolition by Hughes and Salvidge demolition vehicle Undated 127mmx180mm (1 photograph)	[1999]	BM01-RRB1
EST/1/1/1/118	Photograph of huts under demolition by Hughes and Salvidge demolition vehicle with one men spraying the huts with water Undated 127mmx180mm (1 photograph)	[1999]	BM01-RRB1
EST/1/1/1/119	Photograph of huts under demolition by Hughes and Salvidge demolition vehicle with one man spraying the huts with water Undated 127mmx180mm (1 photograph)	[1999]	BM01-RRB1
EST/1/1/1/120	Photograph of huts under demolition by Hughes and Salvidge demolition vehicle with one man spraying the huts with water Undated 127mmx180mm (1 photograph)	[1999]	BM01-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/1/121	Photograph of huts under demolition with view from inside building, facing demolition vehicle Undated 127mmx180mm (1 photograph)	[1999]	BM01-RRB1
EST/1/1/1/122	Photograph of huts under demolition by Hughes and Salvidge demolition vehicle with one man spraying huts with water Undated 127mmx180mm (1 photograph)	[1999]	BM01-RRB1
EST/1/1/1/123	Photograph of huts under demolition by Hughes and Salvidge demolition vehicle with one man spraying huts with water Undated 127mmx180mm (1 photograph)	[1999]	BM01-RRB1
EST/1/1/1/124	Photograph of huts under demolition by Hughes and Salvidge demolition vehicle with one man spraying huts with water Undated 127mmx180mm (1 photograph)	[1999]	BM01-RRB1
EST/1/1/1/125	Photograph of huts under demolition by Hughes and Salvidge demolition vehicle with one man spraying huts with water Undated 127mmx180mm (1 photograph)	[1999]	BM01-RRB1
EST/1/1/1/126	Photograph of huts under demolition by Hughes and Salvidge demolition vehicle Undated 127mmx180mm (1 photograph)	[1999]	BM01-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/1/127	Photograph of huts under demolition by Hughes and Salvidge demolition vehicle Undated 127mmx180mm (1 photograph)	[1999]	BM01-RRB1
EST/1/1/1/128	Photograph of huts under demolition by Hughes and Salvidge demolition vehicle with one man spraying huts with water Undated 127mmx180mm (1 photograph)	[1999]	BM01-RRB1
EST/1/1/1/129	Photograph of huts under demolition by Hughes and Salvidge demolition vehicle with one man spraying huts with water Undated 127mmx180mm (1 photograph)	[1999]	BM01-RRB1
EST/1/1/1/130	Photograph of huts under demolition by Hughes and Salvidge demolition vehicle. Undated 127mmx180mm (1 photograph)	[1999]	BM01-RRB1

Reference	Description	Date	Shelf Mark
<i>Burnaby Huts</i>			
EST/1/1/1/131	Photograph of exterior of a Burnaby hut with yellow door and red fire extinguisher Undated 130mmx175mm (1 photograph)	[2000]	BM02-RRB1
EST/1/1/1/132	Photograph of [front?] exterior of Burnaby huts taken from grass area, white door facing camera Undated 130mmx175mm (1 photograph)	[2000]	BM02-RRB1
EST/1/1/1/133	Photograph of interior teaching room of Burnaby huts with wooden chairs and tables and a projector and blackboard at the back of the room Undated 130mmx175mm (1 photograph)	[2000]	BM02-RRB1
EST/1/1/1/134	Photograph of interior teaching room of Burnaby huts with wooden chairs and tables and a projector and blackboard at the back of the room Undated 130mmx175mm (1 photograph)	[2000]	BM02-RRB1
EST/1/1/1/135	Photograph of exterior of a Burnaby hut with a purple car parked to the left of the photograph and a blue parked on the right Undated 130mmx175mm (1 photograph)	[2000]	BM02-RRB1
EST/1/1/1/136	Photograph of exterior of Burnaby hut with tall windows covered in dust Undated 130mmx175mm (1 photograph)	[2000]	BM02-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/1/137	Photograph of exterior of a Burnaby hut showing a close up of a bottom corner of the building with paint worn away from the edges Undated 130mmx175mm (1 photograph)	[2000]	BM02-RRB1
EST/1/1/1/138	Photograph of exterior of a Burnaby hut showing rotting wood Undated 130mmx175mm (1 photograph)	[2000]	BM02-RRB1
EST/1/1/1/139	Photograph of interior room of a Burnaby hut showing stacked wooden and plastic chairs Undated 130mmx175mm (1 photograph)	[2000]	BM02-RRB1
EST/1/1/1/140	Photograph of interior room of a Burnaby hut showing stacked wooden and plastic chairs Undated 130mmx175mm (1 photograph)	[2000]	BM02-RRB1
EST/1/1/1/141	Photograph of interior staircase of a Burnaby hut with a wooden table on the right and a green cabinet on the left Undated 130mmx175mm (1 photograph)	[2000]	BM02-RRB1
EST/1/1/1/142	Photograph of interior room of a Burnaby hut showing open double doors leading outside Undated 130mmx175mm (1 photograph)	[2000]	BM02-RRB1
EST/1/1/1/143	Photograph of interior room of a Burnaby hut with a blue door with a number 10 on it and cardboard boxes stacked on the right Undated 130mmx175mm (1 photograph)	[2000]	BM02-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/1/144	Photograph of exterior of Burnaby huts with a yellow door Undated 130mmx175mm (1 photograph)	[2000]	BM02-RRB1
EST/1/1/1/145	Photograph of rear exterior of Burnaby huts taken from under a tree across the road with low wall in front of building Undated 130mmx175mm (1 photograph)	[2000]	BM02-RRB1
EST/1/1/1/146	Photograph of side exterior of Burnaby huts with a grey door Undated 130mmx175mm (1 photograph)	[2000]	BM02-RRB1
EST/1/1/1/147	Photograph of exterior side of Burnaby huts with brown shed visible at far end Undated 130mmx175mm (1 photograph)	[2000]	BM02-RRB1
EST/1/1/1/148	Photograph of exterior of Burnaby huts with red door on right and signs reading 'TO-1' and 'TO-2/3' Undated 130mmx175mm (1 photograph)	[2000]	BM02-RRB1
EST/1/1/1/149	Photograph of exterior of Burnaby huts with piece of scrap wood resting against building Undated 130mmx175mm (1 photograph)	[2000]	BM02-RRB1
EST/1/1/1/150	Photograph of front exterior of Burnaby huts with tree on the right and a yellow door Undated 130mmx175mm (1 photograph)	[2000]	BM02-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/1/151	Photograph of front exterior of Burnaby huts with red door closed and white doors open Undated 130mmx175mm (1 photograph)	[2000]	BM02-RRB1
EST/1/1/1/152	Photograph of exterior front of Burnaby huts with sign partially visible reading 'parking' and grey double doors Undated 130mmx175mm (1 photograph)	[2000]	BM02-RRB1
EST/1/1/1/153	Photograph of exterior front of a Burnaby hut with two white vans parked outside Undated 130mmx175mm (1 photograph)	[2000]	BM02-RRB1
EST/1/1/1/154	Photograph of side exterior of Burnaby huts with a white van partially visible Undated 130mmx175mm (1 photograph)	[2000]	BM02-RRB1
EST/1/1/1/155	Photograph of side exterior of Burnaby huts with wooden boards over windows Undated 130mmx175mm (1 photograph)	[2000]	BM02-RRB1
EST/1/1/1/156	Photograph of side exterior of Burnaby huts with grey box on the wall and an [air vent]? above Undated 130mmx175mm (1 photograph)	[2000]	BM02-RRB1
EST/1/1/1/157	Photograph of toilets[?] in Burnaby huts with three sinks under a [soap dispenser?] and a small mirror on the right Undated 130mmx175mm (1 photograph)	[2000]	BM02-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/1/158	<p>Photograph of exterior of Burnaby huts with double doors closed under a low extended roof</p> <p>Undated</p> <p>130mmx175mm</p> <p>(1 photograph)</p>	[2000]	BM02-RRB1
EST/1/1/1/159	<p>Photograph of exterior of Burnaby huts with cardboard boxes on the floor to the right</p> <p>Undated</p> <p>130mmx175mm</p> <p>(1 photograph)</p>	[2000]	BM02-RRB1
EST/1/1/1/160	<p>Photograph of front exterior of Burnaby huts with metal railing on bottom left and white box on wall at far end</p> <p>Undated</p> <p>130mmx175mm</p> <p>(1 photograph)</p>	[2000]	BM02-RRB1
EST/1/1/1/161	<p>Photograph of exterior side and front of Burnaby huts with yellow door and three steps leading up to it</p> <p>Undated</p> <p>130mmx175mm</p> <p>(1 photograph)</p>	[2000]	BM02-RRB1
EST/1/1/1/162	<p>Photograph of exterior front of Burnaby huts with two yellow doors and a fire extinguisher box with the door removed and lying on the ground</p> <p>Undated</p> <p>130mmx175mm</p> <p>(1 photograph)</p>	[2000]	BM02-RRB1
EST/1/1/1/163	<p>Photograph of exterior of Burnaby huts</p> <p>Undated</p> <p>130mmx175mm</p> <p>(1 photograph)</p>	[2000]	BM02-RRB1
EST/1/1/1/164	<p>Photograph of exterior side and front of Burnaby Huts with yellow door and three steps leading Up to it</p> <p>Undated</p> <p>130mmx175mm</p> <p>(1 photograph)</p>	[2000]	BM02-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/1/165	<p>Photograph of exterior of Burnaby huts showing door with a sign reading 'GO-26'</p> <p>Undated</p> <p>130mmx175mm</p> <p>(1 photograph)</p>	[2000]	BM02-RRB1
EST/1/1/1/166	<p>Photograph of rear exterior of Burnaby huts with large cardboard box at far end</p> <p>Undated</p> <p>130mmx175mm</p> <p>(1 photograph)</p>	[2000]	BM02-RRB1
EST/1/1/1/167	<p>Photograph of front exterior of Burnaby huts with flowers growing in front</p> <p>Undated</p> <p>130mmx175mm</p> <p>(1 photograph)</p>	[2000]	BM02-RRB1
EST/1/1/1/168	<p>Photograph of side exterior of Burnaby huts with a yellow door</p> <p>Undated</p> <p>130mmx175mm</p> <p>(1 photograph)</p>	[2000]	BM02-RRB1
EST/1/1/1/169	<p>Photograph of side exterior of Burnaby huts with a yellow door and steps leading up to it</p> <p>Undated</p> <p>130mmx175mm</p> <p>(1 photograph)</p>	[2000]	BM02-RRB1
EST/1/1/1/170	<p>Photograph of rear and side exterior of Burnaby huts with four small windows open and Burnaby Building visible behind it</p> <p>Undated</p> <p>130mmx175mm</p> <p>(1 photograph)</p>	[2000]	BM02-RRB1
EST/1/1/1/171	<p>Photograph of exterior of Burnaby huts with door open</p> <p>Undated</p> <p>130mmx175mm</p> <p>(1 photograph)</p>	[2000]	BM02-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/1/172	<p>Photograph of exterior of Burnaby huts with one open window and a brown closed door with a bucket on the floor</p> <p>Undated</p> <p>130mmx175mm</p> <p>(1 photograph)</p>	[2000]	BM02-RRB1
<i>Burnaby Terrace</i>			
EST/1/1/1/173	<p>Photograph of front exterior of Burnaby Terrace with three men and a woman walking past</p> <p>Undated</p> <p>130mmx190mm</p> <p>(1 photograph)</p>	[1999?]	BM02-RRB1
EST/1/1/1/174	<p>Photograph of front exterior of Burnaby Terrace taken from the other side of Burnaby Road with two white car parked on the left and a yellow bicycle chained to railings</p> <p>Undated</p> <p>130mmx190mm</p> <p>(1 photograph)</p>	[1999?]	BM02-RRB1
EST/1/1/1/175	<p>Photograph of front and side exterior of Burnaby Terrace with Buckingham Building visible in background</p> <p>Undated</p> <p>130mmx190mm</p> <p>(1 photograph)</p>	[1999?]	BM02-RRB1
EST/1/1/1/176	<p>Photograph of interior room of Burnaby Terrace with seven people sat around a table on red chairs</p> <p>Undated</p> <p>130mmx190mm</p> <p>(1 photograph)</p>	[1999?]	BM02-RRB1
EST/1/1/1/177	<p>Photograph of interior room in Burnaby Terrace with 11 people sat around a table on red chairs</p> <p>Undated</p> <p>130mmx190mm</p> <p>(1 photograph)</p>	[1999?]	BM02-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/1/178	Photograph of an I.T. suite in Burnaby Terrace with red chairs and people working at the back of the room Undated 130mmx190mm (1 photograph)	[1999?]	BM02-RRB1
EST/1/1/1/179	Photograph of an I.T. suite in Burnaby Terrace with red chairs and people working at the back of the room Undated 130mmx190mm (1 photograph)	[1999?]	BM02-RRB1
EST/1/1/1/180	Photograph of front exterior of Burnaby Terrace taken from the other side of Burnaby Road with two white car parked on the left and a yellow bicycle chained to railings 130mmx190mm (1 photograph)	[1999?]	BM02-RRB1
EST/1/1/1/181	Photograph of interior hallway in Burnaby Terrace with a white staircase on the right and a door with a sign reading 'BT 0/15 MEETING ROOM' Undated 130mmx190mm (1 photograph)	[1999?]	BM02-RRB1
EST/1/1/1/182	Photograph of front exterior of Burnaby Terrace with Buckingham Building, Portland Building and Milldam visible in background Undated [prior to construction of Richmond Building] 130mmx190mm (1 photograph)	[1999?]	BM02-RRB1

Reference	Description	Date	Shelf Mark
<i>Cambridge Building Demolitions</i>			
EST/1/1/1/183	Photograph of Cambridge Building during demolition with Mercantile House visible in the background Undated 130mmx180mm (1 photograph)	[1999]	BM02-RRB1
EST/1/1/1/184	Photograph of Cambridge Building during demolition with Mercantile House visible in the background Undated 130mmx180mm (1 photograph)	[1999]	BM02-RRB1
EST/1/1/1/185	Photograph of Cambridge Building with a demolition vehicle putting wood into a skip and Mercantile House visible in the background Undated 130mmx180mm (1 photograph)	[1999]	BM02-RRB1
EST/1/1/1/186	Photograph of Cambridge Building during demolition with Mercantile House visible in the background Undated 130mmx180mm (1 photograph)	[1999]	BM02-RRB1
EST/1/1/1/187	Photograph of Cambridge Building during demolition with Mercantile House visible in the background Undated 130mmx180mm (1 photograph)	[1999]	BM02-RRB1
EST/1/1/1/188	Photograph of Cambridge Building during demolition with Mercantile House visible in the background Undated 130mmx180mm (1 photograph)	[1999]	BM02-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/1/189	<p>Photograph of Cambridge Building during demolition with Mercantile House visible in the background</p> <p>Undated</p> <p>130mmx180mm</p> <p>(1 photograph)</p>	[1999]	BM02-RRB1
EST/1/1/1/190	<p>Photograph of Cambridge Building during demolition with Mercantile House visible in the background</p> <p>Undated</p> <p>130mmx180mm</p> <p>(1 photograph)</p>	[1999]	BM02-RRB1
EST/1/1/1/191	<p>Photograph of Cambridge Building during demolition with Mercantile House visible in the background</p> <p>Undated</p> <p>130mmx180mm</p> <p>(1 photograph)</p>	[1999]	BM02-RRB1
EST/1/1/1/192	<p>Photograph of Cambridge Building during demolition with Mercantile House visible in the background</p> <p>Undated</p> <p>130mmx180mm</p> <p>(1 photograph)</p>	[1999]	BM02-RRB1
EST/1/1/1/193	<p>Photograph of Cambridge Building during demolition with Mercantile House visible in the background</p> <p>Undated</p> <p>130mmx180mm</p> <p>(1 photograph)</p>	[1999]	BM02-RRB1
EST/1/1/1/194	<p>Photograph of exterior of Cambridge Building fenced off before demolition</p> <p>Undated</p> <p>130mmx180mm</p> <p>(1 photograph)</p>	[1999]	BM02-RRB1
EST/1/1/1/195	<p>Photograph of interior room in Cambridge Building with seven doors propped up against the right wall</p> <p>Undated</p> <p>130mmx180mm</p> <p>(1 photograph)</p>	[1999]	BM02-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/1/196	Photograph of exterior of Cambridge Building fenced off before demolition Undated 130mmx180mm (1 photograph)	[1999]	BM02-RRB1
EST/1/1/1/197	Photograph of exterior of Cambridge Building from pavement through railings with Mercantile House visible in the background Undated 130mmx180mm (1 photograph)	[1999]	BM02-RRB1
EST/1/1/1/198	Photograph of interior room in Cambridge Building with wall missing fenced off before demolition Undated 130mmx180mm (1 photograph)	[1999]	BM02-RRB1
EST/1/1/1/199	Photograph of interior room in Cambridge Building with open wooden cabinet shortly before demolition Undated 130mmx180mm (1 photograph)	[1999]	BM02-RRB1
EST/1/1/1/200	Photograph of side exterior of Cambridge Building with Mercantile House visible in the background Undated 130mmx180mm (1 photograph)	[1999]	BM02-RRB1
EST/1/1/1/201	Photograph of exterior of Cambridge Building with walls missing behind metal fence Undated 130mmx180mm (1 photograph)	[1999]	BM02-RRB1
EST/1/1/1/202	Photograph of exterior of Cambridge Building behind metal fencing with 'Caution Demolition' sign and surrounded by bushes and trees Undated 130mmx180mm (1 photograph)	[1999]	BM02-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/1/203	<p>Photograph of exterior of Cambridge Building with Hughes and Salvidge van parked outside and Surrounded by metal fencing with sign reading 'CAUTION DEMOLITION'</p> <p>Undated 130mmx180mm (1 photograph)</p>	[1999]	BM02-RRB1
EST/1/1/1/204	<p>Photograph of exterior of Cambridge Building behind metal fencing with 'Caution Demolition' sign and surrounded by bushes and trees</p> <p>Undated 130mmx180mm (1 photograph)</p>	[1999]	BM02-RRB1

Reference	Description	Date	Shelf Mark
<i>Eldon Building Huts/Car Park</i>			
EST/1/1/1/205	Photograph of front exterior of Eldon Building from Winston Churchill Avenue Undated 130mmx180mm (1 photograph)	[1999]	BM02-RRB1
EST/1/1/1/206	Photograph of side exterior of Eldon Building from Winston Churchill Avenue Undated 130mmx180mm (1 photograph)	[1999]	BM02-RRB1
EST/1/1/1/207	Photograph of side exterior of Eldon Building from Winston Churchill Avenue Undated 130mmx180mm (1 photograph)	[1999]	BM02-RRB1
EST/1/1/1/208	Photograph of roof terrace Eldon Building with green tables and chairs Undated 130mmx180mm (1 photograph)	[1999]	BM02-RRB1
EST/1/1/1/209	Photograph of side exterior of Eldon Building from Winston Churchill Avenue with one person climbing the steps to the entrance Undated 130mmx180mm (1 photograph)	[1999]	BM02-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/1/210	Photograph of courtyard of Eldon Building with [Leamington House?] in the background Undated 130mmx180mm (1 photograph)	[1999]	BM02-RRB1
EST/1/1/1/211	Photograph of courtyard of Eldon Building Undated 130mmx180mm (1 photograph)	[1999]	BM02-RRB1
EST/1/1/1/212	Photograph of courtyard of Eldon Building with [Leamington House?] in background Undated 130mmx180mm (1 photograph)	[1999]	BM02-RRB1
EST/1/1/1/213	Photograph of courtyard of Eldon Building Undated 130mmx180mm (1 photograph)	[1999]	BM02-RRB1
EST/1/1/1/214	Photograph of courtyard of Eldon Building taken from slope with red handrails Undated 130mmx180mm (1 photograph)	[1999]	BM02-RRB1
EST/1/1/1/215	Photograph of Eldon Building covered walkway - view into courtyard with a large no smoking sign on the wall Undated 130mmx180mm (1 photograph)	[1999]	BM02-RRB1
EST/1/1/1/216	Photograph of Eldon Building courtyard - view looking North East Undated 130mmx180mm (1 photograph)	[1999]	BM02-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/1/217	Photograph of exterior of Eldon Building [huts?] with a broken window in close-up Undated 130mmx180mm (1 photograph)	[1999]	BM02-RRB1
EST/1/1/1/218	Photograph of Eldon Building covered walkway - view into courtyard Undated 130mmx180mm (1 photograph)	[1999]	BM02-RRB1
EST/1/1/1/219	Photograph of exterior of Eldon huts with a wheel clamping sign Undated 130mmx180mm (1 photograph)	[1999]	BM02-RRB1
EST/1/1/1/220	Photograph of pathway between exterior of Eldon Building [huts?]and brick building with green double doors Undated 130mmx180mm (1 photograph)	[1999]	BM02-RRB1
EST/1/1/1/221	Photograph of a carpark [?] with a large hedge and Eldon Building visible behind Undated 130mmx180mm (1 photograph)	[1999]	BM02-RRB1
EST/1/1/1/222	Photograph of exterior of Eldon Building [huts?] Undated 130mmx180mm (1 photograph)	[1999]	BM02-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/1/223	<p>Photograph of exterior of Eldon Building [huts?] with a dead rat lying on the grass Undated 130mmx180mm (1 photograph)</p>	[1999]	BM02-RRB1
EST/1/1/1/224	<p>Photograph of exterior of Eldon huts Undated 130mmx180mm (1 photograph)</p>	[1999]	BM02-RRB1
EST/1/1/1/225	<p>Photograph of exterior of Eldon huts with wooden stairs leading up to white double doors Undated 130mmx180mm (1 photograph)</p>	[1999]	BM02-RRB1
EST/1/1/1/226	<p>Photograph of exterior of Eldon huts with a sign on the door reading 'The huts are being demolished. Please take home any work still wanted before end of term (Friday 4 June)' Undated 130mmx180mm (1 photograph)</p>	[1999]	BM02-RRB1
EST/1/1/1/227	<p>Photograph of side exterior Eldon huts - view looking North West with Eldon Building in background Undated 130mmx180mm (1 photograph)</p>	[1999]	BM02-RRB1
EST/1/1/1/228	<p>Photograph of interior of Eldon huts with a glass ceiling Undated 130mmx180mm (1 photograph)</p>	[1999]	BM02-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/1/229	Photograph of exterior of Eldon huts with Middle Street and [Leamington House?] in the background and huts on the left and right Undated 130mmx180mm (1 photograph)	[1999]	BM02-RRB1
EST/1/1/1/230	Photograph of interior of workshop in Eldon huts Undated 130mmx180mm (1 photograph)	[1999]	BM02-RRB1
EST/1/1/1/231	Photograph of corridor in Eldon Building with lockers on the left wall Undated 130mmx180mm (1 photograph)	[1999]	BM02-RRB1
EST/1/1/1/232	Photograph of exterior of Eldon huts with [Leamington House?] in the background Undated 130mmx180mm (1 photograph)	[1999]	BM02-RRB1
EST/1/1/1/233	Photograph of exterior of Eldon huts with metal fence and bushes in front taken from the car park Undated 130mmx180mm (1 photograph)	[1999]	BM02-RRB1
EST/1/1/1/234	Photograph of exterior of Eldon huts with Eldon Building visible in the background - view looking North Undated 130mmx180mm (1 photograph)	[1999]	BM02-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/1/235	Photograph of side exterior of Eldon Building from St James' Road with sign on pavement reading 'Portsmouth College of Art Design and Further Education' Undated 130mmx180mm (1 photograph)	[1999]	BM02-RRB1
EST/1/1/1/236	Photograph of front exterior of Eldon Building - view from Winston Churchill Avenue Undated 130mmx180mm (1 photograph)	[1999]	BM02-RRB1
EST/1/1/1/237	Photograph of side exterior of Eldon Building with damaged windows - view from St James' Road Undated 130mmx180mm (1 photograph)	[1999]	BM02-RRB1
EST/1/1/1/238	Photograph of exterior of Eldon Building close up of pillars and windows Undated 130mmx180mm (1 photograph)	[1999]	BM02-RRB1
EST/1/1/1/239	Photograph of exterior of Eldon huts with a brown wooden fence and grassed area Undated 130mmx180mm (1 photograph)	[1999]	BM02-RRB1
EST/1/1/1/240	Photograph of exterior of Eldon Building close up of pillars and windows Undated 130mmx180mm (1 photograph)	[1999]	BM02-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/1/241	Photograph of exterior of Eldon huts from car park – view looking North East with Eldon Building visible in background Undated 130mmx180mm (1 photograph)	[1999]	BM02-RRB1
EST/1/1/1/242	Photograph of exterior of Eldon huts from car park – view looking North East with Eldon Building visible in background Undated 130mmx180mm (1 photograph)	[1999]	BM02-RRB1
EST/1/1/1/243	Photograph of exterior of Eldon Building taken from courtyard with stone stairs and red handrails in foreground Undated 130mmx180mm (1 photograph)	[1999]	BM02-RRB1
EST/1/1/1/244	Photograph of exterior of Eldon huts - view to North East with Eldon Building in background Undated 130mmx180mm (1 photograph)	[1999]	BM02-RRB1
EST/1/1/1/245	Photograph of Eldon car park with Eldon Building and hut visible in background - view looking North West Undated 130mmx180mm (1 photograph)	[1999]	BM02-RRB1
EST/1/1/1/246	Photograph of exterior of Eldon Building from courtyard Undated 130mmx180mm (1 photograph)	[1999]	BM02-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/1/247	<p>Photograph of rear side exterior of Eldon Building with two sets of brown double doors</p> <p>- view from grass area outside looking South</p> <p>Undated</p> <p>130mmx180mm</p> <p>(1 photograph)</p>	[1999]	BM02-RRB1
EST/1/1/1/248	<p>Photograph of exterior of Eldon Building taken from courtyard- view looking North East</p> <p>Undated</p> <p>130mmx180mm</p> <p>(1 photograph)</p>	[1999]	BM02-RRB1
EST/1/1/1/249	<p>Photograph of side exterior of Eldon Building</p> <p>- view looking East?</p> <p>Undated</p> <p>130mmx180mm</p> <p>(1 photograph)</p>	[1999]	BM02-RRB1
EST/1/1/1/250	<p>Photograph of exterior of Eldon huts with open red gates in foreground and Eldon Building in background</p> <p>Undated</p> <p>130mmx180mm</p> <p>(1 photograph)</p>	[1999]	BM02-RRB1
EST/1/1/1/251	<p>Photograph of front exterior of Eldon Building in close up taken from Winston Churchill Avenue with tree in foreground</p> <p>Undated</p> <p>130mmx180mm</p> <p>(1 photograph)</p>	[1999]	BM02-RRB1
EST/1/1/1/252	<p>Photograph of front exterior of Eldon Building showing Winston Churchill Avenue entrance with a sign partially visible advertising a foundation course in contemporary popular musics</p> <p>Undated</p> <p>130mmx180mm</p> <p>(1 photograph)</p>	[1999]	BM02-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/1/253	<p>Photograph of front exterior of Eldon Building showing Winston Churchill Avenue entrance with a sign partially visible advertising a foundation course in contemporary popular musics</p> <p>Undated</p> <p>130mmx180mm</p> <p>(1 photograph)</p>	[1999]	BM02-RRB1
EST/1/1/1/254	<p>Photograph of front exterior of Eldon Building - view towards Middle Street with 'Jimmyz' night club visible in background</p> <p>Undated</p> <p>130mmx180mm</p> <p>(1 photograph)</p>	[1999]	BM02-RRB1
EST/1/1/1/255	<p>Photograph of exterior of Eldon huts with open red gates in foreground and Eldon Building in the background</p> <p>Undated</p> <p>130mmx180mm</p> <p>(1 photograph)</p>	[1999]	BM02-RRB1
EST/1/1/1/256	<p>Photograph of rear side exterior of Eldon Building taken from grass area by Middle Street – view looking North East</p> <p>Undated</p> <p>130mmx180mm</p> <p>(1 photograph)</p>	[1999]	BM02-RRB1
EST/1/1/1/257	<p>Photograph of front exterior of Eldon Building taken from Winston Churchill Avenue</p> <p>Undated</p> <p>130mmx180mm</p> <p>(1 photograph)</p>	[1999]	BM02-RRB1

Reference	Description	Date	Shelf Mark
<i>Eldon Site</i>			
EST/1/1/1/258	Photograph of Eldon huts demolition site with red crane and Eldon Building in background Undated 130mmx190mm (1 photograph)	[2000]	BM02-RRB1
EST/1/1/1/259	Photograph of Eldon huts demolition site with red crane and Eldon Building in background Undated 130mmx190mm (1 photograph)	[2000]	BM02-RRB1
EST/1/1/1/260	Photograph of Eldon huts demolition site close up of red crane – view towards St James' Road Undated 130mmx190mm (1 photograph)	[2000]	BM02-RRB1
EST/1/1/1/261	Photograph of Eldon huts demolition site close up of red crane – view towards St James' Road Undated 130mmx190mm (1 photograph)	[2000]	BM02-RRB1

Reference	Description	Date	Shelf Mark
<i>Eldon Temporary Building</i>			
EST/1/1/1/262	Photograph of interior of Eldon Temporary Building close up view of pipework Undated 120mmx170mm (1 photograph)	[1999]	BM02-RRB1
EST/1/1/1/263	Photograph of interior of Eldon Temporary Building close up view of pipework and wiring Undated 120mmx170mm (1 photograph)	[1999]	BM02-RRB1
EST/1/1/1/264	Photograph of a wooden board across a hole in the tarmac in Eldon car park Undated 120mmx170mm (1 photograph)	[1999]	BM02-RRB1
EST/1/1/1/265	Photograph of a wooden board across a hole in the tarmac in Eldon car park Undated 120mmx170mm (1 photograph)	[1999]	BM02-RRB1
EST/1/1/1/266	Photograph of interior of Eldon Temporary Building close up view of pipework and wiring Undated 120mmx170mm (1 photograph)	[1999]	BM02-RRB1
EST/1/1/1/267	Photograph of interior of Eldon Temporary Building close up view of pipework and wiring Undated 120mmx170mm (1 photograph)	[1999]	BM02-RRB1
EST/1/1/1/268	Photograph of interior of Eldon Temporary Building close up view of pipework and wiring Undated 120mmx170mm (1 photograph)	[1999]	BM02-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/1/269	Photograph of interior of Eldon Temporary Building close up view of pipework and wiring Undated 120mmx170mm (1 photograph)	[1999]	BM02-RRB1
EST/1/1/1/270	Photograph of interior of Eldon Temporary Building close up view of wiring Undated 120mmx170mm (1 photograph)	[1999]	BM02-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/2	'Frewen Library to Lion Gate'	1990s	
	See EST/1/4 Miscellaneous loose photographs – may contain strays		
EST/1/1/2/1	Contact sheet of various photographs of a University of Portsmouth hockey match and ceremonial event in marquee with ribbon cutting Undated 200mmx250mm (1 contact sheet)	1990s	BM02-RRB1
EST/1/1/2/2	Contact sheet of various photographs of a University of Portsmouth hockey match Undated 200mmx250mm (1 contact sheet)	1990s	BM02-RRB1
EST/1/1/3	'Mercantile House to Purbeck Street'	1990s	
	<i>Mercantile House</i>		
EST/1/1/3/1	Photograph of brick wall being laid outside Mercantile House - view towards the A3 including Wiltshire Building and Charter House Undated 130mmx180mm (1 photograph)	1990s	BM02-RRB1
EST/1/1/3/2	Photograph of exterior of Mercantile House covered in scaffolding- view from corner of Wiltshire Street Undated 130mmx180mm (1 photograph)	1990s	BM02-RRB1
EST/1/1/3/3	Photograph of front exterior of Mercantile House with a brick wall being built outside - view towards Ravelin Park Undated 130mmx180mm (1 photograph)	1990s	BM02-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/3/4	<p>Photograph of exterior front and side of Mercantile House covered in scaffolding -view from Hampshire Terrace with Nuffield Building visible in background Undated 100mmx150mm (1 photograph)</p>	1990s	BM02-RRB1
EST/1/1/3/5	<p>Photograph of exterior front and side of Mercantile House covered in scaffolding - view from A3 Undated 100mmx150mm (1 photograph)</p>	1990s	BM02-RRB1
EST/1/1/3/6	<p>Photograph of ceiling of Park Building lecture hall with eight copper light fixtures hanging down [removal of chandeliers?] Undated [Stray from Park Refurbishment] 100mmx150mm (1 photograph)</p>	1990s	BM02-RRB1
EST/1/1/3/7	<p>Photograph of exterior front and side of Mercantile House covered in scaffolding including Charter House Undated 100mmx150mm (1 photograph)</p>	1990s	BM02-RRB1
EST/1/1/3/8	<p>Photograph of ceiling of Park Building lecture hall with copper light fixtures hanging down with three men painting Undated [Stray from Park Refurbishment] 100mmx150mm (1 photograph)</p>	[1999]	BM02-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/3/9	Photograph of the rear exterior of Mercantile House partially covered in scaffolding – view from Cambridge Road Undated 100mmx150mm (1 photograph)	1990s	BM02-RRB1
EST/1/1/3/10	Photograph of the rear exterior of Mercantile House covered in scaffolding – view from Cambridge Road Undated 100mmx150mm (1 photograph)	1990s	BM02-RRB1
EST/1/1/3/11	Photograph of the rear exterior of Mercantile House covered in scaffolding – view from Cambridge Road Undated 100mmx150mm (1 photograph)	1990s	BM02-RRB1
EST/1/1/3/12	Photograph of front exterior of Mercantile House in close up with building sign partially visible Undated 100mmx150mm (1 photograph)	1990s	BM02-RRB1
EST/1/1/3/13	Photograph of exterior of Mercantile House - close up of roof and windows Undated 100mmx150mm (1 photograph)	1990s	BM02-RRB1
EST/1/1/3/14	Photograph of exterior of Mercantile House - close up of roof and windows Undated 100mmx150mm (1 photograph)	1990s	BM02-RRB1
EST/1/1/3/15	Photograph of front exterior of Mercantile House – close up of building sign Undated 100mmx150mm (1 photograph)	1990s	BM02-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/3/16	Photograph of front exterior of Mercantile House - close up of windows Undated 100mmx150mm (1 photograph)	1990s	BM02-RRB1
EST/1/1/3/17	Photograph of exterior of Mercantile House - close up of top section of building Undated 100mmx150mm (1 photograph)	1990s	BM02-RRB1
EST/1/1/3/18	Photograph of front and side exterior of Mercantile House - close up of top section of building Undated 100mmx150mm (1 photograph)	1990s	BM02-RRB1
EST/1/1/3/19	Photograph of front and side exterior of Mercantile House in close up Undated 100mmx150mm (1 photograph)	1990s	BM02-RRB1
EST/1/1/3/20	Photograph of front and side exterior of Mercantile House in close up including building sign Undated 100mmx150mm (1 photograph)	1990s	BM02-RRB1
EST/1/1/3/21	Photograph of side exterior of Mercantile House - top section of building Undated 100mmx150mm (1 photograph)	1990s	BM02-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/3/22	Photograph of side exterior of Mercantile House in close up Undated 100mmx150mm (1 photograph)	1990s	BM02-RRB1
EST/1/1/3/23	Photograph of side exterior of Mercantile House in close up Undated 100mmx150mm (1 photograph)	1990s	BM02-RRB1
EST/1/1/3/24	Photograph of side exterior of Mercantile House in close up Undated 100mmx150mm (1 photograph)	1990s	BM02-RRB1
EST/1/1/3/25	Photograph of side exterior of Mercantile House roof in close up Undated 100mmx150mm (1 photograph)	1990s	BM02-RRB1
EST/1/1/3/26	Photograph of rear exterior of Mercantile House with cars parked underneath the building Undated 100mmx150mm (1 photograph)	1990s	BM02-RRB1
EST/1/1/3/27	Photograph of exterior of Mercantile House with an air vent visible in centre of the photograph Undated 100mmx150mm (1 photograph)	1990s	BM02-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/3/28	Photograph of exterior of Mercantile House in close up Undated 100mmx150mm (1 photograph)	1990s	BM02-RRB1
EST/1/1/3/29	Photograph of exterior of Mercantile House showing windows in close up Undated 100mmx150mm (1 photograph)	1990s	BM02-RRB1
EST/1/1/3/30	Photograph of exterior of Mercantile House roof in close up Undated 100mmx150mm (1 photograph)	1990s	BM02-RRB1
EST/1/1/3/31	Photograph of exterior of Mercantile House roof in close up Undated 100mmx150mm (1 photograph)	1990s	BM02-RRB1
EST/1/1/3/32	Photograph of exterior of Mercantile House windows in close up Undated 100mmx150mm (1 photograph)	1990s	BM02-RRB1
EST/1/1/3/33	Photograph of side exterior of Mercantile House in close up Undated 100mmx150mm (1 photograph)	1990s	BM02-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/3/34	<p>Photograph of exterior of Mercantile House covered in scaffolding in close up with new windows awaiting installation</p> <p>Undated</p> <p>100mmx150mm</p> <p>(1 photograph)</p>	1990s	BM02-RRB1
EST/1/1/3/35	<p>Photograph of front exterior of Mercantile House covered in scaffolding taken from A3 – view towards Ravelin Park</p> <p>Undated</p> <p>100mmx150mm</p> <p>(1 photograph)</p>	1990s	BM02-RRB1
EST/1/1/3/36	<p>Photograph of exterior of Mercantile House covered in scaffolding in close up with workmen installing windows</p> <p>Undated</p> <p>100mmx150mm</p> <p>(1 photograph)</p>	1990s	BM02-RRB1
EST/1/1/3/37	<p>Photograph of exterior of Mercantile House covered in scaffolding with a workman installing windows</p> <p>Undated</p> <p>100mmx150mm</p> <p>(1 photograph)</p>	1990s	BM02-RRB1
EST/1/1/3/38	<p>Photograph of exterior of Mercantile House covered in scaffolding with a workman installing windows</p> <p>Undated</p> <p>100mmx150mm</p> <p>(1 photograph)</p>	1990s	BM02-RRB1
EST/1/1/3/39	<p>Photograph of side exterior of Mercantile House covered in scaffolding with a white van parked outside</p> <p>Undated</p> <p>100mmx150mm</p> <p>(1 photograph)</p>	1990s	BM02-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/3/40	<p>Photograph of front exterior of Mercantile House covered in scaffolding with yellow waste chute and new windows installed</p> <p>Undated</p> <p>100mmx150mm</p> <p>(1 photograph)</p>	1990s	BM02-RRB1
EST/1/1/3/41	<p>Photograph of front and side exterior of Mercantile House covered in scaffolding with yellow waste chute and new windows installed – view from A3 towards Ravelin Park</p> <p>Undated</p> <p>100mmx150mm</p> <p>(1 photograph)</p>	1990s	BM02-RRB1
EST/1/1/3/42	<p>Photograph of front exterior of Mercantile House covered in scaffolding with yellow waste chute and new windows installed</p> <p>Undated</p> <p>100mmx150mm</p> <p>(1 photograph)</p>	1990s	BM02-RRB1
EST/1/1/3/43	<p>Photograph of front and side exterior of Mercantile House covered in scaffolding with yellow waste chute and new windows installed – view from A3 towards Ravelin Park</p> <p>Undated</p> <p>100mmx150mm</p> <p>(1 photograph)</p>	1990s	BM02-RRB1
EST/1/1/3/44	<p>Photograph of front and side exterior of Mercantile House covered in scaffolding with yellow waste chute and new windows installed – view from A3 towards Ravelin Park</p> <p>Undated</p> <p>100mmx150mm</p> <p>(1 photograph)</p>	1990s	BM02-RRB1
EST/1/1/3/45	<p>Photograph of front exterior of Mercantile House covered in scaffolding with yellow waste chute and new windows installed</p> <p>Undated</p> <p>100mmx150mm</p> <p>(1 photograph)</p>	1990s	BM02-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/3/46	Photograph of rear exterior of Mercantile House Covered in scaffolding – view from Cambridge Road Undated 100mmx150mm (1 photograph)	1990s	BM02-RRB1
EST/1/1/3/47	Photograph of front and side exterior of Mercantile House- view from Hampshire Terrace Undated 100mmx150mm (1 photograph)	1990s	BM02-RRB1
EST/1/1/3/48	Photograph of exterior of Mercantile House covered in scaffolding with two work men close up Undated 100mmx150mm (1 photograph)	1990s	BM02-RRB1
<i>Park Building Upper Hall</i>			
EST/1/1/3/48	Contact sheet of six photographs of interior Park Building Upper Hall - parquet wood floor with chandeliers hanging from ceiling Undated 200mmx300mm (1 contact sheet)	[1999]	BM03-RRB1
EST/1/1/3/49	Contact sheet of eight photographs of interior Park Building Upper Hall - parquet wood floor with chandeliers hanging from ceiling Undated 200mmx300mm (1 contact sheet)	[1999]	BM03-RRB1

Reference	Description	Date	Shelf Mark
<i>Park Refurbishment</i>			
EST/1/1/3/50	Photograph of interior of Park Building Upper Hall filled with scaffolding Undated 100mm150xmm (1 photograph)	[1999]	BM03-RRB1
EST/1/1/3/51	Photograph of interior of Park Building Upper Hall filled with scaffolding Undated 100mmx150mm (1 photograph)	[1999]	BM03-RRB1
EST/1/1/3/52	Photograph of interior of Park Building Upper Hall filled with scaffolding four wooden doors removed from hinges Undated 100mmx150mm (1 photograph)	[1999]	BM03-RRB1
EST/1/1/3/53	Photograph of interior of Park Building Upper Hall filled with scaffolding and a man standing on a ladder painting Undated 100mmx150mm (1 photograph)	[1999]	BM03-RRB1
EST/1/1/3/54	Photograph of interior of lecture theatre of Park Building with plastic covers on seating A workman Undated 100mmx150mm (1 photograph)	[1999]	BM03-RRB1
EST/1/1/3/55	Photograph of interior of Park Building Upper Hall with three men painting Undated 100mmx150mm (1 photograph)	[1999]	BM03-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/3/56	Photograph of interior of lecture theatre in Park Building with plastic covers on the seating Undated 100mmx150mm (1 photograph)	[1999]	BM03-RRB1
EST/1/1/3/57	Photograph of interior of lecture theatre in Park Building with plastic covers on the seating and two work men Undated 100mmx150mm (1 photograph)	[1999]	BM03-RRB1
EST/1/1/3/58	Photograph of interior of lecture theatre in Park Building with no seating and a white wire hanging down from the ceiling Undated 100mmx150mm (1 photograph)	[1999]	BM03-RRB1
EST/1/1/3/59	Photograph of interior of lecture theatre in Park Building with plastic covers on the seating and two work men Undated 100mmx150mm (1 photograph)	[1999]	BM03-RRB1
EST/1/1/3/60	Photograph of interior of lecture theatre in Park Building [prior to installation of seating?] Undated 100mmx150mm (1 photograph)	[1999]	BM03-RRB1
EST/1/1/3/61	Photograph of interior of room in Park Building with a workman operating machinery [in basement?] Undated 100mmx150mm (1 photograph)	[1999]	BM03-RRB1
EST/1/1/3/62	Photograph of view from a staircase in Park Building looking down towards open double doors [basement?] Undated 100mmx150mm (1 photograph)	[1999]	BM03-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/3/63	<p>Photograph of main staircase in Park Building covered in scaffolding - looking down towards open main entrance doors [pre installation of lift]</p> <p>Undated</p> <p>100mmx150mm</p> <p>(1 photograph)</p>	[1999]	BM03-RRB1
EST/1/1/3/64	<p>Photograph of interior of hallway in Park Building with pipes running across the ceiling and one man standing on a ladder working</p> <p>Undated</p> <p>100mmx150mm</p> <p>(1 photograph)</p>	[1999]	BM03-RRB1
EST/1/1/3/65	<p>Photograph of main staircase in Park Building covered in scaffolding - looking down towards first and ground floors [pre installation of lift]</p> <p>Undated</p> <p>100mmx150mm</p> <p>(1 photograph)</p>	[1999]	BM03-RRB1
EST/1/1/3/66	<p>Photograph of interior hallway of Park Building with two men working</p> <p>Undated</p> <p>100mmx150mm</p> <p>(1 photograph)</p>	[1999]	BM03-RRB1
EST/1/1/3/67	<p>Photograph taken from interior of Park Building looking through windows with a man working outside in the rain</p> <p>Undated</p> <p>100mmx150mm</p> <p>(1 photograph)</p>	[1999]	BM03-RRB1
EST/1/1/3/68	<p>Photograph of front exterior of Park Building with a blue [crane?] parked outside and a large piece of equipment [air conditioning unit?] lying on pavement</p> <p>photograph</p> <p>Undated</p> <p>100mmx150mm</p> <p>(1 photograph)</p>	[1999]	BM03-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/3/69	Photograph of room of Park Building - parquet flooring with wooden examination desks Undated 100mmx150mm (1 photograph)	[1999]	BM03-RRB1
EST/1/1/3/70	Photograph of empty room in Park Building [formerly public library, latterly Learning Resource Centre] Undated 100mmx150mm (1 photograph)	[1999]	BM03-RRB1
EST/1/1/3/71	Photograph of room in Park Building with wooden desks lined up in rows and one man at the back of the room on a ladder working Undated 100mmx150mm (1 photograph)	[1999]	BM03-RRB1
EST/1/1/3/72	Photograph of front exterior of Park Building with scaffolding partially covering the south side of the building Undated 100mmx150mm (1 photograph)	[1999]	BM03-RRB1
<i>Park Building Lecture Theatre [photographs wrongly labelled in original packaging?]</i>			
EST/1/1/3/73	Photograph of side exterior of Park Building with a large crane in the background and King Henry I Street blocked off Undated 130mmx180mm (1 photograph)	1990s	BM03-RRB1
EST/1/1/3/74	Photograph of a crane [in close-up] parked outside Park Building in King Henry I Street Undated 130mmx180mm (1 photograph)	1990s	BM03-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/3/75	Photograph of side exterior of Park Building with a large crane parked in King Henry I Street Undated 130mmx180mm (1 photograph)	1990s	BM03-RRB1
EST/1/1/3/76	Photograph of a crane [in close-up] parked outside Park Building in King Henry I Street Undated 130mmx180mm (1 photograph)	1990s	BM03-RRB1
EST/1/1/3/77	Photograph of a crane in operation parked outside Park Building in King Henry I Street Undated 130mmx180mm (1 photograph)	1990s	BM03-RRB1
EST/1/1/3/78	Photograph of a crane in operation parked outside Park Building in King Henry I Street Undated 130mmx180mm (1 photograph)	1990s	BM03-RRB1
EST/1/1/3/79	Photograph of a crane in operation parked outside Park Building in King Henry I Street [lifting an air conditioning unit?] Undated 130mmx180mm (1 photograph)	1990s	BM03-RRB1
EST/1/1/3/80	Photograph of a crane in operation [lifting an air conditioning unit?] with roof of Park Building visible Undated 130mmx180mm (1 photograph)	1990s	BM03-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/3/81	<p>Photograph of a crane in operation in close-up [lifting an air conditioning unit?] Undated 130mmx180mm (1 photograph)</p>	1990s	BM03-RRB1
EST/1/1/3/82	<p>Photograph of a crane in operation [lifting an air conditioning unit?] onto roof of Park Building – view from upper floor of King Henry Building Undated 130mmx180mm (1 photograph)</p>	1990s	BM03-RRB1
EST/1/1/3/83	<p>Photograph of a crane in operation [lifting an air conditioning unit?] onto roof of Park Building – view from upper floor of King Henry Building Undated 130mmx180mm (1 photograph)</p>	1990s	BM03-RRB1
EST/1/1/3/84	<p>Photograph of a crane in operation [lifting an air conditioning unit?] onto roof of Park Building – view from upper floor of King Henry Building Undated 130mmx180mm (1 photograph)</p>	1990s	BM03-RRB1
EST/1/1/3/85	<p>Photograph of side exterior of Park Building with a large crane in the background and King Henry I Street blocked off Undated 130mmx180mm (1 photograph)</p>	1990s	BM03-RRB1

Reference	Description	Date	Shelf Mark
<i>Portland Building Construction</i>			
See also EST/1/4/13-19 for further images of Portland Building			
EST/1/1/3/86	Photograph of exterior of Portland Building with scaffolding on one side 15 December 1995 100mmx150mm (1 photograph)	1995	BM03-RRB1
EST/1/1/3/87	Photograph of interior of Portland Building under construction 15 December 1995 100mmx150mm (1 photograph)	1995	BM03-RRB1
EST/1/1/3/88	Photograph of interior of Portland Building under construction showing glass roof 15 December 1995 100mmx150mm (1 photograph)	1995	BM03-RRB1
EST/1/1/3/89	Photograph of interior of Portland Building Under construction Undated 100mmx150mm (1 photograph)	[1995]	BM03-RRB1
EST/1/1/3/90	Photograph of interior of Portland Building under construction Undated 100mmx150mm (1 photograph)	[1995]	BM03-RRB1
EST/1/1/3/91	Photograph of interior of Portland Building under construction Undated 100mmx150mm (1 photograph)	[1995]	BM03-RRB1
EST/1/1/3/92	Photograph of interior of Portland Building under construction Undated 100mmx150mm (1 photograph)	[1995]	BM03-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/3/93	Photograph of interior of Portland Building under construction Undated 100mmx150mm (1 photograph)	[1995]	BM03-RRB1
EST/1/1/3/94	Photograph of interior of Portland Building under construction Undated 100mmx150mm (1 photograph)	[1995]	BM03-RRB1
EST/1/1/3/95	Photograph of interior of Portland Building under construction Undated 100mmx150mm (1 photograph)	[1995]	BM03-RRB1
EST/1/1/3/96	Photograph of interior of Portland Building under construction Undated 100mmx150mm (1 photograph)	[1995]	BM03-RRB1
EST/1/1/3/97	Photograph of interior of Portland Building under construction – close up of flooring Undated 100mmx150mm (1 photograph)	[1995]	BM03-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/3/98	Photograph of exterior of Portland Building covered in scaffolding with Sarah Robinson House in the background Undated 100mmx150mm (1 photograph)	[1995]	BM03-RRB1
EST/1/1/3/99	Photograph of interior of Portland Building under construction Undated 100mmx150mm (1 photograph)	[1995]	BM03-RRB1
EST/1/1/3/100	Photograph of interior of Portland Building under construction Undated 100mmx150mm (1 photograph)	[1995]	BM03-RRB1
EST/1/1/3/101	Photograph of exterior of Portland Building under construction covered with scaffolding and building materials in foreground Undated 100mmx150mm (1 photograph)	[1995]	BM03-RRB1
EST/1/1/3/102	Photograph of interior of Portland Building under construction [plant room?] Undated 100mmx150mm (1 photograph)	[1995]	BM03-RRB1
EST/1/1/3/103	Photograph of exterior of Portland Building under construction covered in scaffolding Undated 100mmx150mm (1 photograph)	[1995]	BM03-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/3/104	<p>Photograph of exterior of Portland Building under construction – view from corner of St George’s Way</p> <p>Undated</p> <p>100mmx150mm</p> <p>(1 photograph)</p>	[1995]	BM03-RRB1
EST/1/1/3/105	<p>Photograph of exterior roof of Portland Building covered in with scaffolding and Mill Gate House in the background</p> <p>Undated</p> <p>100mmx150mm</p> <p>(1 photograph)</p>	[1995]	BM03-RRB1
EST/1/1/3/106	<p>Photograph of interior atrium and roof in Portland Building with a black ladder in the background</p> <p>Undated</p> <p>100mmx150mm</p> <p>(1 photograph)</p>	[1995]	BM03-RRB1
EST/1/1/3/107	<p>Photograph of exterior of Portland Building covered in scaffolding showing three men working on building next door</p> <p>[Beneficial Foundation Quinnell Centre]</p> <p>Undated</p> <p>100mmx150mm</p> <p>(1 photograph)</p>	[1995]	BM03-RRB1
EST/1/1/3/108	<p>Photograph of exterior of Portland Building - view from roof with Sarah Robinson House in the background</p> <p>Undated</p> <p>100mmx150mm</p> <p>(1 photograph)</p>	[1995]	BM03-RRB1
EST/1/1/3/109	<p>Photograph of exterior of Portland Building taken through open metal gates</p> <p>15 December 1995</p> <p>100mmx150mm</p> <p>(1 photograph)</p>	1995	BM03-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/3/110	Photograph of interior of Portland Building under construction 15 December 1995 100mmx150mm (1 photograph)	1995	BM03-RRB1
EST/1/1/3/111	Photograph of exterior of Portland Building from St James' Street 15 December 1995 100mmx150mm (1 photograph)	1995	BM03-RRB1
EST/1/1/3/112	Photograph of room in Portland Building - pipework in close-up 15 December 1995 100mmx150mm (1 photograph)	1995	BM03-RRB1
EST/1/1/3/113	Photograph of interior corridor in Portland Building with lights hanging on wires 15 December 1995 100mmx150mm (1 photograph)	1995	BM03-RRB1
EST/1/1/3/114	Photograph of exterior of Portland Building Covered in scaffolding and with building materials on the ground outside - view from an upper floor 15 December 1995 100mmx150mm (1 photograph)	1995	BM03-RRB1
EST/1/1/3/115	Photograph of room in Portland Building -close up of metal brackets on wall 15 December 1995 100mmx150mm (1 photograph)	1995	BM03-RRB1
EST/1/1/3/116	Photograph of room in Portland Building with wires hanging from the light fixtures in the ceiling and metal poles on the floor 15 December 1995 100mmx150mm (1 photograph)	1995	BM03-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/3/117	Photograph of room in Portland Building with wires hanging from the light fixtures 15 December 1995 100mmx150mm (1 photograph)	[1995]	BM03-RRB1
EST/1/1/3/118	Photograph of a hole dug in Lion Terrace with a blue pipe running through it and Burnaby Building visible in the background 15 December 1995 100mmx150mm (1 photograph)	1995	BM03-RRB1
EST/1/1/3/119	Photograph of room in Portland Building under construction with wooden planks along the floor 15 December 1995 100mmx150mm (1 photograph)	1995	BM03-RRB1
EST/1/1/3/120	Photograph of room in Portland Building under construction with wooden planks along the floor and a man standing in the inner right of the room 15 December 1995 100mmx150mm (1 photograph)	1995	BM03-RRB1
EST/1/1/3/121	Photograph of room in Portland Building under construction with wooden planks along the floor 15 December 1995 100mmx150mm (1 photograph)	1995	BM03-RRB1
EST/1/1/3/122	Photograph of interior corridor in Portland Building under construction 15 December 1995 100mmx150mm (1 photograph)	1995	BM03-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/3/123	Photograph of interior corridor in Portland Building under construction and a man standing looking at the floor 15 December 1995 100mmx150mm (1 photograph)	1995	BM03-RRB1
EST/1/1/3/124	Photograph of interior of Portland Building under construction 15 December 1995 100mmx150mm (1 photograph)	1995	BM03-RRB1
EST/1/1/3/125	Photograph of room in Portland Building under construction 15 December 1995 100mmx150mm (1 photograph)	1995	BM03-RRB1
EST/1/1/3/126	Photograph of exterior of Portland Building with a University sign reading 'Norwest Holst' view from St James' Street 15 December 1995 100mmx150mm (1 photograph)	1995	BM03-RRB1
EST/1/1/3/127	Photograph of interior corridor in Portland Building under construction 15 December 1995 100mmx150mm (1 photograph)	1995	BM03-RRB1
EST/1/1/3/128	Photograph of exterior of Portland Building - view from Portland Street 15 December 1995 100mmx150mm (1 photograph)	1995	BM03-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/3/129	Photograph of exterior roof of Portland Building Covered with wooden scaffolding and a man working Undated 100mmx150mm (1 photograph)	[1995]	BM03-RRB1
EST/1/1/3/130	Photograph of room in Portland Building Under construction with a new window leaning against the wall Undated 100mmx150mm (1 photograph)	[1995]	BM03-RRB1

Portland Building Construction

EST/1/1/3/131	Photograph of exterior of Portland Building and building materials behind a metal fence 28 March 1996 130mmx170mm (1 photograph)	1996	BM03-RRB1
EST/1/1/3/132	Photograph of exterior of Portland Building taken from a high angle with building work taking place on courtyard 28 March 1996 130mmx170mm (1 photograph)	1996	BM03-RRB1
EST/1/1/3/133	Photograph of exterior of Portland Building and building materials behind a metal fence 28 March 1996 130mmx170mm (1 photograph)	1996	BM03-RRB1
EST/1/1/3/134	Photograph of exterior of Portland Building taken from a high angle with building work taking place on courtyard 28 March 1996 130mmx170mm (1 photograph)	1996	BM03-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/3/135	Photograph of exterior of Portland Building with building work taking place on courtyard 28 March 1996 130mmx170mm (1 photograph)	1996	BM03-RRB1
EST/1/1/3/136	Photograph of interior of Portland Building with temporary flooring 28 March 1996 130mmx170mm (1 photograph)	1996	BM03-RRB1
EST/1/1/3/137	Photograph of interior of Portland Building with temporary flooring 28 March 1996 130mmx170mm (1 photograph)	1996	BM03-RRB1
EST/1/1/3/138	Photograph of exterior of Portland Building taken from a high angle with building work taking place on courtyard 28 March 1996 130mmx170mm (1 photograph)	1996	BM03-RRB1
EST/1/1/3/139	Photograph of exterior roof of Portland Building with building work taking place on courtyard 28 March 1996 130mmx170mm (1 photograph)	1996	BM03-RRB1
EST/1/1/3/140	Photograph of room in Portland Building under construction 28 March 1996 130mmx170mm (1 photograph)	1996	BM03-RRB1
EST/1/1/3/141	Photograph of exterior of Portland Building taken from a high angle with building work taking place on courtyard 28 March 1996 130mmx170mm (1 photograph)	1996	BM03-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/3/142	Photograph of room in Portland Building under construction with square holes in new flooring 28 March 1996 130mmx170mm (1 photograph)	1996	BM03-RRB1
EST/1/1/3/143	Photograph of interior of roof in Portland Building 28 March 1996 130mmx170mm (1 photograph)	1996	BM03-RRB1
EST/1/1/3/144	Photograph of three air conditioning units on roof of Portland Building 28 March 1996 130mmx170mm (1 photograph)	1996	BM03-RRB1
EST/1/1/3/145	Photograph of room in Portland Building Under construction 28 March 1996 130mmx170mm (1 photograph)	1996	BM03-RRB1
EST/1/1/3/146	Photograph of exterior roof of Portland Building 28 March 1996 130mmx170mm (1 photograph)	1996	BM03-RRB1
EST/1/1/3/147	Photograph of room in Portland Building under construction 28 March 1996 130mmx170mm (1 photograph)	1996	BM03-RRB1
EST/1/1/3/148	Photograph of room in Portland Building under construction 28 March 1996 130mmx170mm (1 photograph)	1996	BM03-RRB1
EST/1/1/3/149	Photograph of exterior of Portland Building with building work taking place on courtyard 28 March 1996 130mmx170mm (1 photograph)	1996	BM03-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/3/150	<p>Photograph of exterior of Buckingham Building with building work taking place outside</p> <p>28 March 1996</p> <p>130mmx170mm</p> <p>(1 photograph)</p>	1996	BM03-RRB1
EST/1/1/3/151	<p>Photograph of room in Portland Building under construction with square holes in new flooring</p> <p>28 March 1996</p> <p>130mmx170mm</p> <p>(1 photograph)</p>	1996	BM03-RRB1
EST/1/1/3/152	<p>Photograph of lecture theatre in Portland Building Under construction</p> <p>28 March 1996</p> <p>130mmx170mm</p> <p>(1 photograph)</p>	1996	BM03-RRB1
EST/1/1/3/153	<p>Photograph of exterior of Portland Building from corner of St James' Street and Portland Street with The Beneficial Foundation Quinnell Centre on the left</p> <p>28 March 1996</p> <p>130mmx170mm</p> <p>(1 photograph)</p>	1996	BM03-RRB1
EST/1/1/3/154	<p>Photograph of exterior of Portland Building from corner of St James' Street and Portland Street with The Beneficial Foundation Quinnell Centre just visible on the left</p> <p>28 March 1996</p> <p>130mmx170mm</p> <p>(1 photograph)</p>	1996	BM03-RRB1
EST/1/1/3/155	<p>Photograph of exterior of Portland Building from corner of St James' Street and Portland Street with The Beneficial Foundation Quinnell Centre on the left</p> <p>Undated</p> <p>110mmx160mm</p> <p>(1 photograph)</p>	[1996]	BM03-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/3/156	Photograph of interior of Portland Building - view from above Undated 110mmx160mm (1 photograph)	[1996]	BM03-RRB1
EST/1/1/3/157	Photograph of exterior rear of Portland Building taken from the car park Undated 110mmx160mm (1 photograph)	[1996]	BM03-RRB1
EST/1/1/3/158	Photograph of room in Portland Building under construction Undated 110mmx160mm (1 photograph)	[1996]	BM03-RRB1
EST/1/1/3/159	Photograph of exterior of Portland Building and almost completed courtyard taken from the roof Undated 110mmx160mm (1 photograph)	[1996]	BM03-RRB1
EST/1/1/3/160	Photograph of exterior of Portland Building taken from the courtyard with new trees Undated 110mmx160mm (1 photograph)	[1996]	BM03-RRB1
EST/1/1/3/161	Photograph of side exterior of Portland Building with red barriers and cones in front of the building Undated 110mmx160mm (1 photograph)	[1996]	BM03-RRB1
EST/1/1/3/162	Photograph of exterior of Portland Building taken from the courtyard with new trees and building materials Undated 110mmx160mm (1 photograph)	[1996]	BM03-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/3/163	Photograph of interior of Portland Building under construction 26 April 1996 100mmx150mm (1 photograph)	1996	BM03-RRB1
EST/1/1/3/164	Photograph of a corridor? in Portland Building under construction 26 January 1996 100mmx150mm (1 photograph)	1996	BM03-RRB1
EST/1/1/3/165	Photograph of interior of Portland Building under construction 26 April 1996 100mmx150mm (1 photograph)	1996	BM03-RRB1
EST/1/1/3/166	Photograph of room in Portland Building under construction 26 January 1996 100mmx150mm (1 photograph)	1996	BM03-RRB1
EST/1/1/3/167	Photograph of interior of Portland Building covered in scaffolding 26 January 1996 100mmx150mm (1 photograph)	1996	BM03-RRB1
EST/1/1/3/168	Photograph of room in Portland Building under construction 26 January 1996 100mmx150mm (1 photograph)	1996	BM03-RRB1
EST/1/1/3/169	Photograph of interior roof in Portland Building under construction 26 January 1996 100mmx150mm (1 photograph)	1996	BM03-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/3/170	Photograph of exterior front and side of Portland Building with scaffolding covering a section of the building - view from Portland Street 26 January 1996 100mmx150mm (1 photograph)	1996	BM03-RRB1
EST/1/1/3/171	Photograph of exterior of Portland Building with a sign reading Norwest Holst – view from St James’ Street 26 January 1996 100mmx150mm (1 photograph)	1996	BM03-RRB1
EST/1/1/3/172	Photograph of exterior of Portland Building with a sign reading Norwest Holst – view from St James’ Street 26 January 1996 100mmx150mm (1 photograph)	1996	BM03-RRB1
EST/1/1/3/173	Photograph of [lecture theatre?] in Portland Building under construction with lights on the floor 26 January 1996 100mmx150mm (1 photograph)	1996	BM03-RRB1
EST/1/1/3/174	Photograph of room in Portland Building under construction 26 January 1996 100mmx150mm (1 photograph)	1996	BM03-RRB1
EST/1/1/3/175	Photograph of exterior roof of Portland Building - view from on the roof 26 January 1996 100mmx150mm (1 photograph)	1996	BM03-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/3/176	Photograph of room in Portland Building under construction 26 January 1996 100mmx150mm (1 photograph)	1996	BM03-RRB1
EST/1/1/3/177	Photograph of room in Portland Building under construction 26 January 1996 100mmx150mm (1 photograph)	1996	BM03-RRB1
EST/1/1/3/178	Photograph of interior stairwell in Portland Building under construction 26 January 1996 100mmx150mm (1 photograph)	1996	BM03-RRB1
EST/1/1/3/179	Photograph of exterior of Portland Building Partially covered in scaffolding - view from st James' Street with Burnaby Building visible in background 26 January 1996 100mmx150mm (1 photograph)	1996	BM03-RRB1
EST/1/1/3/180	Photograph of exterior of Portland Building Surrounded by metal fence – view from corner of St James' Street and Portland Street 26 January 1996 100mmx150mm (1 photograph)	1996	BM03-RRB1
EST/1/1/3/181	Photograph of exterior of Portland Building Under construction – view from St James' Street with Buckingham Building visible in background 26 January 1996 100mmx150mm (1 photograph)	1996	BM03-RRB1
EST/1/1/3/182	Photograph of interior of Portland Building Covered in scaffolding 26 January 1996 100mmx150mm (1 photograph)	1996	BM03-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/3/183	Photograph of interior [lecture theatre?] in Portland Building under construction 26 January 1996 100mmx150mm (1 photograph)	1996	BM03-RRB1
EST/1/1/3/184	Photograph of exterior of Portland Building roof partially covered with scaffolding 26 January 1996 100mmx150mm (1 photograph)	1996	BM03-RRB1
EST/1/1/3/185	Photograph of room in Portland Building under construction 26 January 1996 100mmx150mm (1 photograph)	1996	BM03-RRB1
EST/1/1/3/186	Photograph of room in Portland Building under construction 26 January 1996 100mmx150mm (1 photograph)	1996	BM03-RRB1
EST/1/1/3/187	Photograph of room in Portland Building under construction 26 January 1996 100mmx150mm (1 photograph)	1996	BM03-RRB1
EST/1/1/3/188	Photograph of room in Portland Building under construction with wooden planks leaning against the walls and on the floor 26 January 1996 100mmx150mm (1 photograph)	1996	BM03-RRB1
EST/1/1/3/189	Photograph of exterior of Portland Building Under construction taken from the roof 26 January 1996 100mmx150mm (1 photograph)	1996	BM03-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/3/190	Photograph of room in Portland Building under construction with one small window 26 January 1996 100mmx150mm (1 photograph)	1996	BM03-RRB1
EST/1/1/3/191	Photograph of exterior side of Portland Building under construction 26 January 1996 100mmx150mm (1 photograph)	1996	BM03-RRB1
EST/1/1/3/192	Photograph of room in Portland Building under construction 26 January 1996 100mmx150mm (1 photograph)	1996	BM03-RRB1
EST/1/1/3/193	Photograph of room in Portland Building under construction 26 January 1996 100mmx150mm (1 photograph)	1996	BM03-RRB1
EST/1/1/3/194	Photograph of interior room in Portland Building under construction with door covered in clear plastic 26 January 1996 100mmx150mm (1 photograph)	1996	BM03-RRB1
EST/1/1/3/195	Photograph of exterior of Portland Building - view from Portland Street with Buckingham Building just visible on right Undated 100mmx150mm (1 photograph)	[1996]	BM03-RRB1
EST/1/1/3/196	Photograph of room in Portland Building under construction 26 April 1996 100mmx150mm (1 photograph)	1996	BM03-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/3/197	Photograph of room in Portland Building under construction Undated 100mmx150mm (1 photograph)	[1996]	BM03-RRB1
EST/1/1/3/198	Photograph of exterior of Portland Building taken from roof 26 April 1996 100mmx150mm (1 photograph)	1996	BM03-RRB1
EST/1/1/3/199	Photograph of interior of Portland Building under construction 26 April 1996 100mmx150mm (1 photograph)	1996	BM03-RRB1
EST/1/1/3/200	Photograph of exterior roof of Portland Building with wooden ladder leaning against building 26 April 1996 100mmx150mm (1 photograph)	1996	BM03-RRB1
EST/1/1/3/201	Photograph of room in Portland Building under construction 26 April 1996 100mmx150mm (1 photograph)	1996	BM03-RRB1
EST/1/1/3/202	Photograph of exterior of Portland Building taken from roof 26 April 1996 100mmx150mm (1 photograph)	1996	BM03-RRB1
EST/1/1/3/203	Photograph of exterior of Portland Building and courtyard with new trees – view from roof 26 April 1996 100mmx150mm (1 photograph)	1996	BM03-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/3/204	Photograph of interior of Portland Building under construction 26 April 1996 100mmx150mm (1 photograph)	1996	BM03-RRB1
EST/1/1/3/205	Photograph of exterior of Portland Building and courtyard with new trees – view from roof 26 April 1996 100mmx150mm (1 photograph)	1996	BM03-RRB1
EST/1/1/3/206	Photograph of exterior of Portland Building and Beneficial Foundation Quinnell Centre - view from corner of St James' and Street and Portland Street 26 April 1996 100mmx150mm (1 photograph)	1996	BM03-RRB1
EST/1/1/3/207	Photograph of interior of Portland Building - wooden walkway 26 April 1996 100mmx150mm (1 photograph)	1996	BM03-RRB1
EST/1/1/3/208	Photograph of room in Portland Building under construction 26 April 1996 100mmx150mm (1 photograph)	1996	BM03-RRB1
EST/1/1/3/209	Photograph of exterior of Portland Building with green skip outside 26 April 1996 100mmx150mm (1 photograph)	1996	BM03-RRB1
EST/1/1/3/210	Photograph of exterior of Portland Building - view from car park 26 April 1996 100mmx150mm (1 photograph)	1996	BM03-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/3/211	Photograph of exterior of Portland Building with Buckingham Building visible in background 26 February 1996 100mmx150mm (1 photograph)	1996	BM03-RRB1
EST/1/1/3/212	Photograph of room in Portland Building under construction 26 February 1996 100mmx150mm (1 photograph)	1996	BM03-RRB1
EST/1/1/3/213	Photograph of exterior of Portland Building and courtyard filled with building materials 26 February 1996 100mmx150mm (1 photograph)	1996	BM03-RRB1
EST/1/1/3/214	Photograph of interior of Portland Building under construction 26 February 1996 100mmx150mm (1 photograph)	1996	BM03-RRB1
EST/1/1/3/215	Photograph of exterior of Portland Building - view from corner of St James' Street and Portland Street with Beneficial Foundation Quinnell Centre on left 26 February 1996 100mmx150mm (1 photograph)	1996	BM03-RRB1
EST/1/1/3/216	Photograph of room in Portland Building under construction 26 February 1996 100mmx150mm (1 photograph)	1996	BM03-RRB1
EST/1/1/3/217	Photograph of exterior of Portland Building with Norwest Holst sign – view from St James' Street 26 February 1996 100mmx150mm (1 photograph)	1996	BM03-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/3/218	Photograph of room in Portland Building under construction 26 February 1996 100mmx150mm (1 photograph)	1996	BM03-RRB1
EST/1/1/3/219	Photograph of interior staircase in Portland Building under construction 26 February 1996 100mmx150mm (1 photograph)	1996	BM03-RRB1
EST/1/1/3/220	Photograph of interior of Portland Building under construction -view from above 26 February 1996 100mmx150mm (1 photograph)	1996	BM03-RRB1
EST/1/1/3/221	Photograph of interior roof in Portland Building 26 February 1996 100mmx150mm (1 photograph)	1996	BM03-RRB1
EST/1/1/3/222	Photograph of interior of Portland Building under construction - view from above 26 February 1996 100mmx150mm (1 photograph)	1996	BM03-RRB1
EST/1/1/3/223	Photograph of interior hallway and room in Portland Building under construction 26 February 1996 100mmx150mm (1 photograph)	1996	BM03-RRB1
EST/1/1/3/224	Photograph of interior [lecture theatre?] in Portland Building under construction 26 February 1996 100mmx150mm (1 photograph)	1996	BM03-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/3/225	Photograph of room in Portland Building under construction 26 February 1996 100mmx150mm (1 photograph)	1996	BM03-RRB1
EST/1/1/3/226	Photograph of exterior of Portland Building from courtyard Undated 100mmx150mm (1 photograph)	[1996]	BM03-RRB1
EST/1/1/3/227	Photograph of exterior of Portland Building and Buckingham Building 26 February 1996 100mmx150mm (1 photograph)	1996	BM03-RRB1
EST/1/1/3/228	Photograph of exterior of Portland Building taken from the car park 26 February 1996 100mmx150mm (1 photograph)	1996	BM03-RRB1
EST/1/1/3/229	Photograph of exterior of Portland Building - view from corner of St James' Street and Portland Street with Beneficial Foundation Quinnell Centre on the left 26 February 1996 100mmx150mm (1 photograph)	1996	BM03-RRB1

Reference	Description	Date	Shelf Mark
<i>Purbeck Street Fire</i>			
<i>See also EST/1/2/16/9 Photograph front and side exterior</i>			
EST/1/1/3/230	Photograph of exterior of fire damaged building with a skip outside and a street sign for 'Purbeck Street' Undated 100mmx150mm (1 photograph)	1990s	BM03-RRB1
EST/1/1/3/231	Photograph of exterior of fire damaged building in Purbeck Street Undated 100mmx150mm (1 photograph)	1990s	BM03-RRB1
EST/1/1/3/232	Photograph of exterior of fire damaged building in Purbeck Street with three men putting debris in a skip Undated 100mmx150mm (1 photograph)	1990s	BM03-RRB1
EST/1/1/3/233	Photograph of exterior of fire damaged building in Purbeck Street with three men putting debris in a skip Undated 100mmx150mm (1 photograph)	1990s	BM03-RRB1
EST/1/1/3/234	Photograph of exterior of fire damaged building in Purbeck Street Undated 100mmx150mm (1 photograph)	1990s	BM03-RRB1
EST/1/1/3/235	Photograph of Purbeck Street sign in close-up Undated 100mmx150mm (1 photograph)	1990s	BM03-RRB1
EST/1/1/3/236	Photograph of fire damaged building in Purbeck Street with four men sweeping up debris Undated 100mmx150mm (1 photograph)	1990s	BM03-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/3/237	Photograph of interior of fire damaged building in Purbeck Street Undated 100mmx150mm (1 photograph)	1990s	BM03-RRB1
EST/1/1/3/238	Photograph of exterior of fire damaged building in Purbeck Street – close-up on windows Undated 100mmx150mm (1 photograph)	1990s	BM03-RRB1
EST/1/1/3/239	Photograph of exterior of fire damaged building in Purbeck Street – Richmond Place and Lion Terrace street signs visible Undated 100mmx150mm (1 photograph)	1990s	BM03-RRB1
EST/1/1/3/240	Photograph of [rear?] exterior of fire damaged building in Purbeck Street – area with two vehicles parked behind Undated 100mmx150mm (1 photograph)	1990s	BM03-RRB1
EST/1/1/3/241	Photograph of exterior of fire damaged building in Purbeck Street under demolition Undated 100mmx150mm (1 photograph)	1990s	BM03-RRB1
EST/1/1/3/242	Photograph of exterior of fire damaged building in Purbeck Street in close-up Undated 100mmx150mm (1 photograph)	1990s	BM03-RRB1
EST/1/1/3/243	Photograph of exterior of fire damaged building in Purbeck Street under demolition Undated 100mmx150mm (1 photograph)	1990s	BM03-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/3/244	Photograph of exterior of fire damaged building in Purbeck Street under demolition Undated 100mmx150mm (1 photograph)	1990s	BM03-RRB1
EST/1/1/3/245	Photograph of exterior of fire damaged building in Purbeck Street under demolition Undated 100mmx150mm (1 photograph)	1990s	BM03-RRB1
EST/1/1/3/246	Photograph of exterior of fire damaged building in Purbeck Street under demolition Undated 100mmx150mm (1 photograph)	1990s	BM03-RRB1
EST/1/1/3/247	Photograph of area in Purbeck Street after demolition of 1990s fire damaged building Undated 100mmx150mm (1 photograph)		BM03-RRB1
EST/1/1/3/248	Photograph of area in Purbeck Street after demolition of 1990s fire damaged building Undated 100mmx150mm (1 photograph)		BM03-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/4	'Ravelin site to Wiltshire'	1990s-[2002]	
<i>Ravelin House</i>			
EST/1/1/4/1	Contact sheet with three images of exterior of Ravelin House Undated 210mmx290mm (1 contact sheet)	1990s	BM03-RRB1
EST/1/1/4/2	Contact sheet with seven images of exterior of Ravelin House Undated 210mmx290mm (1 contact sheet)	1990s	BM03-RRB1
EST/1/1/4/3	Contact sheet with seven images of exterior of Ravelin House Undated 210mmx290mm (1 contact sheet)	1990s	BM03-RRB1
<i>Richmond House</i>			
EST/1/1/4/4	Photograph of front exterior of Richmond House with scaffolding and boarded up windows [prior to demolition?] - view from Burnaby Road Undated 100mmx150mm (1 photograph)	[2002?]	BM04-RRB1
EST/1/1/4/5	Photograph of front exterior of Richmond House with scaffolding and boarded up windows [prior to demolition?] – view from Burnaby Road with Milldam Building visible on left Undated 100mmx150mm (1 photograph)	[2002?]	BM04-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/4/6	Photograph of front exterior of Richmond House with boarded up windows [prior to demolition?] – view from Burnaby Road Undated 100mmx150mm (1 photograph)	[2002?]	BM04-RRB1
<i>St. George's Building Prior to Alterations</i>			
EST/1/1/4/7	Photograph of seminar room in St George's Building with furniture removed Undated 130mmx180mm (1 photograph)	1990s	BM04-RRB1
EST/1/1/4/8	Photograph of empty room in St. George's Building - view through two doorways Undated 130mmx180mm (1 photograph)	1990s	BM04-RRB1
EST/1/1/4/9	Photograph of interior corridor in St. George's Building with two lifts and a feather duster on the ground Undated 130mmx180mm (1 photograph)	1990s	BM04-RRB1
EST/1/1/4/10	Photograph of interior corridor in St. George's Building Undated 130mmx180mm (1 photograph)	1990s	BM04-RRB1
EST/1/1/4/11	Photograph of interior corridor in St. George's Building Undated 130mmx180mm (1 photograph)	1990s	BM04-RRB1
EST/1/1/4/12	Photograph of interior corridor in St. George's Building with signs on doors reading ['Barry Reavill' and 'David Hatborn'?] Undated 130mmx180mm (1 photograph)	1990s	BM04-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/4/13	Photograph of a common room? in St. George's Building with a pool table and blue chairs - same room as EST/1/1/4/15 + 16 Undated 130mmx180mm (1 photograph)	1990s	BM04-RRB1
EST/1/1/4/14	Photograph of a lecture theatre in St. George's Building Undated 130mmx180mm (1 photograph)	1990s	BM04-RRB1
EST/1/1/4/15	Photograph of a common room? in St. George's Building - same room as EST/1/1/4/13 + 16 Undated 130mmx180mm (1 photograph)	1990s	BM04-RRB1
EST/1/1/4/16	Photograph of a common room? in St. George's Building - same room as EST/1/1/4/13 + 15 Undated 130mmx180mm (1 photograph)	1990s	BM04-RRB1
EST/1/1/4/17	Photograph of a kitchen in St. George's Building Undated 130mmx180mm (1 photograph)	1990s	BM04-RRB1
EST/1/1/4/18	Photograph of interior room in St. George's Building Undated 130mmx180mm (1 photograph)	1990s	BM04-RRB1
EST/1/1/4/19	Photograph of a kitchen in St. George's Building Undated 130mmx180mm (1 photograph)	1990s	BM04-RRB1
EST/1/1/4/20	Photograph of a kitchen in St. George's Building Undated 130mmx180mm (1 photograph)	1990s	BM04-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/4/21	Photograph of a kitchen in St. George's Building Undated 130mmx180mm (1 photograph)	1990s	BM04-RRB1
EST/1/1/4/22	Photograph of a kitchen in St. George's Building Undated 130mmx180mm (1 photograph)	1990s	BM04-RRB1
EST/1/1/4/23	Photograph of a kitchen in St. George's Building Undated 130mmx180mm (1 photograph)	1990s	BM04-RRB1
EST/1/1/4/24	Photograph of a locker/changing room in St. George's Building – view from toilets Undated 130mmx180mm (1 photograph)	1990s	BM04-RRB1
EST/1/1/4/25	Photograph of interior of St. George's Building with a large sliding metal door to a goods lift? Undated 130mmx180mm (1 photograph)	1990s	BM04-RRB1
EST/1/1/4/26	Photograph of toilets in St. George's Building Undated 130mmx180mm (1 photograph)	1990s	BM04-RRB1
EST/1/1/4/27	Photograph of the basement in St. George's Building with a Christmas tree lying on the floor Undated 130mmx180mm (1 photograph)	1990s	BM04-RRB1
EST/1/1/4/28	Photograph of the basement in St. George's Building filled with miscellaneous items Undated 130mmx180mm (1 photograph)	1990s	BM04-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/4/29	<p>Photograph of empty room in St. George's Building with empty wooden shelves</p> <p>Undated</p> <p>130mmx180mm</p> <p>(1 photograph)</p>	1990s	BM04-RRB1
EST/1/1/4/30	<p>Photograph of a locker/changing room in St. George's Building with two urinals</p> <p>Undated</p> <p>130mmx180mm</p> <p>(1 photograph)</p>	1990s	BM04-RRB1
EST/1/1/4/31	<p>Photograph of room in St. George's Building with a red fire extinguisher holding the door open and stacked chairs</p> <p>Undated</p> <p>130mmx180mm</p> <p>(1 photograph)</p>	1990s	BM04-RRB1
EST/1/1/4/32	<p>Photograph of interior corridor in St. George's Building with a white bucket on the floor</p> <p>Undated</p> <p>130mmx180mm</p> <p>(1 photograph)</p>	1990s	BM04-RRB1
EST/1/1/4/33	<p>Photograph of former cafeteria in St. George's Building with chairs stacked around the room</p> <p>Undated</p> <p>130mmx180mm</p> <p>(1 photograph)</p>	1990s	BM04-RRB1
EST/1/1/4/34	<p>Photograph of interior corridor in St. George's Building</p> <p>Undated</p> <p>130mmx180mm</p> <p>(1 photograph)</p>	1990s	BM04-RRB1
EST/1/1/4/35	<p>Photograph of former staff lounge in St. George's Building with chairs stacked up in the centre of the room and food serving counters along the left</p> <p>Undated</p> <p>130mmx180mm</p> <p>(1 photograph)</p>	1990s	BM04-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/4/36	Photograph of former staff lounge in St. George's Building with chairs stacked up on the left and food serving counters on the right Undated 130mmx180mm (1 photograph)	1990s	BM04-RRB1
EST/1/1/4/37	Photograph of former staff lounge in St. George's Building Undated 130mmx180mm (1 photograph)	1990s	BM04-RRB1
EST/1/1/4/38	Photograph of former staff lounge in St. George's Building with chairs around the edge of the room and a closed serving hatch Undated 130mmx180mm (1 photograph)	1990s	BM04-RRB1
EST/1/1/4/39	Photograph of former staff lounge in St. George's Building - view from entrance to cafeteria Undated 130mmx180mm (1 photograph)	1990s	BM04-RRB1
EST/1/1/4/40	Photograph of entrance to staff lounge in St. George's Building with a sign reading 'Staff Lounge' Undated 130mmx180mm (1 photograph)	1990s	BM04-RRB1
EST/1/1/4/41	Photograph of interior corridor in St. George's Building looking into a former teaching room Undated 130mmx180mm (1 photograph)	1990s	BM04-RRB1
EST/1/1/4/42	Photograph of interior corridor in St. George's Building looking into a former teaching room Undated 130mmx180mm (1 photograph)	1990s	BM04-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/4/43	Photograph of interior corridor in St. George's Building looking into a former teaching room Undated 130mmx180mm (1 photograph)	1990s	BM04-RRB1
EST/1/1/4/44	Photograph of a corridor in St. George's Building showing a reception desk with shutter pulled down Undated 130mmx180mm (1 photograph)	1990s	BM04-RRB1
EST/1/1/4/45	Photograph of a corridor in St. George's Building showing a reception desk with shutter pulled down Undated 130mmx180mm (1 photograph)	1990s	BM04-RRB1
EST/1/1/4/46	Photograph of a corridor in St. George's Building showing a reception desk with shutter pulled down Undated 130mmx180mm (1 photograph)	1990s	BM04-RRB1
EST/1/1/4/47	Photograph of a corridor in St. George's Building showing a reception desk with shutter pulled down Undated 130mmx180mm (1 photograph)	1990s	BM04-RRB1
EST/1/1/4/48	Photograph of a bathroom in St. George's Building Undated 130mmx180mm (1 photograph)	1990s	BM04-RRB1
EST/1/1/4/49	Photograph of a bathroom in St. George's Building Undated 130mmx180mm (1 photograph)	1990s	BM04-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/4/50	Photograph of a bedroom in St. George's Building Undated 130mmx180mm (1 photograph)	1990s	BM04-RRB1
EST/1/1/4/51	Photograph of a bedroom in St. George's Building Undated 130mmx180mm (1 photograph)	1990s	BM04-RRB1
EST/1/1/4/52	Photograph of a lounge in St. George's Building with a brown sofa Undated 130mmx180mm (1 photograph)	1990s	BM04-RRB1
EST/1/1/4/53	Photograph of a bedroom in St. George's Building Undated 130mmx180mm (1 photograph)	1990s	BM04-RRB1
EST/1/1/4/54	Photograph of a bedroom in St. George's Building Undated 130mmx180mm (1 photograph)	1990s	BM04-RRB1
EST/1/1/4/55	Photograph of a hallway in St. George's Building in a student living area Undated 130mmx180mm (1 photograph)	1990s	BM04-RRB1
EST/1/1/4/56	Photograph of a hallway in St. George's Building in a student living area Undated 130mmx180mm (1 photograph)	1990s	BM04-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/4/57	Photograph of a kitchen in St. George's Building in a student living area Undated 130mmx180mm (1 photograph)	1990s	BM04-RRB1
EST/1/1/4/58	Photograph of a room in St. George's Building in a student living area? with armchairs Undated 130mmx180mm (1 photograph)	1990s	BM04-RRB1
EST/1/1/4/59	Photograph of a student living area? in St. George's Building with sofa and armchairs and a wooden dining table Undated 130mmx180mm (1 photograph)	1990s	BM04-RRB1
EST/1/1/4/60	Photograph of a student living area? in St. George's Building with sofa and armchairs and a wooden dining table with Portsmouth Museum visible through window Undated 130mmx180mm (1 photograph)	1990s	BM04-RRB1
EST/1/1/4/61	Photograph of a student living area? in St. George's Building with armchairs and sofa Undated 130mmx180mm (1 photograph)	1990s	BM04-RRB1
EST/1/1/4/62	Photograph of interior of St. George's Building Close-up of brick wall and pipework Undated 130mmx180mm (1 photograph)	1990s	BM04-RRB1
EST/1/1/4/63	Photograph of a student living area? in St. George's Building with armchairs and sofa Undated 130mmx180mm (1 photograph)	1990s	BM04-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/4/64	Photograph of interior hallway in St. George's Building with three wooden doors Undated 130mmx180mm (1 photograph)	1990s	BM04-RRB1
EST/1/1/4/65	Photograph of student living area? in St. George's Building with sofa and armchairs and a wooden dining table with Portsmouth Museum visible through window Undated 130mmx180mm (1 photograph)	1990s	BM04-RRB1
EST/1/1/4/66	Photograph of a corridor in St. George's Building with a lift Undated 130mmx180mm (1 photograph)	1990s	BM04-RRB1
EST/1/1/4/67	Photograph of a bedroom in St. George's Building with a noticeboard above the bed Undated 130mmx180mm (1 photograph)	1990s	BM04-RRB1
EST/1/1/4/68	Photograph of the interior of St. George's Building showing both a bathroom and bedroom Undated 130mmx180mm (1 photograph)	1990s	BM04-RRB1
EST/1/1/4/69	Photograph of the interior St. George's Building showing both a bathroom and bedroom with a wooden desk under window Undated 130mmx180mm (1 photograph)	1990s	BM04-RRB1
EST/1/1/4/70	Photograph of a room in St. George's Building containing tables and chairs Undated 130mmx180mm (1 photograph)	1990s	BM04-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/4/71	Photograph of interior room in St. George's Building showing both a bathroom and bedroom with a wooden desk under window Undated 130mmx180mm (1 photograph)	1990s	BM04-RRB1
EST/1/1/4/72	Photograph of a room in St. George's Building with tables and chairs Undated 130mmx180mm (1 photograph)	1990s	BM04-RRB1
EST/1/1/4/73	Photograph of a former bedroom in St. George's Building with a noticeboard but the bed removed Undated 130mmx180mm (1 photograph)	1990s	BM04-RRB1

St. Michael's Building New Extension

EST/1/1/4/74	Photograph of Prof James D Watson standing next to the opening plaque at the opening of St. Michael's Building extension 13 March 1997 130mmx180mm (1 photograph)	1997	BM04-RRB1
EST/1/1/4/75	Photograph of a science laboratory in St. Michael's Building with staff/students 130mmx180mm (1 photograph)	1997	BM04-RRB1
EST/1/1/4/76	Photograph of a lecture theatre in St. Michael's Building with red walls 130mmx180mm (1 photograph)	1997	BM04-RRB1
EST/1/1/4/77	Photograph of the front exterior of St. Michael's Building – a close-up of the 'University of Portsmouth' sign 130mmx180mm (1 photograph)	1997	BM04-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/4/78	Photograph of exterior of St. Michael's Building [old and new extension] with Park Building visible on left 130mmx180mm (1 photograph)	1997	BM04-RRB1
EST/1/1/4/79	Photograph of a laboratory in St. Michael's Building 130mmx180mm (1 photograph)	1997	BM04-RRB1
EST/1/1/4/80	Photograph of a student/member of staff Working in a laboratory in St. Michael's Building with blue tint to lighting 130mmx180mm (1 photograph)	1997	BM04-RRB1
EST/1/1/4/81	Photograph of front exterior of St. Michael's Building extension taken from junction of Anglesea Road and St Michael's Road 130mmx180mm (1 photograph)	1997	BM04-RRB1
EST/1/1/4/82	Photograph of front exterior of St. Michael's Building extension – view from upper floor of Nuffield Building with St Andrews Court, King Henry Building and Portsmouth Guildhall Clock 130mmx180mm (1 photograph)	1997	BM04-RRB1
EST/1/1/4/83	Photograph of interior staircase in St. Michael's Building with circular lights on the ceiling 130mmx180mm (1 photograph)	1997	BM04-RRB1

Reference	Description	Date	Shelf Mark
<i>St Paul's Sports Hall</i>			
<i>See also EST/1/4/1 image of exterior</i>			
EST/1/1/4/84	Photograph of interior stairwell in St Paul's Sports Hall Undated 130mmx180mm (1 photograph)	[2000]	BM04-RRB1
EST/1/1/4/85	Photograph of interior room in St Paul's Sports Hall with a builder visible through the doorway Undated 130mmx180mm (1 photograph)	[2000]	BM04-RRB1
EST/1/1/4/86	Photograph of interior of St Paul's Sports Hall under renovation Undated 130mmx180mm (1 photograph)	[2000]	BM04-RRB1
EST/1/1/4/87	Photograph of interior staircase in St Paul's Sports Hall - view from top of stairs Undated 130mmx180mm (1 photograph)	[2000]	BM04-RRB1
EST/1/1/4/88	Photograph of interior of St Paul's Sports Hall with under renovation Undated 130mmx180mm (1 photograph)	[2000]	BM04-RRB1
EST/1/1/4/89	Photograph of interior of St Paul's Sports Hall under renovation Undated 130mmx180mm (1 photograph)	[2000]	BM04-RRB1
EST/1/1/4/90	Photograph of interior of St Paul's Sports Hall under renovation Undated 130mmx180mm (1 photograph)	[2000]	BM04-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/4/91	Photograph of interior of St Paul's Sports Hall under renovation Undated 130mmx180mm (1 photograph)	[2000]	BM04-RRB1
EST/1/1/4/92	Photograph of interior of St Paul's Sports Hall Undated under renovation 130mmx180mm (1 photograph)	[2000]	BM04-RRB1
EST/1/1/4/93	Photograph of interior of St Paul's Sports Hall under renovation Undated 130mmx180mm (1 photograph)	[2000]	BM04-RRB1
EST/1/1/4/94	Photograph of interior of St Paul's Sports Hall under renovation Undated 130mmx180mm (1 photograph)	[2000]	BM04-RRB1
EST/1/1/4/95	Photograph of interior of St Paul's Sports Hall under renovation with a builder cutting a metal beam creating sparks Undated 130mmx180mm (1 photograph)	[2000]	BM04-RRB1
EST/1/1/4/96	Photograph of interior of St Paul's Sports Hall under renovation with a builder cutting a metal beam creating sparks Undated 130mmx180mm (1 photograph)	[2000]	BM04-RRB1
EST/1/1/4/97	Photograph of interior of St Paul's Sports Hall under renovation Undated 130mmx180mm (1 photograph)	[2000]	BM04-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/4/98	Photograph of interior of St Paul's Sports Hall Under renovation Undated 130mmx180mm (1 photograph)	[2000]	BM04-RRB1
EST/1/1/4/99	Photograph of interior of St Paul's Sports Hall - plant room? Undated 130mmx180mm (1 photograph)	[2000]	BM04-RRB1
EST/1/1/4/100	Photograph of interior of St Paul's Sports Hall - plant room? Undated 130mmx180mm (1 photograph)	[2000]	BM04-RRB1
EST/1/1/4/101	Photograph of interior of St Paul's Sports Hall - plant room? Undated 130mmx180mm (1 photograph)	[2000]	BM04-RRB1
EST/1/1/4/102	Photograph of interior of St Paul's Sports Hall - empty room with hifi equipment? Undated 130mmx180mm (1 photograph)	[2000]	BM04-RRB1
EST/1/1/4/103	Photograph of interior of St Paul's Sports Hall with a - empty room with hifi equipment? Undated 130mmx180mm (1 photograph)	[2000]	BM04-RRB1
EST/1/1/4/104	Photograph of interior of St Paul's Sports Hall under renovation Undated 130mmx180mm (1 photograph)	[2000]	BM04-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/4/105	Photograph of interior of St Paul's Sports Hall under renovation Undated 130mmx180mm (1 photograph)	[2000]	BM04-RRB1
EST/1/1/4/106	Photograph of interior of St Paul's Sports Hall under renovation Undated 130mmx180mm (1 photograph)	[2000]	BM04-RRB1
EST/1/1/4/107	Photograph of interior of St Paul's Sports Hall under renovation Undated 130mmx180mm (1 photograph)	[2000]	BM04-RRB1
EST/1/1/4/108	Photograph of interior of St Paul's Sports Hall under renovation Undated 130mmx180mm (1 photograph)	[2000]	BM04-RRB1
EST/1/1/4/109	Photograph of interior of St Paul's Sports Hall under renovation Undated 130mmx180mm (1 photograph)	[2000]	BM04-RRB1
EST/1/1/4/110	Photograph of interior of St Paul's Sports Hall under renovation Undated 130mmx180mm (1 photograph)	[2000]	BM04-RRB1
EST/1/1/4/111	Photograph of interior of St Paul's Sports Hall under renovation Undated 130mmx180mm (1 photograph)	[2000]	BM04-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/4/112	Photograph of interior of St Paul's Sports Hall under renovation Undated 130mmx180mm (1 photograph)	[2000]	BM04-RRB1
EST/1/1/4/113	Photograph of interior of St Paul's Sports Hall under renovation Undated 130mmx180mm (1 photograph)	[2000]	BM04-RRB1
EST/1/1/4/114	Photograph of interior of St Paul's Sports Hall under renovation Undated 130mmx180mm (1 photograph)	[2000]	BM04-RRB1
EST/1/1/4/115	Photograph of interior of St Paul's Sports Hall under renovation Undated 130mmx180mm (1 photograph)	[2000]	BM04-RRB1
EST/1/1/4/116	Photograph of interior of St Paul's Sports Hall under renovation Undated 130mmx180mm (1 photograph)	[2000]	BM04-RRB1
EST/1/1/4/117	Photograph of interior of St Paul's Sports Hall under renovation Undated 130mmx180mm (1 photograph)	[2000]	BM04-RRB1
EST/1/1/4/118	Photograph of interior of St Paul's Sports Hall under renovation Undated 130mmx180mm (1 photograph)	[2000]	BM04-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/4/119	Photograph of a room in St Paul's Sports Hall containing tables and chairs – used by builders? Undated 130mmx180mm (1 photograph)	[2000]	BM04-RRB1
EST/1/1/4/120	Photograph of a room in St Paul's Sports Hall with a wooden ladder and cabinets pushed against the wall Undated 130mmx180mm (1 photograph)	[2000]	BM04-RRB1
EST/1/1/4/121	Photograph of an empty room in St Paul's Sports Hall Undated 130mmx180mm (1 photograph)	[2000]	BM04-RRB1
EST/1/1/4/122	Photograph of an empty room in St Paul's Sports Hall with rubbish on the floor Undated 130mmx180mm (1 photograph)	[2000]	BM04-RRB1
EST/1/1/4/123	Photograph of an empty room in St Paul's Sports Hall Undated 130mmx180mm (1 photograph)	[2000]	BM04-RRB1
EST/1/1/4/124	Photograph of an empty room in St Paul's Sports Hall Undated 130mmx180mm (1 photograph)	[2000]	BM04-RRB1
EST/1/1/4/125	Photograph of interior of St Paul's Sports Hall under renovation Undated 130mmx180mm (1 photograph)	[2000]	BM04-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/4/126	Photograph of interior of St Paul's Sports Hall under renovation Undated 130mmx180mm (1 photograph)	[2000]	BM04-RRB1
EST/1/1/4/127	Photograph of interior of St Paul's Sports Hall under renovation Undated 130mmx180mm (1 photograph)	[2000]	BM04-RRB1
EST/1/1/4/128	Photograph of interior of St Paul's Sports Hall under renovation Undated 130mmx180mm (1 photograph)	[2000]	BM04-RRB1
EST/1/1/4/129	Photograph of interior of St Paul's Sports Hall under renovation – demolition vehicle Undated 130mmx180mm (1 photograph)	[2000]	BM04-RRB1
EST/1/1/4/130	Photograph of an empty room in St Paul's Sports Hall with a ladder leaning against the far wall Undated 130mmx180mm (1 photograph)	[2000]	BM04-RRB1
EST/1/1/4/131	Photograph of an empty room in St Paul's Sports Hall with a ladder leaning against the far wall Undated 130mmx180mm (1 photograph)	[2000]	BM04-RRB1
EST/1/1/4/132	Photograph of an empty room in St Paul's Sports Hall with a ladder leaning against the far wall Undated 130mmx180mm (1 photograph)	[2000]	BM04-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/4/133	Photograph of an empty room in St Paul's Sports Hall with a ladder leaning against the far wall Undated 130mmx180mm (1 photograph)	[2000]	BM04-RRB1
EST/1/1/4/134	Photograph of an empty room in St Paul's Sports Hall with a University of Portsmouth sign on a white door 130mmx180mm (1 photograph)	[2000]	BM04-RRB1
EST/1/1/4/135	Photograph of a stairwell in St Paul's Sports Hall Undated 130mmx180mm (1 photograph)	[2000]	BM04-RRB1
EST/1/1/4/136	Photograph of a hallway in St Paul's Sports Hall red metal girders Undated 130mmx180mm (1 photograph)	[2000]	BM04-RRB1
EST/1/1/4/137	Photograph of a hallway in St Paul's Sports Hall with a stairwell on the left and coat hooks along the wall Undated 130mmx180mm (1 photograph)	[2000]	BM04-RRB1
EST/1/1/4/138	Photograph of a hallway in St Paul's Sports Hall with a stairwell on the left and coat hooks along the wall Undated 130mmx180mm (1 photograph)	[2000]	BM04-RRB1
EST/1/1/4/139	Photograph of a stairwell in St Paul's Sports Hall Undated 130mmx180mm (1 photograph)	[2000]	BM04-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/4/140	Photograph of a stairwell in St Paul's Sports Hall Undated 130mmx180mm (1 photograph)	[2000]	BM04-RRB1
EST/1/1/4/141	Photograph of a hallway in St Paul's Sports Hall with a small set of wooden stairs Undated 130mmx180mm (1 photograph)	[2000]	BM04-RRB1
EST/1/1/4/142	Photograph of an empty room in St Paul's Sports Hall Undated 130mmx180mm (1 photograph)	[2000]	BM04-RRB1
EST/1/1/4/143	Photograph of an empty room in St Paul's Sports Hall with a brown ceiling Undated 130mmx180mm (1 photograph)	[2000]	BM04-RRB1
EST/1/1/4/144	Photograph of a hallway in St Paul's Sports Hall with stairs on the left and a doorway with a sign reading 'Sister's Prayer Room' Undated 130mmx180mm (1 photograph)	[2000]	BM04-RRB1
EST/1/1/4/145	Photograph of an empty room in St Paul's Sports Hall with a brown ceiling Undated 130mmx180mm (1 photograph)	[2000]	BM04-RRB1
EST/1/1/4/146	Photograph of an empty room in St Paul's Sports Hall with a brown ceiling Undated 130mmx180mm (1 photograph)	[2000]	BM04-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/4/147	Photograph of a stairwell in St Paul's Sports Hall Undated 130mmx180mm (1 photograph)	[2000]	BM04-RRB1
EST/1/1/4/148	Photograph of an empty room in St Paul's Sports Hall with a brown ceiling Undated 130mmx180mm (1 photograph)	[2000]	BM04-RRB1
EST/1/1/4/149	Photograph of an empty room in St Paul's Sports Hall with a red vaulted ceiling Undated 130mmx180mm (1 photograph)	[2000]	BM04-RRB1
EST/1/1/4/150	Photograph of an empty room in St Paul's Sports Hall with a red vaulted ceiling Undated 130mmx180mm (1 photograph)	[2000]	BM04-RRB1
EST/1/1/4/151	Photograph of an empty room in St Paul's Sports Hall with a small flight of steps leading to an open doorway Undated 130mmx180mm (1 photograph)	[2000]	BM04-RRB1
EST/1/1/4/152	Photograph of an empty room in St Paul's Sports Hall with a red vaulted ceiling Undated 130mmx180mm (1 photograph)	[2000]	BM04-RRB1
EST/1/1/4/153	Photograph of an empty room in St Paul's Sports Hall with a small flight of steps leading to an open doorway to a toilet Undated 130mmx180mm (1 photograph)	[2000]	BM04-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/4/154	Photograph of a toilet in St Paul's Sports Hall with two sinks – one coming away from the wall Undated 130mmx180mm (1 photograph)	[2000]	BM04-RRB1
EST/1/1/4/155	Photograph of the ceiling of a room in St Paul's Sports Hall with water damage in close -up Undated 130mmx180mm (1 photograph)	[2000]	BM04-RRB1
EST/1/1/4/156	Photograph of the ceiling of a room in St Paul's Sports Hall with water damage in close -up Undated 130mmx180mm (1 photograph)	[2000]	BM04-RRB1
EST/1/1/4/157	Photograph of a stairwell in St Paul's Sports Hall Undated 130mmx180mm (1 photograph)	[2000]	BM04-RRB1
EST/1/1/4/158	Photograph of an empty room in St Paul's Sports Hall with dark green walls Undated 130mmx180mm (1 photograph)	[2000]	BM04-RRB1
EST/1/1/4/159	Photograph of an empty room in St Paul's Sports Hall with dark green walls Undated 130mmx180mm (1 photograph)	[2000]	BM04-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/5	'Miscellaneous and Environmental'	1990s	
<i>Aerial Photos</i>			
EST/1/1/5/1	Contact sheet of various aerial photographs of Portsea Island including Portsea and Old Portsmouth Undated 210mmx300mm (1 contact sheet)	1990s	BM05-RRB1
EST/1/1/5/2	Contact sheet of various aerial photographs of Portsea Island including Portland Building; Buckingham Building; Lion Gate Building; Burnaby Building; Park Building; St Michael's Building; King Henry Building; Anglesea Building; Nuffield; Mercantile House; Alexandra House; University Library; Town Mount; and Rees Hall Undated 210mmx300mm (1 contact sheet)	1990s	BM05-RRB1
EST/1/1/5/3	Contact sheet of various aerial photographs of Portsea Island including Langstone campus Undated 210mmx300mm (1 contact sheet)	1990s	BM05-RRB1
EST/1/1/5/4	Contact sheet of various aerial photographs of Gosport and Portsea Island including Old Portsmouth; Portsea and Southsea Undated 210mmx300mm (1 contact sheet)	1990s	BM05-RRB1
EST/1/1/5/5	Contact sheet of various aerial photographs of Eastney and Milton including Langstone campus Undated 210mmx300mm (1 contact sheet)	1990s	BM05-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/5/6	Contact sheet of various aerial photographs of Portsea Island [identical to EST/1/1/5/2?] Undated 210mmx300mm (1 contact sheet)	1990s	BM05-RRB1
EST/1/1/5/7	Contact sheet of various aerial photographs of Portsea Island including Portland Building; Burnaby Building; Anglesea Building; Buckingham Building; Lion Gate Building; Milldam; Park Building; Tricorn Centre and Southsea Common Undated 210mmx300mm (1 contact sheet)	1990s	BM05-RRB1
EST/1/1/5/8	Contact sheet of various aerial photographs of Langstone – area north of Hayling Island Undated 210mmx300mm (1 contact sheet)	1990s	BM05-RRB1
EST/1/1/5/9	Contact sheet of various aerial photographs of Portsea Island including Portland Building; Buckingham Building; Lion Gate Building; Burnaby Building; Park Building; St Michael's Building; King Henry Building; Anglesea Building and Nuffield Undated 210mmx300mm (1 contact sheet)	1990s	BM05-RRB1
EST/1/1/5/10	Contact sheet of various aerial photographs of Portsea Island including St George's Building; University Library; Alexandra House; St Michael's Building; King Henry Building; Mercantile House; Nuffield; Anglesea Building; Buckingham Building; Lion Gate Building and Eastney Esplanade Undated 210mmx300mm (1 contact sheet)	1990s	BM05-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/5/11	Contact sheet of various aerial photographs of Portsea Island including Rees Hall; Portland Building; Buckingham Building; Lion Gate Building; Burnaby Building; Park Building; St Michael's Building; King Henry Building; Anglesea Building; Nuffield and H.M.S. Warrior Undated 210mmx300mm (1 contact sheet)	1990s	BM05-RRB1
EST/1/1/5/12	Contact sheet of various aerial photographs of Portsea Island including Port Solent Undated 210mmx300mm (1 contact sheet)	1990s	BM05-RRB1
EST/1/1/5/13	Contact sheet of various aerial photographs of Portsea Island showing Southsea Common and seafront area Undated 210mmx300mm (1 contact sheet)	1990s	BM05-RRB1
EST/1/1/5/14	Contact sheet of various aerial photographs of Portsea Island including South Common and seafront area Undated 210mmx300mm (1 contact sheet)	1990s	BM05-RRB1

Reference	Description	Date	Shelf Mark
<i>Poor Estate</i>			
<i>See also EST/1/4/20-25 Strays from this section</i>			
EST/1/1/5/15	Photograph of poor estate showing a red pipe buried in the ground Undated 100mmx150mm (1 photograph)	1990s	BM05-RRB1
EST/1/1/5/16	Photograph of poor estate showing a red pipe buried in the ground Undated 100mmx150mm (1 photograph)	1990s	BM05-RRB1
EST/1/1/5/17	Photograph of poor estate showing an unidentified building with the sign 'GO26' Undated 100mmx150mm (1 photograph)	1990s	BM05-RRB1
EST/1/1/5/18	Photograph of poor estate showing a red pipe buried in the ground Undated 100mmx150mm (1 photograph)	1990s	BM05-RRB1
EST/1/1/5/19	Photograph of poor estate showing rubble Undated 100mmx150mm (1 photograph)	1990s	BM05-RRB1
EST/1/1/5/20	Photograph of poor estate showing rubble Undated 100mmx150mm (1 photograph)	1990s	BM05-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/5/21	Photograph of poor estate showing rubble Undated 100mmx150mm (1 photograph)	1990s	BM05-RRB1
EST/1/1/5/22	Photograph of poor estate showing a red pipe buried in the ground Undated 100mmx150mm (1 photograph)	1990s	BM05-RRB1
EST/1/1/5/23	Photograph of poor estate showing a window frame Undated 100mmx150mm (1 photograph)	1990s	BM05-RRB1
EST/1/1/5/24	Photograph of poor estate looking up at a window frame Undated 100mmx150mm (1 photograph)	1990s	BM05-RRB1
EST/1/1/5/25	Photograph of poor estate showing the side of a building with a drainpipe Undated 100mmx150mm (1 photograph)	1990s	BM05-RRB1
EST/1/1/5/26	Photograph of poor estate showing a man standing in a hole digging Undated 100mmx150mm (1 photograph)	1990s	BM05-RRB1
EST/1/1/5/27	Photograph of poor estate showing a bush Undated 100mmx150mm (1 photograph)	1990s	BM05-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/5/28	Photograph of poor estate showing a window frame Undated 100mmx150mm (1 photograph)	1990s	BM05-RRB1
EST/1/1/5/29	Photograph of poor estate showing the part of an unidentified building with ivy growing up the wall Undated 100mmx150mm (1 photograph)	1990s	BM05-RRB1
EST/1/1/5/30	Photograph of poor estate showing the white wall of a building in close up Undated 100mmx150mm (1 photograph)	1990s	BM05-RRB1
EST/1/1/5/31	Photograph of poor estate showing the exterior of 'Nelson Building' [and 'Collingwood Building?'] at Milton Campus Undated 100mmx150mm (1 photograph)	1990s	BM05-RRB1
EST/1/1/5/32	Photograph of poor estate showing the flat roof of a building with leaves and pools of water Undated 100mmx150mm (1 photograph)	1990s	BM05-RRB1
EST/1/1/5/33	Photograph of poor estate showing the roofs of two buildings at Milton Campus - Nelson Building [and Collingwood Building?] Undated 100mmx150mm (1 photograph)	1990s	BM05-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/5/34	Photograph of poor estate showing a tape measure on a crack in a roof? Undated 100mmx150mm (1 photograph)	1990s	BM05-RRB1
EST/1/1/5/35	Photograph of poor estate showing exterior of an unidentified brick building Undated 100mmx150mm (1 photograph)	1990s	BM05-RRB1
EST/1/1/5/36	Photograph of poor estate showing exterior of an unidentified brick building Undated 100mmx150mm (1 photograph)	1990s	BM05-RRB1
EST/1/1/5/37	Photograph of poor estate showing exterior of an unidentified brick building Undated 100mmx150mm (1 photograph)	1990s	BM05-RRB1
EST/1/1/5/38	Photograph of poor estate showing a man in a black coat walking up some steps Undated 100mmx150mm (1 photograph)	1990s	BM05-RRB1
EST/1/1/5/39	Photograph of poor estate showing a brick wall in close up Undated 100mmx150mm (1 photograph)	1990s	BM05-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/5/40	Photograph of poor estate showing a screwdriver embedded in a window frame Undated 100mmx150mm (1 photograph)	1990s	BM05-RRB1
EST/1/1/5/41	Photograph of poor estate showing the rear of a building overgrown with plants 20 November 1997 100mmx150mm (1 photograph)	1997	BM05-RRB1
EST/1/1/5/42	Photograph of poor estate showing the exterior of a building 20 November 1997 100mmx150mm (1 photograph)	1997	BM05-RRB1
EST/1/1/5/43	Photograph of poor estate showing the rear exterior of Park Building 20 November 1997 100mmx150mm (1 photograph)	1997	BM05-RRB1
EST/1/1/5/44	Photograph of poor estate showing showing the rear exterior of Park Building and a corrugated iron building 20 November 1997 100mmx150mm (1 photograph)	1997	BM05-RRB1
EST/1/1/5/45	Photograph of poor estate showing the exterior of a corrugated iron building at the rear of Park Building 20 November 1997 100mmx150mm (1 photograph)	1997	BM05-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/5/46	<p>Photograph of poor estate showing the exterior of a building with white window frames</p> <p>20 November 1997</p> <p>100mmx150mm</p> <p>(1 photograph)</p>	1997	BM05-RRB1
EST/1/1/5/47	<p>Photograph of poor estate showing exterior of a white building with a white car parked outside</p> <p>20 November 1997</p> <p>100mmx150mm</p> <p>(1 photograph)</p>	1997	BM05-RRB1
EST/1/1/5/48	<p>Photograph of poor estate showing The upper section of a brick wall in close-up</p> <p>20 November 1997</p> <p>100mmx150mm</p> <p>(1 photograph)</p>	1997	BM05-RRB1
EST/1/1/5/49	<p>Photograph of poor estate showing a screwdriver embedded in a wall</p> <p>20 November 1997</p> <p>100mmx150mm</p> <p>(1 photograph)</p>	1997	BM05-RRB1
EST/1/1/5/50	<p>Photograph of poor estate showing a screwdriver embedded in a brick wall</p> <p>20 November 1997</p> <p>100mmx150mm</p> <p>(1 photograph)</p>	1997	BM05-RRB1
EST/1/1/5/51	<p>Photograph of poor estate showing a screwdriver embedded in a wooden door frame?</p> <p>20 November 1997</p> <p>100mmx150mm</p> <p>(1 photograph)</p>	1997	BM05-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/5/52	Photograph of poor estate showing corroded garage doors with roof of Portland Building visible in background 20 November 1997 100mmx150mm (1 photograph)	1997	BM05-RRB1
EST/1/1/5/53	Photograph of poor estate showing A screwdriver embedded in a brick wall 20 November 1997 100mmx150mm (1 photograph)	1997	BM05-RRB1
EST/1/1/5/54	Photograph of poor estate showing a window frame with peeling paint 20 November 1997 100mmx150mm (1 photograph)	1997	BM05-RRB1
EST/1/1/5/55	Photograph of poor estate showing the bottom of a yellow door with peeling paint 20 November 1997 100mmx150mm (1 photograph)	1997	BM05-RRB1
EST/1/1/5/56	Photograph of poor estate showing the exterior of an identified building 20 November 1997 100mmx150mm (1 photograph)	1997	BM05-RRB1
EST/1/1/5/57	Photograph of poor estate showing an interior window in closeup 20 November 1997 100mmx150mm (1 photograph)	1997	BM05-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/5/58	Photograph of poor estate looking up at a building with wooden panels 100mmx150mm (1 photograph)	1997	BM05-RRB1
EST/1/1/5/59	Photograph of poor estate showing a the exterior of a building with grey door and 19 November 1997 100mmx150mm (1 photograph)	1997	BM05-RRB1
EST/1/1/5/60	Photographic negatives of poor estate showing photographs 15-39 [Polyester?] Undated 40mmx140mm (1 photograph)	1997	BM05-RRB1
EST/1/1/5/61	Photographic negatives of poor estate showing photographs 31-55 [Polyester?] Undated 40mmx140mm (1 photograph)	1997	BM05-RRB1
EST/1/1/5/62	Photograph of poor estate exterior roof taken from above 21 November 1997 100mmx150mm (1 photograph)	1997	BM05-RRB1
EST/1/1/5/63	Photograph of poor estate showing the side exterior of the old John Pounds Centre 21 November 1997 100mmx150mm (1 photograph)	1997	BM05-RRB1
EST/1/1/5/64	Photograph of poor estate showing exterior of lockup garages on corner of St George's Way and Portland Street 21 November 1997 100mmx150mm (1 photograph)	1997	BM05-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/5/65	<p>Photograph of poor estate showing the exterior of the old John Pounds Centre [the section of the site including a library]</p> <p>21 November 1997</p> <p>100mmx150mm</p> <p>(1 photograph)</p>	1997	BM05-RRB1
EST/1/1/5/66	<p>Photograph of poor estate showing an aerial view of the exterior roof of a building - St Georges Way?</p> <p>21 November 1997</p> <p>100mmx150mm</p> <p>(1 photograph)</p>	1997	BM05-RRB1
EST/1/1/5/67	<p>Photograph of poor estate showing front exterior of Collingwood building at Milton</p> <p>Undated</p> <p>100mmx150mm</p> <p>(1 photograph)</p>	1997	BM05-RRB1
EST/1/1/5/68	<p>Photograph taken from a vehicle whilst driving through Portsmouth showing a double rainbow</p> <p>21 November 1997</p> <p>100mmx150mm</p> <p>(1 photograph)</p>	1997	BM05-RRB1
EST/1/1/5/69	<p>Photograph of poor estate showing a view from Eldon Building looking towards area behind building including Middle Street</p> <p>21 November 1997</p> <p>100mmx150mm</p> <p>(1 photograph)</p>	1997	BM05-RRB1
EST/1/1/5/70	<p>Photograph of poor estate showing exterior of an unidentified brick building at Milton?</p> <p>21 November 1997</p> <p>100mmx150mm</p> <p>(1 photograph)</p>	1997	BM05-RRB1
EST/1/1/5/71	<p>Photograph of poor estate showing exterior of Eldon Building – damage around mosaic pillar and walls</p> <p>21 November 1997</p> <p>100mmx150mm</p> <p>(1 photograph)</p>	1997	BM05-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/5/72	Photograph of poor estate showing exterior of a hut 21 November 1997 100mmx150mm (1 photograph)	1997	BM05-RRB1
EST/1/1/5/73	Photograph of poor estate showing the exterior of an unidentified brick building 21 November 1997 100mmx150mm (1 photograph)	1997	BM05-RRB1
EST/1/1/5/74	Photograph of poor estate showing exterior of a building at Milton Campus with a sign reading 'Nelson 11' on window 21 November 1997 100mmx150mm (1 photograph)	1997	BM05-RRB1
EST/1/1/5/75	Photograph of poor estate showing a screwdriver embedded in a wooden wall? 20 November 1997 100mmx150mm (1 photograph)	1997	BM05-RRB1
EST/1/1/5/76	Photograph of poor estate showing showing a mural on the wall of huts 20 November 1997 100mmx150mm (1 photograph)	1997	BM05-RRB1
EST/1/1/5/77	Photograph of poor estate showing exterior front of a hut? with damage to door frame 20 November 1997 100mmx150mm (1 photograph)	1997	BM05-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/5/78	Photograph of poor estate showing a window in close up 20 November 1997 100mmx150mm (1 photograph)	1997	BM05-RRB1
EST/1/1/5/79	Photograph of poor estate showing a green garage door with peeling paint 20 November 1997 100mmx150mm (1 photograph)	1997	BM05-RRB1
EST/1/1/5/80	Photograph of poor estate showing a green doorway with peeling paint and the shadow of the photographer 20 November 1997 100mmx150mm (1 photograph)	1997	BM05-RRB1
EST/1/1/5/81	Photograph of poor estate showing the top of garage doors with peeling green paint 20 November 1997 100mmx150mm (1 photograph)	1997	BM05-RRB1
EST/1/1/5/82	Photograph of poor estate showing a screwdriver embedded in a window frame 20 November 1997 100mmx150mm (1 photograph)	1997	BM05-RRB1
EST/1/1/5/83	Photograph of poor estate showing the bottom of blue double doors at the old John Pounds Centre 20 November 1997 100mmx150mm (1 photograph)	1997	BM05-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/5/84	Photograph of poor estate showing the exterior of the old John Pounds Centre in close up 20 November 1997 100mmx150mm (1 photograph)	1997	BM05-RRB1
EST/1/1/5/85	Photograph of poor estate showing a drainage hole in a wall with peeling paint [old John Pounds Centre?] 20 November 1997 100mmx150mm (1 photograph)	1997	BM05-RRB1
EST/1/1/5/86	Photograph of poor estate showing the exterior of the old John Pounds Centre in close-up with a street sign for 'The Portsea Venture' 20 November 1997 100mmx150mm (1 photograph)	1997	BM05-RRB1
EST/1/1/5/87	Photograph of poor estate showing the exterior of the Old John Pounds Centre - close-up of a window 20 November 1997 100mmx150mm (1 photograph)	1997	BM05-RRB1
EST/1/1/5/88	Photograph of poor estate showing a roof in close-up with rotting wood [old John Pounds Centre?] 20 November 1997 100mmx150mm (1 photograph)	1997	BM05-RRB1
EST/1/1/5/89	Photograph of poor estate showing the exterior of the Old John Pounds Centre - close-up of a window 20 November 1997 100mmx150mm (1 photograph)	1997	BM05-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/5/90	Photographic negatives of poor estate showing photographs 62-86 [Polyester?] Undated 100mmx150mm (1 photograph)	1997	BM05-RRB1
EST/1/1/5/91	Photograph of poor estate showing Front exterior of Eldon Building 20 November 1997 100mmx150mm (1 photograph)	1997	BM05-RRB1
EST/1/1/5/92	Photographic negatives of poor estate showing photographs of exteriors of buildings [Polyester?] Undated 100mmx150mm (1 photograph)	1997	BM05-RRB1
EST/1/1/5/93	Photographic negatives of poor estate showing photographs of exteriors of buildings [Polyester?] Undated 100mmx150mm (1 photograph)	1997	BM05-RRB1
EST/1/1/5/94	Photograph of poor estate taken from above [from future site of Richmond Building] looking towards Milldam 21 November 1997 100mmx150mm (1 photograph)	1997	BM05-RRB1
EST/1/1/5/95	Photograph of poor estate taken from above [from future site of Richmond Building] looking North West 21 November 1997 100mmx150mm (1 photograph)	1997	BM05-RRB1
EST/1/1/5/96	Photograph of poor estate showing an interior window frame in closeup Undated 100mmx150mm (1 photograph)	1990s	BM05-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/5/97	Photograph of poor estate taken from above [from future site of Richmond Building] looking North West 21 November 1997 100mmx150mm (1 photograph)	1997	BM05-RRB1
EST/1/1/5/98	Photograph of poor estate taken from above [from future site of Richmond Building] looking towards Milldam 21 November 1997 100mmx150mm (1 photograph)	1997	BM05-RRB1
EST/1/1/5/99	Photograph of poor estate showing side exterior of a building 21 November 1997 100mmx150mm (1 photograph)	1997	BM05-RRB1
EST/1/1/5/100	Photograph of poor estate showing side exterior of a building 21 November 1997 100mmx150mm (1 photograph)	1997	BM05-RRB1
EST/1/1/5/101	Photograph of poor estate showing a blurred image of view of Lion Terrace from a window including Burnaby Building and Argonaut sculpture 21 November 1997 100mmx150mm (1 photograph)	1997	BM05-RRB1
EST/1/1/5/102	Photograph of poor estate showing the side of a hut with sign 'GO28' 21 November 1997 100mmx150mm (1 photograph)	1997	BM05-RRB1
EST/1/1/5/103	Photograph of poor estate showing side exterior of a hut with sign 'GO31' 21 November 1997 100mmx150mm (1 photograph)	1997	BM05-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/5/104	Photograph of poor estate showing an alley between a hut and a shed 21 November 1997 100mmx150mm (1 photograph)	1997	BM05-RRB1
EST/1/1/5/105	Photograph of poor estate showing the rear exterior of a building with metal fenced off area- image taken from road 21 November 1997 100mmx150mm (1 photograph)	1997	BM05-RRB1
EST/1/1/5/106	Photograph of poor estate view taken from a window showing huts and car park [Anglesea?] 21 November 1997 100mmx150mm (1 photograph)	1997	BM05-RRB1
EST/1/1/5/107	Photograph of poor estate showing the roof of an unidentified building 21 November 1997 100mmx150mm (1 photograph)	1997	BM05-RRB1
EST/1/1/5/108	Photograph of poor estate showing a blurred image of huts taken from a window [Anglesea?] 21 November 1997 100mmx150mm (1 photograph)	1997	BM05-RRB1
EST/1/1/5/109	Photograph of poor estate showing the exterior of an unidentified building with a person walking past 21 November 1997 100mmx150mm (1 photograph)	1997	BM05-RRB1
EST/1/1/5/110	Photograph of poor estate showing view taken from window of a roof [Anglesea?] 21 November 1997 100mmx150mm (1 photograph)	1997	BM05-RRB1

Reference	Description	Date	Shelf Mark
<i>Environment: Compost Heap</i>			
EST/1/1/5/111	Photograph of a woodchipper at Langstone campus Undated 150mmx200mm (1 photograph)	1990s	BM05-RRB1
EST/1/1/5/112	Photograph of a woodchipper at Langstone campus Undated 150mmx200mm (1 photograph)	1990s	BM05-RRB1
EST/1/1/5/113	Photograph of a woodchipper at Langstone campus Undated 150mmx200mm (1 photograph)	1990s	BM05-RRB1
EST/1/1/5/114	Photograph of a woodchipper at Langstone campus Undated 150mmx200mm (1 photograph)	1990s	BM05-RRB1
EST/1/1/5/115	Photograph of a woodchipper next to a yellow digger at Langstone campus Undated 150mmx200mm (1 photograph)	1990s	BM05-RRB1
EST/1/1/5/116	Photograph of a woodchipper next to a yellow digger at Langstone campus Undated 150mmx200mm (1 photograph)	1990s	BM05-RRB1
EST/1/1/5/117	Photograph of the back of a woodchipper at Langstone campus Undated 150mmx200mm (1 photograph)	1990s	BM05-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/5/118	Photograph of the back of a woodchipper at Langstone campus Undated 150mmx200mm (1 photograph)	1990s	BM05-RRB1
EST/1/1/5/119	Photograph of a yellow digger loading wood into a green container at Langstone campus Undated 150mmx200mm (1 photograph)	1990s	BM05-RRB1
EST/1/1/5/120	Photograph of the back of a woodchipper at Langstone campus Undated 150mmx200mm (1 photograph)	1990s	BM05-RRB1
EST/1/1/5/121	Photograph of a digger loading wood into a woodchipper at Langstone campus Undated 150mmx200mm (1 photograph)	1990s	BM05-RRB1
EST/1/1/5/122	Photograph of a digger loading wood into a woodchipper at Langstone campus Undated 150mmx200mm (1 photograph)	1990s	BM05-RRB1
EST/1/1/5/123	Photograph of the back of a woodchipper at Langstone campus Undated 150mmx200mm (1 photograph)	1990s	BM05-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/5/124	Photograph of the back of a woodchipper at Langstone campus Undated 150mmx200mm (1 photograph)	1990s	BM05-RRB1
EST/1/1/5/125	Photograph of the back of a woodchipper at Langstone campus Undated 150mmx200mm (1 photograph)	1990s	BM05-RRB1
EST/1/1/5/126	Photograph of the back of a woodchipper at Langstone campus Undated 150mmx200mm (1 photograph)	1990s	BM05-RRB1
EST/1/1/5/127	Photograph of a pile of wooden branches at Langstone campus Undated 150mmx200mm (1 photograph)	1990s	BM05-RRB1
EST/1/1/5/128	Photograph of a digger loading wood into a woodchipper Undated 150mmx200mm (1 photograph)	1990s	BM05-RRB1
EST/1/1/5/129	Photograph of a digger collecting wood at Langstone campus Undated 150mmx200mm (1 photograph)	1990s	BM05-RRB1
EST/1/1/5/130	Photograph of piles of wood amongst trees at Langstone campus Undated 150mmx200mm (1 photograph)	1990s	BM05-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/5/131	Photograph of a woodchipper at Langstone campus Undated 150mmx200mm (1 photograph)	1990s	BM05-RRB1
EST/1/1/5/132	Photograph of a woodchipper at Langstone campus Undated 150mmx200mm (1 photograph)	1990s	BM05-RRB1
EST/1/1/5/133	Photograph of the back of a woodchipper at Langstone campus Undated 150mmx200mm (1 photograph)	1990s	BM05-RRB1
EST/1/1/5/134	Photograph of the back of a woodchipper at Langstone campus Undated 150mmx200mm (1 photograph)	1990s	BM05-RRB1
EST/1/1/5/135	Photograph of the back of a woodchipper at Langstone campus Undated 150mmx200mm (1 photograph)	1990s	BM05-RRB1
EST/1/1/5/136	Photograph of the back of a woodchipper at Langstone campus Undated 150mmx200mm (1 photograph)	1990s	BM05-RRB1
EST/1/1/5/137	Photograph of the back of a woodchipper at Langstone campus Undated 150mmx200mm (1 photograph)	1990s	BM05-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/5/138	Photograph of the back of a woodchipper at Langstone campus Undated 150mmx200mm (1 photograph)	1990s	BM05-RRB1
EST/1/1/5/139	Photograph of the back of a woodchipper at Langstone campus Undated 150mmx200mm (1 photograph)	1990s	BM05-RRB1
EST/1/1/5/140	Photograph of a woodchipper at Langstone campus Undated 150mmx200mm (1 photograph)	1990s	BM05-RRB1
EST/1/1/5/141	Photograph of a pile of wooden branches at Langstone campus Undated 150mmx200mm (1 photograph)	1990s	BM05-RRB1
EST/1/1/5/142	Photograph of a pile of wooden branches at Langstone campus Undated 150mmx200mm (1 photograph)	1990s	BM05-RRB1
EST/1/1/5/143	Photograph of a pile of wooden branches at Langstone campus Undated 150mmx200mm (1 photograph)	1990s	BM05-RRB1
EST/1/1/5/144	Photograph of a pile of wooden branches at Langstone campus Undated 150mmx200mm (1 photograph)	1990s	BM05-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/5/145	Photograph of a woodchipper at Langstone campus Undated 150mmx200mm (1 photograph)	1990s	BM05-RRB1
EST/1/1/5/146	Photograph of a woodchipper at Langstone campus Undated 150mmx200mm (1 photograph)	1990s	BM05-RRB1
EST/1/1/5/147	Photograph of a digger placing wood in a woodchipper at Langstone campus Undated 150mmx200mm (1 photograph)	1990s	BM05-RRB1
<i>Environment: Ravelin Park</i>			
EST/1/1/5/148	Photograph of Ravelin House garden – view of fence and Museum Road visible behind 18 June 1998 100mmx150mm (1 photograph)	1998	BM06-RRB1
EST/1/1/5/149	Photograph of Ravelin House garden with Museum Road visible through trees 18 June 1998 100mmx150mm (1 photograph)	1998	BM06-RRB1
EST/1/1/5/150	Photograph of Ravelin House garden with Kings Road junction visible through trees 18 June 1998 100mmx150mm (1 photograph)	1998	BM06-RRB1
EST/1/1/5/151	Photograph of exterior of Ravelin House - view from garden 18 June 1998 100mmx150mm (1 photograph)	1998	BM06-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/5/152	Photograph of Ravelin House garden – view of fence and Museum Road visible behind Undated 100mmx150mm (1 photograph)	1990s	BM06-RRB1
EST/1/1/5/153	Photograph of Ravelin House garden with Kings Road junction visible through trees 18 June 1998 100mmx150mm (1 photograph)	1998	BM06-RRB1
EST/1/1/5/154	Photograph of a pathway in Ravelin House garden with Museum Road visible through trees in background 18 June 1998 100mmx150mm (1 photograph)	1998	BM06-RRB1
EST/1/1/5/155	Photograph of a wooden bench in Ravelin House garden 18 June 1998 100mmx150mm (1 photograph)	1998	BM06-RRB1
EST/1/1/5/156	Photograph of exterior of Ravelin House - view from far end of garden Undated 130mmx200mm (1 photograph)	1990s	BM06-RRB1
EST/1/1/5/157	Photograph of exterior of Ravelin House - view from far end of garden Undated 130mmx200mm (1 photograph)	1990s	BM06-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/5/158	Photograph of Ravelin House with a large tree in the foreground - view from far end of garden Undated 130mmx200mm (1 photograph)	1990s	BM06-RRB1
EST/1/1/5/159	Photograph of a pathway in Ravelin Park with three people walking in the distance walking away from the camera Undated 130mmx200mm (1 photograph)	1990s	BM06-RRB1
EST/1/1/5/160	Photograph of a pathway in Ravelin Park with three people walking towards the camera with Museum Road just visible through the trees Undated 130mmx200mm (1 photograph)	1990s	BM06-RRB1
EST/1/1/5/161	Photograph of a pathway in Ravelin Park with two people in the distance and University Library just visible in background Undated 130mmx200mm (1 photograph)	1990s	BM06-RRB1
EST/1/1/5/162	Photograph of a pathway in Ravelin Park with three people walking along it and University Library just visible in background Undated 130mmx200mm (1 photograph)	1990s	BM06-RRB1
EST/1/1/5/163	Photograph of Ravelin House garden - view towards fence into Museum Road Undated 130mmx200mm (1 photograph)	1990s	BM06-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/5/164	Photograph of Ravelin Park wooded area with Ravelin House just visible in the background Undated 130mmx200mm (1 photograph)	1990s	BM06-RRB1
EST/1/1/5/165	Photograph of Ravelin Park wooded area with Ravelin House just visible in the background Undated 130mmx200mm (1 photograph)	1990s	BM06-RRB1
EST/1/1/5/166	Photograph of a pathway in Ravelin Park with three people walking towards the camera and Museum Road just visible in background through trees Undated 130mmx200mm (1 photograph)	1990s	BM06-RRB1
EST/1/1/5/167	Photograph of a pathway in Ravelin Park with one person walking towards the camera and Museum Road just visible in the background through trees Undated 130mmx200mm (1 photograph)	1990s	BM06-RRB1
EST/1/1/5/168	Photograph of a pathway in Ravelin Park with two people walking on the pathway and Museum Road just visible in the background through trees Undated 130mmx200mm (1 photograph)	1990s	BM06-RRB1
EST/1/1/5/169	Photograph of a pathway in Ravelin Park - view towards University Library just visible through trees Undated 130mmx200mm (1 photograph)	1990s	BM06-RRB1
EST/1/1/5/170	Photograph of a pathway in Ravelin Park with one person walking away from the camera and Museum Road just visible in the background through trees Undated 130mmx200mm (1 photograph)	1990s	BM06-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/5/171	<p>Photograph of Ravelin Park with one person walking towards a log pile with Landport Terrace just visible in background</p> <p>Undated</p> <p>130mmx200mm</p> <p>(1 photograph)</p>	1990s	BM06-RRB1
EST/1/1/5/172	<p>Photograph of exterior of Ravelin House - view from far end of the garden with a person mowing the lawn</p> <p>Undated</p> <p>130mmx200mm</p> <p>(1 photograph)</p>	1990s	BM06-RRB1
EST/1/1/5/173	<p>Photograph of Ravelin Park wooded area with Ravelin House just visible in the background</p> <p>Undated</p> <p>130mmx200mm</p> <p>(1 photograph)</p>	1990s	BM06-RRB1
EST/1/1/5/174	<p>Photograph of a tractor attached to a turf conditioner on the sports fields at Langstone Campus</p> <p>Undated</p> <p>130mmx180mm</p> <p>(1 photograph)</p>	1990s	BM06-RRB1
EST/1/1/5/175	<p>Photograph of a tractor attached to a turf conditioner on the sports fields at Langstone Campus</p> <p>Undated</p> <p>130mmx180mm</p> <p>(1 photograph)</p>	1990s	BM06-RRB1
EST/1/1/5/176	<p>Photograph of a tractor attached to a turf conditioner on the sports fields at Langstone Campus</p> <p>Undated</p> <p>130mmx180mm</p> <p>(1 photograph)</p>	1990s	BM06-RRB1
EST/1/1/5/177	<p>Photograph of a tractor attached to a turf conditioner on the sports fields at Langstone Campus</p> <p>Undated</p> <p>130mmx180mm</p> <p>(1 photograph)</p>	1990s	BM06-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/5/178	Photograph of a tractor attached to a turf conditioner on the sports fields at Langstone Campus Undated 130mmx180mm (1 photograph)	1990s	BM06-RRB1
EST/1/1/5/179	Photograph of a tractor attached to a turf conditioner on the sports fields at Langstone Campus Undated 130mmx180mm (1 photograph)	1990s	BM06-RRB1
EST/1/1/5/180	Photograph of a tractor attached to a turf conditioner on the sports fields at Langstone Campus Undated 130mmx180mm (1 photograph)	1990s	BM06-RRB1
EST/1/1/5/181	Photograph of a tractor attached to a turf conditioner on the sports fields at Langstone Campus Undated 130mmx180mm (1 photograph)	1990s	BM06-RRB1
EST/1/1/5/182	Photograph of a tractor attached to a turf conditioner on the sports fields at Langstone Campus Undated 130mmx180mm (1 photograph)	1990s	BM06-RRB1
EST/1/1/5/183	Photograph of Langstone Student Village with a tractor attached to a turf conditioner with a man sat in the tractor opening the window Undated 130mmx180mm (1 photograph)	1990s	BM06-RRB1
EST/1/1/5/184	Photograph of a tractor attached to a turf conditioner on the sports fields at Langstone Campus Undated 130mmx180mm (1 photograph)	1990s	BM06-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/5/185	Photograph of a tractor attached to a turf conditioner on the sports fields at Langstone Campus Undated 130mmx180mm (1 photograph)	1990s	BM06-RRB1
EST/1/1/5/186	Photograph of a tractor attached to a turf conditioner on the sports fields at Langstone Campus Undated 130mmx180mm (1 photograph)	1990s	BM06-RRB1
EST/1/1/5/187	Photograph of Langstone Student Village with a tractor attached to a turf conditioner with a man sat in the tractor and a yellow vehicle on the right of the photograph Undated 130mmx180mm (1 photograph)	1990s	BM06-RRB1
EST/1/1/5/188	Photograph of a tractor attached to a turf conditioner on the sports fields at Langstone Campus Undated 130mmx180mm (1 photograph)	1990s	BM06-RRB1
EST/1/1/5/189	Photograph of a tractor attached to a turf conditioner on the sports fields at Langstone Campus Undated 130mmx180mm (1 photograph)	1990s	BM06-RRB1
EST/1/1/5/190	Photograph of a tractor attached to a turf conditioner on the sports fields at Langstone Campus Undated 130mmx180mm (1 photograph)	1990s	BM06-RRB1
EST/1/1/5/191	Photograph of a tractor attached to a turf conditioner on the sports fields at Langstone Campus Undated 130mmx180mm (1 photograph)	1990s	BM06-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/5/192	Photograph of a tractor attached to a turf conditioner on the sports fields at Langstone Campus Undated 130mmx180mm (1 photograph)	1990s	BM06-RRB1
EST/1/1/5/193	Photograph of a man looking at a turf conditioner attached to a tractor at Langstone campus Undated 130mmx180mm (1 photograph)	1990s	BM06-RRB1
EST/1/1/5/194	Photograph of a tractor attached to a turf conditioner on the sports fields at Langstone Campus Undated 170mmx210mm (1 photograph)	1990s	BM06-RRB1
EST/1/1/5/195	Photograph of a University of Portsmouth bus at Cambridge Road bus stop with passengers sat inside Undated 150mmx180mm (1 photograph)	[2000]	BM06-RRB1
EST/1/1/5/196	Photograph of rear exterior of Eldon Building from courtyard area [stray?] Undated 150mmx180mm (1 photograph)	1990s	BM06-RRB1
EST/1/1/5/197	Photograph of the front of a University of Portsmouth bus at a bus stop in Cambridge Road Undated 150mmx180mm (1 photograph)	[2000]	BM06-RRB1
EST/1/1/5/198	Photograph of the side of a University of Portsmouth bus Undated 150mmx180mm (1 photograph)	[2000]	BM06-RRB1

Reference	Description	Date	Shelf Mark
EST/1/1/5/199	Photograph of a bus driver sat behind the wheel of the University of Portsmouth bus Undated 150mmx180mm (1 photograph)	[2000]	BM06-RRB1
EST/1/1/5/200	Photograph of the rear of a University of Portsmouth bus showing an advert for open days Undated 150mmx180mm (1 photograph)	[2000]	BM06-RRB1

Reference	Description	Date	Shelf Mark
EST/1/2	Series of photographic prints Sets of photographs found grouped together in boxes or envelopes within a larger box. These were originally untitled and titles have been created by the archivist.	1970-2000	
EST/1/2/1	King Henry Building under construction	1970-1971	
EST/1/2/1/1	Photograph of the King Henry Building site before construction, view across Anglesea Road looking down Park Road with Anglesea Building visible on right and power station on left with manuscript annotation on reverse 'Site pre-closure Feb 1970'. February 1970 B/W 170mmx240mm (1 photograph)	1970	BM06-RRB1
EST/1/2/1/2	Photograph of the King Henry Building site before construction, view across Anglesea Road looking down Park Road with Anglesea Building visible on right and power station on left undated [February 1970] B/W 160mmx210mm (1 photograph)	1970	BM06-RRB1
EST/1/2/1/3	Photograph of the King Henry Building construction site with one man walking in the road and two trees in the centre of the photograph view across Anglesea Road looking down Park Road with Anglesea Building visible on right and power station on left Undated [April 1970?] B/W 170mmx250mm (1 photograph)	1970	BM06-RRB1
EST/1/2/1/4	Photograph of the King Henry Building construction site and a black [crane?] with one builder stood next to it and Park Building in the background includes manuscript annotation on reverse 'April 1 st ' 1 st April [1970] B/W 180mmx250mm (1 photograph)	1970	BM06-RRB1

Reference	Description	Date	Shelf Mark
EST/1/2/1/5	<p>Photograph of the King Henry Building construction site with stacks of bricks and a cement mixer on the bottom right of the photograph</p> <p>view across Anglesea Road looking down Park Road with power station visible on left includes manuscript annotation on reverse 'Form work to Pile Capo and ground Beams'</p> <p>5th June [1970]</p> <p>B/W 180mmx250mm</p> <p>(1 photograph)</p>	1970	BM06-RRB1
EST/1/2/1/6	<p>Photograph of King Henry Building construction site view across Anglesea Road looking down Park Road includes manuscript annotation on reverse 'July 26th 1970 Installing Ground Floor Window Panels'</p> <p>26 July 1970</p> <p>Cropped version of EST/1/2/1/7</p> <p>B/W 150mmx220mm</p> <p>(1 photograph)</p>	1970	BM06-RRB1
EST/1/2/1/7	<p>Photograph of the King Henry Building construction site with a sign at the bottom of the image reading 'Carruthers, Davies and Company Limited'</p> <p>view across Anglesea Road looking down Park Road uncropped version of EST/1/2/6</p> <p>Undated [26 July 1970]</p> <p>B/W 150mmx240mm</p> <p>(1 photograph)</p>	1970	BM06-RRB1
EST/1/2/1/8	<p>Photograph of King Henry construction site view across Anglesea Road looking down Park Road with power station visible on left, manuscript annotation on reverse 'Aug 12th'</p> <p>12 August [1970]</p> <p>B/W 200mmx250mm</p> <p>(1 photograph)</p>	1970	BM06-RRB1
EST/1/2/1/9	<p>Photograph of King Henry construction site view across Anglesea Road looking down Park Road with power station visible on left and a sign at the bottom of the image reading 'Carruthers, Davies and Company Limited'</p> <p>Undated [August 1970]</p> <p>B/W 200mmx250mm</p> <p>(1 photograph)</p>	1970	BM06-RRB1

Reference	Description	Date	Shelf Mark
EST/1/2/1/10	<p>Photograph of King Henry Building under construction lower floors only view across Anglesea Road looking down Park Road with power station visible on left includes manuscript annotation on reverse 'Aug 21st' 21 August [1970] B/W 200mmx250mm (1 photograph)</p>	1970	BM06-RRB1
EST/1/2/1/11	<p>Photograph of King Henry Building under construction includes manuscript annotation on reverse '9/ 2/3 floor section' 28 August 1970 B/W 200mmx250mm (1 photograph)</p>	1970	BM06-RRB1
EST/1/2/1/12	<p>Photograph of King Henry Building under construction lower floors includes manuscript annotation on reverse 'Sept. 1st' 1 September [1970] B/W 200mmx250mm (1 photograph)</p>	1970	BM06-RRB1
EST/1/2/1/13	<p>Photograph of exterior of King Henry Building under construction includes manuscript annotation on reverse '10-9-70 3rd Floor' 10 September 1970 B/W 200mmx250mm (1 photograph)</p>	1970	BM06-RRB1
EST/1/2/1/14	<p>Photograph of exterior of King Henry Building under construction includes manuscript annotation on reverse '23/9/70' 23 September 1970 B/W 200mmx250mm (1 photograph)</p>	1970	BM06-RRB1
EST/1/2/1/15	<p>Photograph of exterior of King Henry Building under construction including crane lifting a beam? into place includes manuscript annotation on reverse '29th Sept 5th Floor' 29 September [1970] B/W 200mmx250mm (1 photograph)</p>	1970	BM06-RRB1

Reference	Description	Date	Shelf Mark
EST/1/2/1/16	Photograph of exterior of King Henry Building under construction includes manuscript annotation on reverse '8 th Oct 1970' 8 October 1970 B/W 200mmx250mm (1 photograph)	1970	BM06-RRB1
EST/1/2/1/17	Photograph of exterior of King Henry Building under construction includes manuscript annotation on reverse '16/10/70 6 th Floor' 16 October 1970 B/W 200mmx250mm (1 photograph)	1970	BM06-RRB1
EST/1/2/1/18	Photograph of exterior of King Henry Building under construction includes manuscript annotation on reverse '23 rd November 1970 3 ton 'planks'' 23 November 1970 B/W 200mmx250mm (1 photograph)	1970	BM06-RRB1
EST/1/2/1/19	Photograph of exterior of King Henry Building under construction includes manuscript annotation on reverse '23 rd November 1970 3 ton 'planks'' 23 November 1970 B/W 200mmx250mm (1 photograph)	1970	BM06-RRB1
EST/1/2/1/20	Photograph of exterior of King Henry Building mid-construction includes manuscript annotation on reverse '16/12/70' 16 December 1970 B/W 200mmx250mm (1 photograph)	1970	BM06-RRB1
EST/1/2/1/21	Photograph of exterior of King Henry Building under construction includes manuscript annotation on reverse '18 th January 1971' 18 January 1971 B/W 200mmx250mm (1 photograph)	1971	BM06-RRB1

Reference	Description	Date	Shelf Mark
EST/1/2/1/22	<p>Photograph of exterior of King Henry Building under construction side view with scaffolding on the right includes manuscript annotation on reverse '5th March 1971'</p> <p>5 March 1971</p> <p>B/W 200mmx250mm</p> <p>(1 photograph)</p>	1971	BM06-RRB1
EST/1/2/1/23	<p>Photograph of exterior of King Henry Building under Construction, side view with scaffolding on the right includes manuscript annotation on reverse '5th March 1971'</p> <p>5 March 1971</p> <p>B/W 200mmx250mm</p> <p>(1 photograph)</p>	1971	BM06-RRB1
EST/1/2/1/24	<p>Photograph of exterior of King Henry Building under construction, side view with scaffolding on the right, image taken from across Anglesea Road includes manuscript annotation on reverse '5th March 1971'</p> <p>5 March 1971</p> <p>B/W 200mmx250mm</p> <p>(1 photograph)</p>	1971	BM06-RRB1
EST/1/2/1/25	<p>Photograph of exterior of King Henry Building under construction includes manuscript annotation on reverse '5th March 1971'</p> <p>5 March 1971</p> <p>B/W 200mmx250mm</p> <p>(1 photograph)</p>	1971	BM06-RRB1
EST/1/2/1/26	<p>Photograph of exterior of King Henry Building under construction includes manuscript annotation on reverse '5th March 1971'</p> <p>5 March 1971</p> <p>B/W 200mmx250mm</p> <p>(1 photograph)</p>	1971	BM06-RRB1

Reference	Description	Date	Shelf Mark
EST/1/2/2	<p>Portsmouth Building Society [later University House]</p> <p>All images include labels on reverse from Juniper Photographic Services</p>	1986	
EST/1/2/2/1	<p>Photograph of construction site of Portsmouth Building Society [later University House] with Park Building visible in the background</p> <p>13 January 1986</p> <p>Photographer: Juniper Photographic Services</p> <p>B/W 150mmx200mm</p> <p>(1 photograph)</p>	1986	BM06-RRB1
EST/1/2/2/2	<p>Photograph of Portsmouth Building Society building [later University House] under construction with Park Building visible in the background</p> <p>5 February 1986</p> <p>Photographer: Juniper Photographic Services</p> <p>B/W 150mmx200mm</p> <p>(1 photograph)</p>	1986	BM06-RRB1
EST/1/2/2/3	<p>Photograph of Portsmouth Building Society building [later University House] under construction, metal frame</p> <p>5 March 1986</p> <p>Photographer: Juniper Photographic Services</p> <p>B/W 150mmx200mm</p> <p>Some [water?] damage to lower right hand corner of image</p> <p>(1 photograph)</p>	1986	BM06-RRB1
EST/1/2/2/4	<p>Photograph of Portsmouth Building Society building [later University House] under construction, metal frame</p> <p>3 April 1986</p> <p>Photographer: Juniper Photographic Services</p> <p>B/W 150mmx200mm</p> <p>(1 photograph)</p>	1986	BM06-RRB1
EST/1/2/2/5	<p>Photograph of Portsmouth Building Society building under construction, metal frame covered with scaffolding</p> <p>5 May 1986</p> <p>Photographer: Juniper Photographic Services</p> <p>B/W 150mmx200mm</p> <p>(1 photograph)</p>	1986	BM06-RRB1

Reference	Description	Date	Shelf Mark
EST/1/2/3	Park Building Upper Hall	1999	
Enclosed with a note from Printing and Photographic Services re: 'contacts and prints of new lecture theatre Park Building' asking for someone to look over the photographs and send a requisition to cover cost			
EST/1/2/3/1	Contact sheet of various photographs of interior of empty Park Building lecture theatre [Upper Hall] and lecture theatre foyer area Undated 210mmx300mm (1 contact sheet)	[1999]	BM06-RRB1
EST/1/2/3/2	Contact sheet of various photographs of empty Park Building [Upper Hall] lecture theatre Undated 210mmx300mm (1 contact sheet)	[1999]	BM06-RRB1
EST/1/2/3/3	Contact sheet of various photographs of Park Building [Upper Hall] lecture theatre during a lecture Undated 210mmx300mm (1 contact sheet)	[1999]	BM06-RRB1
EST/1/2/3/4	Photograph of empty Park Building [Upper Hall] lecture theatre Image appears on contact sheet EST/1/2/3/1 Undated 160mmx210mm (1 photograph)	[1999]	BM06-RRB1
EST/1/2/3/5	Photograph of empty Park Building [Upper Hall] lecture theatre Image appears on contact sheet EST/1/2/3/2 Undated 160mmx210mm (1 photograph)	[1999]	BM06-RRB1

Reference	Description	Date	Shelf Mark
EST/1/2/3/6	<p>Photograph of empty Park Building [Upper Hall] lecture theatre – view from seating towards front, with a photograph of Park Building on the presentation screen Image appears on contact sheet EST/1/2/3/2 Undated 160mmx210mm (1 photograph)</p>	[1999]	BM06-RRB1
EST/1/2/3/7	<p>Photograph of empty Park Building [Upper Hall] lecture theatre – view from front towards seating Image appears on contact sheet EST/1/2/3/2 Undated 160mmx210mm (1 photograph)</p>	[1999]	BM06-RRB1
EST/1/2/3/8	<p>Photograph of Park Building [Upper Hall] lecture theatre foyer area Image appears on contact sheet EST/1/2/3/1 Undated 160mmx210mm (1 photograph)</p>	[1999]	BM06-RRB1
EST/1/2/3/9	<p>Photograph of Park Building [Upper Hall] lecture theatre, view from podium in foreground towards rows of seating Image appears on contact sheet EST/1/2/3/2 Undated 160mmx210mm (1 photograph)</p>	[1999]	BM06-RRB1
EST/1/2/3/10	<p>Photograph of Park Building [Upper Hall] lecture theatre during a lecture Image appears on contact sheet EST/1/2/3/3 Undated 160mmx210mm (1 photograph)</p>	[1999]	BM06-RRB1
EST/1/2/3/11	<p>Photograph of Park Building [Upper Hall] lecture theatre during a lecture Image appears on contact sheet EST/1/2/3/2 Undated 160mmx210mm (1 photograph)</p>	[1999]	BM06-RRB1

Reference	Description	Date	Shelf Mark
EST/1/2/4	Park Building galleon weathervane	1980s	
EST/1/2/4/1	<p>Photograph of the exterior of Park Building with a crane on the right lifting the galleon weathervane to the tallest part of the roof</p> <p>Undated</p> <p>180mmx270mm</p> <p>(2 copies of the photograph – one with damage to lower left corner)</p>	1980s	BM08-RR1
EST/1/2/4/2	<p>Photograph of the galleon weathervane being lifted out of the back of a vehicle by a crane surrounded by people [Polytechnic staff?] watching</p> <p>Undated</p> <p>180mmx270mm</p> <p>(1 photograph)</p>	1980s	BM08-RR1
EST/1/2/4/3	<p>Photograph of a close up side view of the galleon weathervane in situ on the roof of Park Building surrounded by scaffolding</p> <p>Undated</p> <p>B/W 180mmx270mm</p> <p>(1 photograph)</p>	1980s	BM08-RR1
EST/1/2/4/4	<p>Photograph of the galleon weathervane in situ on top of Park Building surrounded by wooden scaffolding</p> <p>Undated</p> <p>B/W 180mmx270mm</p> <p>(2 copies of the photograph)</p>	1980s	BM08-RR1
EST/1/2/4/5	<p>Photograph of a close up side view of the galleon Weathervane in situ on top of Park Building surrounded by wooden scaffolding</p> <p>Undated</p> <p>B/W 180mmx270mm</p> <p>(1 photograph)</p>	1980s	BM08-RR1
EST/1/2/4/6	<p>Photograph of the galleon weathervane in situ on top of Park Building on wooden scaffolding</p> <p>Undated</p> <p>B/W 180mmx270mm</p> <p>(1 photograph)</p>	1980s	BM08-RR1

Reference	Description	Date	Shelf Mark
EST/1/2/4/7	Photograph of the galleon weathervane in situ on top of Park Building surrounded by wooden scaffolding Undated B/W 180mmx270mm (1 photograph)	1980s	BM08-RR1
EST/1/2/4/8	Photograph of a close up side view of the galleon weathervane on Park Building focused on the rigging and sails Undated B/W 180mmx270mm (1 photograph)	1980s	BM08-RR1
EST/1/2/4/9	Photograph of the galleon weathervane in situ on top of Park Building surrounded by wooden scaffolding Undated B/W 180mmx270mm (1 photograph)	1980s	BM08-RR1
EST/1/2/5	Park Building stonework	1970s?	
EST/1/2/5/1	Set of 43 B/W photographs of various parts of stonework on Park Building with manuscript annotations in red pen identifying areas of damage Photographer: Stoneham Masonry Works Southampton (43 photographs)		BM10-RR1

Reference	Description	Date	Shelf Mark
EST/1/2/6	St Michael's Building and Buckingham Building	1980s	
<i>See also EST/1/4/26-27 for further images of St Michael's Building</i>			
Originally packaged with envelopes with notes on reading 'Unfinished Side: St. Michael's Building' and 'Possible Alternative Shots of Buckingham Building & Unfinished End of St. Michael's Building'.			
EST/1/2/6/1	Photograph of the side exterior of St. Michael's Building from corner of Anglesea Road and King Richard Road Undated B/W 170mmx210mm (2 copies of the photograph)	1980s	BM08-RR1
EST/1/2/6/2	Photograph of exterior side and rear of St. Michael's Building taken from the car park with four people walking through the car park Undated B/W 170mmx210mm (2 copies of the photograph)	1980s	BM08-RR1
EST/1/2/6/3	Photograph of exterior side and rear of St. Michael's Building taken from the car park Undated B/W 170mmx210mm (2 copies of the photograph)	1980s	BM08-RR1
EST/1/2/6/4	Photograph of exterior of Buckingham Building taken from the car park with cars parked in foreground Undated B/W 170mmx210mm (2 copies of the photograph)	1980s	BM08-RR1
EST/1/2/6/5	Photograph of exterior of Buckingham Building taken from the car park with cars parked in foreground Undated B/W 170mmx210mm (2 copies of the photograph)	1980s	BM08-RR1
EST/1/2/6/6	Photograph of exterior of Buckingham Building taken from the car park with cars parked in foreground Undated B/W 170mmx210mm (2 copies of the photograph)	1980s	BM08-RR1

Reference	Description	Date	Shelf Mark
EST/1/2/6/7	<p>Photograph of exterior of Buckingham Building taken from the car park with cars parked in foreground Undated B/W 170mmx210mm (2 copies of the photograph)</p>	1980s	BM08-RAA1
EST/1/2/7	<p>St Michael's Building extension <i>See also EST/1/1/4/74-83 and EST/1/4/26-27 for further images</i></p> <p>Marked 'The White Swan Development'</p>	1996	
EST/1/2/7/1	<p>Photograph of a corridor in St Michael's Building extension Col 127mm x 176mm 25 April 1996 Photographer: Wimpey Construction UK Ltd? (1 photograph)</p>	1996	BM09-RAA1
EST/1/2/7/2	<p>Photograph of a lecture theatre in St Michael's Building extension Col 127mm x 176mm 25 April 1996 Photographer: Wimpey Construction UK Ltd? (1 photograph)</p>	1996	BM09-RAA1
EST/1/2/7/3	<p>Photograph of a staircase in St Michael's Building extension Col 127mm x 176mm 25 April 1996 Photographer: Wimpey Construction UK Ltd? (1 photograph)</p>	1996	BM09-RAA1
EST/1/2/7/4	<p>Photograph of a lecture theatre in St Michael's Building extension Col 127mm x 176mm 25 April 1996 Photographer: Wimpey Construction UK Ltd? (1 photograph)</p>	1996	BM09-RAA1
EST/1/2/7/5	<p>Photograph of a laboratory in St Michael's Building extension Col 127mm x 176mm 25 April 1996 Photographer: Wimpey Construction UK Ltd? (1 photograph)</p>	1996	BM09-RAA1

Reference	Description	Date	Shelf Mark
EST/1/2/7/6	<p>Photograph of a stairwell in St Michael's Building extension</p> <p>Col 127mm x 176mm</p> <p>25 April 1996</p> <p>Photographer: Wimpey Construction UK Ltd?</p> <p>(1 photograph)</p>	1996	BM09-RRA1
EST/1/2/7/7	<p>Photograph of a laboratory in St Michael's Building extension</p> <p>Col 127mm x 176mm</p> <p>25 April 1996</p> <p>Photographer: Wimpey Construction UK Ltd?</p> <p>(1 photograph)</p>	1996	BM09-RRA1
EST/1/2/7/8	<p>Photograph of a laboratory in St Michael's Building extension</p> <p>Col 127mm x 176mm</p> <p>25 April 1996</p> <p>Photographer: Wimpey Construction UK Ltd?</p> <p>(1 photograph)</p>	1996	BM09-RRA1
EST/1/2/7/9	<p>Photograph of a laboratory in St Michael's Building extension</p> <p>Col 127mm x 176mm</p> <p>25 April 1996</p> <p>Photographer: Wimpey Construction UK Ltd?</p> <p>(1 photograph)</p>	1996	BM09-RRA1
EST/1/2/7/10	<p>Photograph of the interior of the plant room in St Michael's Building extension</p> <p>Col 127mm x 176mm</p> <p>25 April 1996</p> <p>Photographer: Wimpey Construction UK Ltd?</p> <p>(1 photograph)</p>	1996	BM09-RRA1
EST/1/2/7/11	<p>Photograph of the rear exterior of St Michael's Building extension from the crossing at King Richard I Road</p> <p>Col 127mm x 176mm</p> <p>25 April 1996</p> <p>Photographer: Wimpey Construction UK Ltd?</p> <p>(1 photograph)</p>	1996	BM09-RRA1

Reference	Description	Date	Shelf Mark
EST/1/2/7/12	Photograph of the rear exterior of St Michael's Building extension from St Andrews Court? Col 127mm x 176mm 25 April 1996 Photographer: Wimpey Construction UK Ltd? (1 photograph)	1996	BM09-RRA1
EST/1/2/7/13	Photograph of the front exterior of St Michael's Building extension from St Michael's Road Col 127mm x 176mm 25 April 1996 Photographer: Wimpey Construction UK Ltd? (1 photograph)	1996	BM09-RRA1
EST/1/2/7/14	Photograph of the rear exterior of St Michael's Building extension Col 127mm x 176mm 25 April 1996 Photographer: Wimpey Construction UK Ltd? (1 photograph)	1996	BM09-RRA1
EST/1/2/7/15	Photograph of the front exterior of St Michael's Building extension from St Michael's Road Col 127mm x 176mm 25 April 1996 Photographer: Wimpey Construction UK Ltd? (1 photograph)	1996	BM09-RRA1
EST/1/2/7/16	Photograph of front exterior of St Michael's Building extension from St Michael's Road Col 127mm x 176mm (1 photograph)	[1996]	BM09-RRA1
EST/1/2/7/17	Photograph of rear exterior of St Michael's Building extension Col 127mm x 176mm (1 photograph)	[1996]	BM09-RRA1
EST/1/2/7/18	Photograph of front exterior of St Michael's Building extension from sports ground Col 127mm x 176mm (1 photograph)	[1996]	BM09-RRA1

Reference	Description	Date	Shelf Mark
EST/1/2/8	Rees Hall (Old) <i>See also EST/1/4/3-6, 8-11 and 68 images of various dates</i>	[1995]	
EST/1/2/8/1	Photograph of front exterior of Rees Hall from opposite side of the road Col 102mm x 149mm (1 photograph)	[1995]	BM09-RR1
EST/1/2/8/2	Photograph of front exterior of Rees Hall from opposite side of the road Col 102mm x 149mm (1 photograph)	[1995]	BM09-RR1
EST/1/2/8/3	Photographs of front exterior of Rees Hall taped together to form a panoramic image Col 102mm x 149mm (3 photographs)	[1995]	BM09-RR1
EST/1/2/8/4	Photograph of rear exterior of old Rees Hall from the garages [three photographs fixed together to create a panoramic view] Undated 150mmx220mm (1 photograph)	[1995]	BM09-RR1
EST/1/2/9	Rees Hall (New) With compliment slip from Hayward Building Contractors	[1996]	
EST/1/2/9/1	Photograph of the front exterior of Rees Hall from Pier Road Col 156mm x 201mm Photographer: Grahame Jackson, Romsey (1 photograph)	[1996]	BM09-RR1
EST/1/2/9/2	Photograph of the front exterior of Rees Hall from Southsea Common Col 156mm x 201mm Photographer: Grahame Jackson, Romsey (1 photograph)	[1996]	BM09-RR1
EST/1/2/9/3	Photograph of the interior of kitchens at Rees Hall with two members of kitchen staff Col 156mm x 201mm Photographer: Grahame Jackson, Romsey (1 photograph)	[1996]	BM09-RR1

Reference	Description	Date	Shelf Mark
EST/1/2/9/4	Photograph of the interior of a student bedroom Col 156mm x 201mm Photographer: Grahame Jackson, Romsey (1 photograph)	[1996]	BM09-RAA1
EST/1/2/9/5	Photograph of the front exterior of Rees Hall from Southsea Common Col 156mm x 201mm Photographer: Grahame Jackson, Romsey (1 photograph)	[1996]	BM09-RAA1
EST/1/2/9/6	Photograph of the ironwork on the front exterior of Rees Hall Col 156mm x 201mm Photographer: Grahame Jackson, Romsey (1 photograph)	[1996]	BM09-RAA1
EST/1/2/9/7	Photograph of a communal seating area with tables and television in Rees Hall Col 156mm x 201mm Photographer: Grahame Jackson, Romsey (1 photograph)	[1996]	BM09-RAA1
EST/1/2/9/8	Photograph of the interior of a student bedroom with ensuite bathroom Col 156mm x 201mm Photographer: Grahame Jackson, Romsey (1 photograph)	[1996]	BM09-RAA1
EST/1/2/9/9	Photograph of the interior of a student bathroom Col 156mm x 201mm Photographer: Grahame Jackson, Romsey (1 photograph)	[1996]	BM09-RAA1
EST/1/2/9/10	Photograph of the interior of a student bedroom with ensuite bathroom Col 156mm x 201mm Photographer: Grahame Jackson, Romsey (1 photograph)	[1996]	BM09-RAA1
EST/1/2/9/11	Photograph of the front exterior of Rees Hall from opposite side of the road Col 156mm x 201mm Photographer: Grahame Jackson, Romsey (1 photograph)	[1996]	BM09-RAA1

Reference	Description	Date	Shelf Mark
EST/1/2/10	Various University of Portsmouth Buildings 1 See EST/1/2/10/38 for negatives of some images	1990s?	
EST/1/2/10/1	Photograph of the front exterior of Portland Building Col 109mm x 164mm (1 photograph)	1990s	BM09-RR1
EST/1/2/10/2	Photograph of the side exterior of Portland Building Col 109mm x 164mm (1 photograph)	1990s	BM09-RR1
EST/1/2/10/3	Photograph of the exterior of Buckingham Building and the side exterior of Portland Building with sign reading 'A new building for the Faculty of the Environment' from the car park Col 109mm x 164mm (1 photograph)	1990s	BM09-RR1
EST/1/2/10/4	Photograph of a car park with Buckingham Building and Lion Gate Building visible behind Col 109mm x 164mm (1 photograph)	1990s	BM09-RR1
EST/1/2/10/5	Photograph of the exterior of Lion Gate Building from the car park with a small section of Buckingham Building visible partly obscured by a finger on the lens Col 109mm x 164mm (1 photograph)	1990s	BM09-RR1
EST/1/2/10/6	Photograph of the side of a public house with Lion Gate Building and Guildhall clock visible in the background Col 109mm x 164mm (1 photograph)	1990s	BM09-RR1
EST/1/2/10/7	Photograph of exterior of St Michael's Building from King Henry I Street Col 109mm x 164mm (1 photograph)	1990s	BM09-RR1
EST/1/2/10/8	Photograph of front entrance of King Henry Building during building work Col 109mm x 164mm (1 photograph)	1990s	BM09-RR1

Reference	Description	Date	Shelf Mark
EST/1/2/10/9	Photograph of front exterior of Buckingham Building rear exterior of Burnaby Building and area around Portland Street Col 109mm x 164mm (1 photograph)	1990s	BM09-RAA1
EST/1/2/10/10	Photograph of Cambridge Road with University Library obscured by trees with Mercantile House visible in the background Col 109mm x 164mm (1 photograph)	1990s	BM09-RAA1
EST/1/2/10/11	Photograph of White Swan car park with St Andrews Court visible in background Col 109mm x 164mm (1 photograph)	1990s	BM09-RAA1
EST/1/2/10/12	Photograph of the rear exterior of Burnaby Building Col 109mm x 164mm (1 photograph)	1990s	BM09-RAA1
EST/1/2/10/13	Photograph of the exterior Lion Gate Building from the courtyard Col 109mm x 164mm (1 photograph)	1990s	BM09-RAA1
EST/1/2/10/14	Photograph of the front exterior Buckingham Building and rear exterior of Burnaby Building with Argonaut sculpture Col 109mm x 164mm (1 photograph)	1990s	BM09-RAA1
EST/1/2/10/15	Photograph of the rear exterior of Lion Gate Building and buildings behind in St James Street? from car park Col 109mm x 164mm (1 photograph)	1990s	BM09-RAA1

Reference	Description	Date	Shelf Mark
EST/1/2/10/16	Photograph of the side exterior of a building on St James' Street? from car park Col 109mm x 164mm (1 photograph)	1990s	BM09-RR1
EST/1/2/10/17	Photograph of the side exterior of Buckingham Building Col 109mm x 164mm (1 photograph)	1990s	BM09-RR1
EST/1/2/10/18	Photograph of the front exterior of Park Building in summer Col 109mm x 164mm (1 photograph)	1990s	BM09-RR1
EST/1/2/10/19	Photograph of the rear exterior of a building in St James' Street? with area of car park caged off Col 109mm x 164mm (1 photograph)	1990s	BM09-RR1
EST/1/2/10/20	Photograph of the rear exterior and gate of Burnaby Building Col 109mm x 164mm (1 photograph)	1990s	BM09-RR1
EST/1/2/10/21	Photograph of the side gate of Burnaby Building Col 109mm x 164mm (1 photograph)	1990s	BM09-RR1
EST/1/2/10/22	Photograph of the rear exterior of Wiltshire Street Building Col 109mm x 164mm (1 photograph)	1990s	BM09-RR1
EST/1/2/10/23	Photograph of the front exterior of St Pauls Annexe Col 109mm x 164mm (1 photograph)	1990s	BM09-RR1
EST/1/2/10/24	Photograph of the gates to the old John Pounds Centre School of Art, Design and Media Col 109mm x 164mm (1 photograph)	1990s	BM09-RR1
EST/1/2/10/25	Photograph of rear exterior of the old John Pounds Centre School of Art, Design and Media Col 109mm x 164mm (1 photograph)	1990s	BM09-RR1

Reference	Description	Date	Shelf Mark
EST/1/2/10/26	Photograph of rear exterior of the old John Pounds Centre School of Art, Design and Media from the corner of Aylward Street Col 109mm x 164mm (1 photograph)	1990s	BM09-RAA1
EST/1/2/10/27	Photograph of a derelict building in Aylward Street taken from the corner of Aylward Street [former caretaker's house, John Pounds Centre?] Col 109mm x 164mm (1 photograph)	1990s	BM09-RAA1
EST/1/2/10/28	Photograph of the front exterior of the old John Pounds Centre, School of Art, Design and Media Col 109mm x 164mm (1 photograph)	1990s	BM09-RAA1
EST/1/2/10/29	Photograph of the gates to the old John Pounds Centre, School of Art, Design and Media Col 109mm x 164mm (1 photograph)	1990s	BM09-RAA1
EST/1/2/10/30	Photograph of a section of the front exterior of the old John Pounds Centre, School of Art, Design and Media Col 109mm x 164mm (1 photograph)	1990s	BM09-RAA1
EST/1/2/10/31	Photograph of a doorway into the old John Pounds Centre, School of Art, Design and Media Col 109mm x 164mm (1 photograph)	1990s	BM09-RAA1
EST/1/2/10/32	Photograph of the exterior of the Institute of Marine Sciences [from Ferry Road?] Col 126mm x 176mm (1 photograph)	1990s	BM09-RAA1
EST/1/2/10/33	Photograph of the front exterior of Burnaby Terrace from Burnaby Road Col 126mm x 176mm (1 photograph)	1990s	BM09-RAA1
EST/1/2/10/34	Photograph of an aerial view of the Langstone campus from Burnaby Road Col 114mm x 166mm (1 photograph)	1990s	BM09-RAA1

Reference	Description	Date	Shelf Mark
EST/1/2/10/35	Photograph of a many students sat in Ravelin Park on a sunny day Col 111mm x 169mm (1 photograph)	1990s	BM09-RRA1
EST/1/2/10/36	Photograph of the front exterior of Park Building Col 115mm x 165mm (1 photograph)	1990s	BM09-RRA1
EST/1/2/10/37	Photograph of an aerial view of Ravelin Park and surrounding area including University Library; Alexander House; Town Mount; Rotunda; Ravelin House; Gun House; Mercantile House; St Andrews court; University House; Nuffield Centre; St Pauls Building; Institute of Surveying and Harry Law Hall construction site [Harry Law Hall opened October 1995] Col 115mm x 153mm (1 photograph)	1990s	BM09-RRA1
EST/1/2/10/38	Photographic negatives of images of various buildings including Portland Building; Buckingham Building; Liongate Building; Burnaby Building; St Michael's Building; King Henry Building and old John Pounds Centre containing EST/1/2/10/1-8,15-16; 18-20 and 24-31 Undated B/W 40mmx150mm Former Ref: EST/1/4/39 (1 photograph)	1990s	BM09-RRA1

Reference	Description	Date	Shelf Mark
EST/1/2/11	Eldon Building	[2000]	
EST/1/2/11/1	Photograph of huts behind Eldon Building under demolition with an excavator and two workmen Col 126mm x 189mm (1 photograph)	[2000]	BM10-RR1
EST/1/2/11/2	Photograph of exterior of Eldon Building with huts under demolition Col 126mm x 189mm (1 photograph)	[2000]	BM10-RR1
EST/1/2/11/3	Photograph of huts behind Eldon Building under demolition with an excavator and a workman Col 126mm x 189mm (1 photograph)	[2000]	BM10-RR1
EST/1/2/11/4	Photograph of huts behind Eldon Building under demolition with an excavator and two workmen Col 126mm x 189mm (1 photograph)	[2000]	BM10-RR1
EST/1/2/11/5	Photograph of huts behind Eldon Building under demolition with an excavator and a workman cutting metal Col 126mm x 189mm (1 photograph)	[2000]	BM10-RR1
EST/1/2/11/6	Photograph of huts behind Eldon Building under demolition with an excavator and a workman cutting metal Col 126mm x 189mm (1 photograph)	[2000]	BM10-RR1
EST/1/2/11/7	Photograph of huts behind Eldon Building under demolition with an excavator and a workman cutting metal Col 126mm x 189mm (1 photograph)	[2000]	BM10-RR1
EST/1/2/11/8	Photograph of huts behind Eldon Building under demolition with an excavator and a workman cutting metal Col 126mm x 189mm (1 photograph)	[2000]	BM10-RR1

Reference	Description	Date	Shelf Mark
EST/1/2/11/9	Photograph of exterior of Eldon Building with huts under demolition Col 126mm x 189mm (1 photograph)	[2000]	BM10-RR1
EST/1/2/11/10	Photograph of huts behind Eldon Building under demolition Col 126mm x 189mm (1 photograph)	[2000]	BM10-RR1
EST/1/2/11/11	Photograph of huts behind Eldon Building under demolition with an excavator Col 126mm x 189mm (1 photograph)	[2000]	BM10-RR1
EST/1/2/11/12	Photograph of huts behind Eldon Building under demolition with an excavator Col 126mm x 189mm (1 photograph)	[2000]	BM10-RR1
EST/1/2/11/13	Photograph of the interior of an unfinished stairwell in Eldon Building Col 126mm x 189mm (1 photograph)	[2000]	BM10-RR1
EST/1/2/11/14	Photograph of the interior of an unfinished stairwell in Eldon Building Col 126mm x 189mm (1 photograph)	[2000]	BM10-RR1
EST/1/2/11/15	Photograph of the interior of a computer room in Eldon Building? Col 126mm x 189mm (1 photograph)	[2000]	BM10-RR1
EST/1/2/11/16	Photograph of the interior of a computer room in Eldon Building? Col 126mm x 189mm (1 photograph)	[2000]	BM10-RR1
EST/1/2/11/17	Photograph of the interior of a stairwell in Eldon Building Col 126mm x 189mm (1 photograph)	[2000]	BM10-RR1

Reference	Description	Date	Shelf Mark
EST/1/2/11/18	Photograph of the interior of a stairwell in in Eldon Building Col 126mm x 189mm (1 photograph)	[2000]	BM10-RR1
EST/1/2/11/19	Photograph of the interior of a stairwell in in Eldon Building Col 126mm x 189mm (1 photograph)	[2000]	BM10-RR1
EST/1/2/11/20	Photograph of the interior of a stairwell in in Eldon Building Col 126mm x 189mm (1 photograph)	[2000]	BM10-RR1
EST/1/2/11/21	Photograph of the interior of Eldon Building top floor [open plan display space?] filled with furniture and panels Col 126mm x 189mm (1 photograph)	[2000]	BM10-RR1
EST/1/2/11/22	Photograph of the interior of Eldon Building top floor [open plan display space?] filled with furniture and panels Col 126mm x 189mm (1 photograph)	[2000]	BM10-RR1
EST/1/2/11/23	Photograph of the interior of Eldon Building close up of ceiling Col 126mm x 189mm (1 photograph)	[2000]	BM10-RR1
EST/1/2/11/24	Photograph of the interior of Eldon Building close up of ceiling Col 126mm x 189mm (1 photograph)	[2000]	BM10-RR1
EST/1/2/11/25	Photograph of the interior of Eldon Building close up of ceiling Col 126mm x 189mm (1 photograph)	[2000]	BM10-RR1
EST/1/2/11/26	Photograph of the interior of Eldon Building close up of ceiling Col 126mm x 189mm (1 photograph)	[2000]	BM10-RR1

Reference	Description	Date	Shelf Mark
EST/1/2/11/27	Photograph of the interior of Eldon Building close up of ceiling Col 126mm x 189mm (1 photograph)	[2000]	BM10-RR1
EST/1/2/11/28	Photograph of the view from the window in Eldon Building looking over courtyard Col 126mm x 189mm (1 photograph)	[2000]	BM10-RR1
EST/1/2/11/29	Photograph of the interior of Eldon Building top floor [open plan display space?] filled with furniture and panels Col 126mm x 189mm (1 photograph)	[2000]	BM10-RR1
EST/1/2/11/30	Photograph of the interior of Eldon Building top floor [open plan display space?] filled with furniture and panels Col 126mm x 189mm (1 photograph)	[2000]	BM10-RR1
EST/1/2/11/31	Photograph of the interior of Eldon Building top floor [open plan display space?] filled with furniture and panels including John Pounds Centre sign Col 126mm x 189mm (1 photograph)	[2000]	BM10-RR1
EST/1/2/11/32	Photograph of huts behind Eldon Building under demolition with an excavator Col 126mm x 189mm (1 photograph)	[2000]	BM10-RR1
EST/1/2/11/33	Photograph of huts behind Eldon Building under demolition with an excavator Col 126mm x 189mm (1 photograph)	[2000]	BM10-RR1
EST/1/2/11/34	Photograph of the interior of an unfinished stairwell in Eldon Building Col 126mm x 189mm (1 photograph)	[2000]	BM10-RR1
EST/1/2/11/35	Photograph of the interior of an unfinished stairwell in Eldon Building Col 126mm x 189mm (1 photograph)	[2000]	BM10-RR1

Reference	Description	Date	Shelf Mark
EST/1/2/12	Burnaby Building fire damage Fire occurred night of 23 May 2000 at hut next door which also caused significant damage to Burnaby Building. Reported in Portsmouth News 24 May 2000 p3/	2000	
EST/1/2/12/1	Photograph of area outside Burnaby Building damaged by fire with sign reading 'GO26' Col 126mm x 189mm (1 photograph)	May 2000	
EST/1/2/12/2	Photograph of area outside Burnaby Building damaged by fire Col 126mm x 189mm (1 photograph)	May 2000	BM10-RR1
EST/1/2/12/3	Photograph of exterior of Burnaby Building and area outside damaged by fire Col 126mm x 189mm (1 photograph)	May 2000	BM10-RR1
EST/1/2/12/4	Photograph of exterior of Burnaby Building and area outside damaged by fire Col 126mm x 189mm (1 photograph)	May 2000	BM10-RR1
EST/1/2/12/5	Photograph of exterior of Burnaby Building and area outside damaged by fire Col 126mm x 189mm (1 photograph)	May 2000	BM10-RR1
EST/1/2/12/6	Photograph of exterior of Burnaby Building and area outside damaged by fire Col 126mm x 189mm (1 photograph)	May 2000	BM10-RR1
EST/1/2/12/7	Photograph of exterior of Burnaby Building and area outside damaged by fire Col 126mm x 189mm (1 photograph)	May 2000	BM10-RR1
EST/1/2/12/8	Photograph of area outside Burnaby Building damaged by fire Col 126mm x 189mm (1 photograph)	May 2000	BM10-RR1
EST/1/2/12/9	Photograph of area outside Burnaby Building damaged by fire Col 126mm x 189mm (1 photograph)	May 2000	BM10-RR1

Reference	Description	Date	Shelf Mark
EST/1/2/12/10	Photograph of area outside Burnaby Building damaged by fire Col 126mm x 189mm (1 photograph)	May 2000	BM10-RR1
EST/1/2/12/11	Photograph of shed outside Burnaby Building damaged by fire Col 126mm x 189mm (1 photograph)	May 2000	BM10-RR1
EST/1/2/12/12	Photograph of exterior of Burnaby Building damaged by fire Col 126mm x 189mm (1 photograph)	May 2000	BM10-RR1
EST/1/2/12/13	Photograph of exterior of Burnaby Building and area outside damaged by fire Col 126mm x 189mm (1 photograph)	May 2000	BM10-RR1
EST/1/2/12/14	Photograph of exterior of Burnaby Building and area outside damaged by fire Col 126mm x 189mm (1 photograph)	May 2000	BM10-RR1
EST/1/2/12/15	Photograph of exterior of Burnaby Building and area outside damaged by fire Col 126mm x 189mm (1 photograph)	May 2000	BM10-RR1
EST/1/2/12/16	Photograph of area outside Burnaby Building damaged by fire Col 126mm x 189mm (1 photograph)	May 2000	BM10-RR1
EST/1/2/12/17	Photograph of area outside Burnaby Building damaged by fire Col 126mm x 189mm (1 photograph)	May 2000	BM10-RR1
EST/1/2/12/18	Photograph of area outside Burnaby Building damaged by fire Col 126mm x 189mm (1 photograph)	May 2000	BM10-RR1

Reference	Description	Date	Shelf Mark
EST/1/2/12/19	Photograph of area outside Burnaby Building damaged by fire with a man looking at the site Col 126mm x 189mm (1 photograph)	May 2000	BM10-RR1
EST/1/2/12/20	Photograph of the exterior of Burnaby Building damaged by fire Col 126mm x 189mm (1 photograph)	May 2000	BM10-RR1
EST/1/2/12/21	Photograph of the exterior of Burnaby Building damaged by fire Col 126mm x 189mm (1 photograph)	May 2000	BM10-RR1
EST/1/2/12/22	Photograph of the exterior of Burnaby Building damaged by fire Col 126mm x 189mm (1 photograph)	May 2000	BM10-RR1
EST/1/2/12/23	Photograph of the exterior of Burnaby Building damaged by fire Col 126mm x 189mm (1 photograph)	May 2000	BM10-RR1
EST/1/2/12/24	Photograph of the exterior of Burnaby Building damaged by fire Col 126mm x 189mm (1 photograph)	May 2000	BM10-RR1
EST/1/2/12/25	Photograph of area outside Burnaby Building damaged by fire Col 126mm x 189mm (1 photograph)	May 2000	BM10-RR1
EST/1/2/12/26	Photograph of the exterior of Burnaby Building damaged by fire with a man looking out of a broken window Col 126mm x 189mm (1 photograph)	May 2000	BM10-RR1
EST/1/2/12/27	Photograph of area outside Burnaby Building damaged by fire Col 126mm x 189mm (1 photograph)	May 2000	BM10-RR1

Reference	Description	Date	Shelf Mark
EST/1/2/12/28	Photograph of area outside Burnaby Building damaged by fire Col 126mm x 189mm (1 photograph)	May 2000	BM10-RR1
EST/1/2/12/29	Photograph of area outside Burnaby Building damaged by fire Col 126mm x 189mm (1 photograph)	May 2000	BM10-RR1
EST/1/2/12/30	Photograph of area outside Burnaby Building damaged by fire Col 126mm x 189mm (1 photograph)	May 2000	BM10-RR1
EST/1/2/12/31	Photograph of area outside Burnaby Building damaged by fire Col 126mm x 189mm (1 photograph)	May 2000	BM10-RR1
EST/1/2/12/32	Photograph of area outside Burnaby Building damaged by fire including roof of hut view from Burnaby Building Col 126mm x 189mm (1 photograph)	May 2000	BM10-RR1
EST/1/2/12/33	Photograph of area outside Burnaby Building damaged by fire including roof of hut view from Burnaby Building Col 126mm x 189mm (1 photograph)	May 2000	BM10-RR1
EST/1/2/12/34	Photograph of glasshouses with some fire damage and overhanging tree with burnt leaves view from Burnaby Building Col 126mm x 189mm (1 photograph)	May 2000	BM10-RR1
EST/1/2/12/35	Photograph of area outside Burnaby Building damaged by fire view from Burnaby Building Col 126mm x 189mm (1 photograph)	May 2000	BM10-RR1

Reference	Description	Date	Shelf Mark
EST/1/2/12/36	Photograph of area outside Burnaby Building damaged by fire view from Burnaby Building Col 126mm x 189mm (1 photograph)	May 2000	BM10-RR1
EST/1/2/12/37	Photograph of area outside Burnaby Building damaged by fire view from Burnaby Building Col 126mm x 189mm (1 photograph)	May 2000	BM10-RR1
EST/1/2/12/38	Photograph of area outside Burnaby Building damaged by fire view from Burnaby Building Col 126mm x 189mm (1 photograph)	May 2000	BM10-RR1
EST/1/2/12/39	Photograph of area outside Burnaby Building damaged by fire view from Burnaby Building Col 126mm x 189mm (1 photograph)	May 2000	BM10-RR1
EST/1/2/12/40	Photograph of area outside Burnaby Building damaged by fire view from Burnaby Building Col 126mm x 189mm (1 photograph)	May 2000	BM10-RR1
EST/1/2/12/41	Photograph of area outside Burnaby Building damaged by fire view from Burnaby Building Col 126mm x 189mm (1 photograph)	May 2000	BM10-RR1
EST/1/2/12/42	Photograph of the exterior of Burnaby Building damaged by fire Col 126mm x 189mm (1 photograph)	May 2000	BM10-RR1
EST/1/2/12/43	Photograph of the interior of Burnaby Building damaged by fire with two men removing broken windows Col 126mm x 189mm (1 photograph)	May 2000	BM10-RR1

Reference	Description	Date	Shelf Mark
EST/1/2/12/44	Photograph of the interior of Burnaby Building damaged by fire with broken windows Col 126mm x 189mm (1 photograph)	May 2000	BM10-RR1
EST/1/2/12/45	Photograph of the interior of an office in Burnaby Building with damage to windows caused by fire Col 126mm x 189mm (1 photograph)	May 2000	BM10-RR1
EST/1/2/12/46	Photograph of the interior of Burnaby Building looking through window Col 126mm x 189mm (1 photograph)	May 2000	BM10-RR1
EST/1/2/12/47	Photograph of the interior of Burnaby Building with broken windows caused by fire damage Col 126mm x 189mm (1 photograph)	May 2000	BM10-RR1

Reference	Description	Date	Shelf Mark
EST/1/2/13	Portland Building, University of Portsmouth Bus and Langstone Campus <i>See also EST/1/4/13-19 for further images of Portland Building</i> <i>See also EST/1/4/31+33-40 for further images of Langstone Campus</i>	1990s-2000	
EST/1/2/13/1	Photograph of exterior of Portland Building under construction Col 126mm x 189mm (1 photograph)	c1995	BM10-RRA1
EST/1/2/13/2	Photograph of exterior of Portland Building under construction with Park Building, St Michaels and Guildhall visible in background Col 126mm x 189mm (1 photograph)	c1995	BM10-RRA1
EST/1/2/13/3	Photograph of exterior of Portland Building under construction with Park Building, St Michaels and Guildhall visible in background Col 126mm x 189mm (1 photograph)	c1995	BM10-RRA1
EST/1/2/13/4	Photograph of exterior of Portland Building under construction with Park Building, St Michaels and Guildhall visible in background Col 126mm x 189mm (1 photograph)	c1995	BM10-RRA1
EST/1/2/13/5	Photograph of exterior of Portland Building under construction Col 126mm x 189mm (1 photograph)	c1995	BM10-RRA1
EST/1/2/13/6	Photograph of exterior of Portland Building under construction Col 126mm x 189mm (1 photograph)	c1995	BM10-RRA1
EST/1/2/13/7	Photograph of exterior of Portland Building under construction Col 126mm x 189mm (1 photograph)	c1995	BM10-RRA1
EST/1/2/13/8	Photograph of exterior of Portland Building under construction Col 126mm x 189mm (1 photograph)	c1995	BM10-RRA1

Reference	Description	Date	Shelf Mark
EST/1/2/13/9	Photograph of single deck University of Portsmouth bus at Langstone campus with Barnard Tower in background Col 126mm x 189mm (1 photograph)	2000	BM10-RR1
EST/1/2/13/10	Photograph of single deck University of Portsmouth bus at Langstone campus front view with sign in window reading 'Business School Milton Campus shuttle' Col 126mm x 189mm (1 photograph)	2000	BM10-RR1
EST/1/2/13/11	Photograph of single deck University of Portsmouth bus at Langstone campus front view with sign in window reading 'Business School Milton Campus shuttle' Col 126mm x 189mm (1 photograph)	2000	BM10-RR1
EST/1/2/13/12	Photograph of playing fields at Langstone campus view from Barnard Tower? Col 126mm x 189mm (1 photograph)	2000	BM10-RR1
EST/1/2/13/13	Photograph of the exterior of Barnard Tower at Langstone campus [elevated view] Col 126mm x 189mm (1 photograph)	2000	BM10-RR1
EST/1/2/13/14	Photograph of the exterior of Barnard Tower at Langstone campus with view across Langstone Harbour [elevated view] Col 126mm x 189mm (1 photograph)	2000	BM10-RR1
EST/1/2/13/15	Photograph of the exterior of Barnard Tower at Langstone campus with view across Langstone Harbour [elevated view] Col 126mm x 189mm (1 photograph)	2000	BM10-RR1
EST/1/2/13/16	Photograph of the exterior of Barnard Tower at Langstone campus with view across Langstone Harbour [elevated view] Col 126mm x 189mm (1 photograph)	2000	BM10-RR1

Reference	Description	Date	Shelf Mark
EST/1/2/13/17	<p>Photograph of Langstone campus including Barnard Tower, Dorothy Dymond and Edith White Halls and Trust Hall with view across Langstone Harbour [elevated view]</p> <p>Col 126mm x 189mm</p> <p>(1 photograph)</p>	2000	BM10-RR1
EST/1/2/13/18	<p>Photograph of Langstone campus including Dorothy Dymond and Edith White Halls</p> <p>Col 126mm x 189mm</p> <p>(1 photograph)</p>	2000	BM10-RR1
EST/1/2/13/19	<p>Photograph of Langstone campus including Dorothy Dymond and Edith White Halls and Trust Hall with view across Langstone Harbour [elevated view]</p> <p>Col 126mm x 189mm</p> <p>(1 photograph)</p>	2000	BM10-RR1
EST/1/2/13/20	<p>Photograph of Langstone campus including Dorothy Dymond and Edith White Halls and Trust Hall with view across Langstone Harbour [elevated view]</p> <p>Col 126mm x 189mm</p> <p>(1 photograph)</p>	2000	BM10-RR1
EST/1/2/13/21	<p>Photograph of Langstone campus including Dorothy Dymond and Edith White Halls with view across Langstone Harbour [elevated view]</p> <p>Col 126mm x 189mm</p> <p>(1 photograph)</p>	2000	BM10-RR1
EST/1/2/13/22	<p>Photograph of Langstone campus including Dorothy Dymond and Edith White Halls and Trust Hall at Langstone campus with view across Langstone Harbour [elevated view]</p> <p>Col 126mm x 189mm</p> <p>(1 photograph)</p>	2000	BM10-RR1
EST/1/2/13/23	<p>Photograph of Langstone campus including Barnard Tower, Dorothy Dymond and Edith White Halls and Trust Hall with view across Langstone Harbour [elevated view]</p> <p>Col 126mm x 189mm</p> <p>(1 photograph)</p>	2000	BM10-RR1

Reference	Description	Date	Shelf Mark
EST/1/2/13/24	Photograph of the exterior of Barnard Tower at Langstone campus with sports pitches in background Col 126mm x 189mm (1 photograph)	2000	BM10-RR1
EST/1/2/13/25	Photograph of Langstone Campus including Barnard Tower and Trust Hall [elevated view] Col 126mm x 189mm (1 photograph)	2000	BM10-RR1
EST/1/2/13/26	Photograph of Langstone campus including Barnard Tower and Trust Hall with view across Langstone Harbour [elevated view] Col 126mm x 189mm (1 photograph)	2000	BM10-RR1
EST/1/2/13/27	Photograph of Langstone campus including Barnard Tower and Trust Hall with view across Langstone Harbour [elevated view] Col 126mm x 189mm (1 photograph)	2000	BM10-RR1
EST/1/2/13/28	Photograph of Langstone campus including Barnard Tower and Trust Hall with view across Langstone Harbour [elevated view] Col 126mm x 189mm (1 photograph)	2000	BM10-RR1
EST/1/2/13/29	Photograph of Langstone campus including Barnard Tower, Dorothy Dymond and Edith White Halls and Trust Hall with view across Langstone Harbour [elevated view] Col 126mm x 189mm (1 photograph)	2000	BM10-RR1
EST/1/2/13/30	Photograph of Langstone campus including Barnard Tower [elevated view] Col 126mm x 189mm (1 photograph)	2000	BM10-RR1
EST/1/2/13/31	Photograph of the exterior of Barnard Tower at Langstone campus looking upwards Col 126mm x 189mm (1 photograph)	2000	BM10-RR1

Reference	Description	Date	Shelf Mark
EST/1/2/13/32	Photograph of the exterior of Barnard Tower at Langstone campus looking upwards Col 126mm x 189mm (1 photograph)	2000	BM10-RR1
EST/1/2/13/33	Photograph of the exterior of Barnard Tower at Langstone campus looking upwards Col 126mm x 189mm (1 photograph)	2000	BM10-RR1
EST/1/2/13/34	Photograph of single deck University of Portsmouth bus at Langstone campus side view Col 126mm x 189mm (1 photograph)	2000	BM10-RR1
EST/1/2/13/35	Photograph of single deck University of Portsmouth bus at Langstone campus rear view Col 126mm x 189mm (1 photograph)	2000	BM10-RR1
EST/1/2/14	Langstone playing fields	1997	
With covering letter from Monk Rawling Chartered Surveyors explaining that the photographs were taken to document the state and condition of the ground on which boreholes will be carried out			
EST/1/2/14/1	Photograph of playing fields at Langstone campus Col 101mm x 151mm (1 photograph)	24 Feb 1997	BM09-RR1
EST/1/2/14/2	Photograph of playing fields at Langstone campus Col 101mm x 151mm (1 photograph)	24 Feb 1997	BM09-RR1
EST/1/2/14/3	Photograph of playing fields at Langstone campus with Langstone Village in background Col 101mm x 151mm (1 photograph)	24 Feb 1997	BM09-RR1
EST/1/2/14/4	Photograph of playing fields at Langstone campus Col 101mm x 151mm (1 photograph)	24 Feb 1997	BM09-RR1

Reference	Description	Date	Shelf Mark
EST/1/2/14/5	Photograph of playing fields at Langstone campus Col 101mm x 151mm (1 photograph)	24 Feb 1997	BM09-RR1
EST/1/2/14/6	Photograph of playing fields at Langstone campus with Trust Hall in background Col 101mm x 151mm (1 photograph)	24 Feb 1997	BM09-RR1
EST/1/2/14/7	Photograph of playing fields at Langstone campus with Trust Hall in background Col 101mm x 151mm (1 photograph)	24 Feb 1997	BM09-RR1
EST/1/2/14/8	Photograph of playing fields at Langstone campus Col 101mm x 151mm (1 photograph)	24 Feb 1997	BM09-RR1
EST/1/2/14/9	Photograph of playing fields at Langstone campus Col 101mm x 151mm (1 photograph)	24 Feb 1997	BM09-RR1
EST/1/2/14/10	Photograph of playing fields at Langstone campus Col 101mm x 151mm (1 photograph)	24 Feb 1997	BM09-RR1
EST/1/2/14/11	Photograph of playing fields at Langstone campus Col 101mm x 151mm (1 photograph)	24 Feb 1997	BM09-RR1
EST/1/2/14/12	Photograph of playing fields at Langstone campus Col 101mm x 151mm (1 photograph)	24 Feb 1997	BM09-RR1
EST/1/2/14/13	Photograph of playing fields at Langstone campus Col 101mm x 151mm (1 photograph)	24 Feb 1997	BM09-RR1

Reference	Description	Date	Shelf Mark
EST/1/2/14/14	Photograph of playing fields and car park at Langstone campus Col 101mm x 151mm (1 photograph)	24 Feb 1997	BM09-RRA1
EST/1/2/14/15	Photograph of car park at Langstone campus Col 101mm x 151mm (1 photograph)	24 Feb 1997	BM09-RRA1
EST/1/2/14/16	Photograph of playing fields and car park at Langstone campus Col 101mm x 151mm (1 photograph)	24 Feb 1997	BM09-RRA1
EST/1/2/14/17	Photograph of playing fields and car park at Langstone campus Col 101mm x 151mm (1 photograph)	24 Feb 1997	BM09-RRA1

Reference	Description	Date	Shelf Mark
EST/1/2/15	Environment [Ravelin Park meadow, planting and University of Portsmouth Bus]	1997-[2001]	
EST/1/2/15/1	Photograph of meadow in Ravelin Park looking South with Hartford House visible in background Col 102mm x 149mm (2 copies of the photograph)	Jun 2000	BM09-RAA1
EST/1/2/15/2	Photograph of path through meadow in Ravelin Park Col 102mm x 149mm (2 copies of the photograph)	Jun 2000	BM09-RAA1
EST/1/2/15/3	Photograph of plants in meadow in Ravelin Park with Town Mount? visible in background Col 102mm x 149mm (2 copies of the photograph)	Jun 2000	BM09-RAA1
EST/1/2/15/4	Photograph of planting in front of Burnaby Cottages later Burnaby Terrace with two men working on it in the background Col 102mm x 149mm (2 copies of the photograph)	Jun 2000	BM09-RAA1
EST/1/2/15/5	Photograph of two men planting shrubs in front of Burnaby Cottages later Burnaby Terrace Col 102mm x 149mm (2 copies of the photograph)	Jun 2000	BM09-RAA1
EST/1/2/15/6	Photograph of planting in front of Burnaby Cottages later Burnaby Terrace with Milldam and site later occupied by Richmond Building in the background Col 102mm x 149mm (2 copies of the photograph)	Jun 2000	BM09-RAA1
EST/1/2/15/7	Photograph of a small area in front of Burnaby Cottages later Burnaby Terrace prior to planting Col 102mm x 149mm (2 copies of the photograph)	Jun 2000	BM09-RAA1
EST/1/2/15/8	Photograph of Ravelin House garden and small section of side exterior of building Col 102mm x 149mm (1 photograph)	Jun 2000	BM09-RAA1

Reference	Description	Date	Shelf Mark
EST/1/2/15/9	Photograph of side exterior of Ravelin House and garden looking towards Hampshire Terrace Col 102mm x 149mm (1 photograph)	Jun 2000	BM09-RAA1
EST/1/2/15/10	Photograph of section of side exterior of Ravelin House and steps into garden Col 102mm x 149mm (1 photograph)	Jun 2000	BM09-RAA1
EST/1/2/15/11	Photograph of Ravelin House garden with Record Office building visible in background Col 102mm x 149mm (2 copies of the photograph)	Jun 2000	BM09-RAA1
EST/1/2/15/12	Photograph of bicycle stand with bicycles attached outside Cambridge Building? Col 102mm x 151mm (2 copies of the photograph)	21 Nov 1997	BM09-RAA1
EST/1/2/15/13	Photograph of a fox cub on bank opposite University Library with 'spring 2000' written on reverse with date stamp 9 May 2001 Col 177mm x 121mm (1 photograph)	[2000]	BM09-RAA1
EST/1/2/15/14	Photograph of a fox cub [head and front paws visible only] on bank opposite library with 'spring 2000' in written on reverse and date stamp 9 May 2001 Col 177mm x 121mm (1 photograph)	[2000]	BM09-RAA1
EST/1/2/15/15	Photograph of a fox cub curled up on bank opposite University Library Col 177mm x 121mm (1 photograph)	[2000]	BM09-RAA1
EST/1/2/15/16	Photograph of a fox cub sitting up on bank opposite University Library Col 177mm x 121mm (1 photograph)	[2000]	BM09-RAA1
EST/1/2/15/17	Photograph of a single decker University of Portsmouth bus at bus stop in Cambridge Road opposite the University Library with 'diesel bus' written on reverse with date stamp 9 May 2001 on reverse Col 177mm x 121mm (1 photograph)	[2001]	BM09-RAA1

Reference	Description	Date	Shelf Mark
EST/1/2/15/18	<p>Photograph of the front of a single decker University of Portsmouth bus and two men at a bus stop in Cambridge Road opposite the University Library with 'diesel bus' written on reverse with date stamp 9 May 2001</p> <p>Col 177mm x 121mm</p> <p>(1 photograph)</p>	[2001]	BM09-RR1
EST/1/2/15/19	<p>Photograph of the rear of a single decker University of Portsmouth bus driving away from the bus stop opposite the University Library with Mercantile House visible in the background</p> <p>Col 177mm x 121mm</p> <p>(1 photograph)</p>	[2001]	BM09-RR1
EST/1/2/15/20	<p>Photograph of the bus stop in Cambridge Road opposite the University Library labelled 'Guildhall Campus' and the front of a single decker University of Portsmouth bus</p> <p>Col 177mm x 121mm</p> <p>(1 photograph)</p>	[2001]	BM09-RR1
EST/1/2/15/21	<p>Photograph of the front of a single decker University of Portsmouth bus at a bus stop in Cambridge Road opposite the University Library with two men standing at the bus stop</p> <p>Col 177mm x 121mm</p> <p>(1 photograph)</p>	[2001]	BM09-RR1
EST/1/2/15/22	<p>Photograph of side exterior of Ravelin House and garden looking towards Hampshire Terrace with 'Aug 2000' in manuscript and date stamp 9 May 2001 on reverse</p> <p>Col 177mm x 121mm</p> <p>(1 photograph)</p>	[2000]	BM09-RR1
EST/1/2/15/23	<p>Photograph of side exterior of Ravelin House and garden looking towards Hampshire Terrace with long grass obscuring the foreground, with 'Aug 2000' in manuscript and date stamp 9 May 2001 on reverse</p> <p>Col 177mm x 121mm</p> <p>(1 photograph)</p>	[2000]	BM09-RR1

Reference	Description	Date	Shelf Mark
EST/1/2/15/24	Photograph of area under trees in grounds of Ravelin House Col 178mm x 126mm (1 photograph)	[2000]	BM09-RAA1
EST/1/2/15/25	Photograph of area under trees in grounds of Ravelin House Col 178mm x 126mm (1 photograph)	[2000]	BM09-RAA1
EST/1/2/15/26	Photograph of the side exterior of Ravelin House from the garden with Hampshire Terrace visible in the background Col 178mm x 126mm (1 photograph)	[2000]	BM09-RAA1
EST/1/2/15/27	Photograph of the side exterior of Ravelin House from the garden with Hampshire Terrace visible in the background Col 178mm x 126mm (1 photograph)	[2000]	BM09-RAA1
EST/1/2/15/28	Photograph of the side exterior of Ravelin House from the garden with Hampshire Terrace and Horatia House visible in the background Col 178mm x 126mm (1 photograph)	[2000]	BM09-RAA1
EST/1/2/15/29	Photograph of the side exterior of Ravelin House from the garden with Hampshire Terrace and Horatia House visible in the background Col 178mm x 126mm (1 photograph)	[2000]	BM09-RAA1
EST/1/2/15/30	Photograph of the side exterior of Ravelin House from the garden Col 178mm x 126mm (1 photograph)	[2000]	BM09-RAA1
EST/1/2/15/31	Photograph of the side exterior of Ravelin House from the garden Col 178mm x 126mm (1 photograph)	[2000]	BM09-RAA1
EST/1/2/15/32	Photograph of the side exterior of Ravelin House from the garden from between two bushes Col 178mm x 126mm (1 photograph)	[2000]	BM09-RAA1

Reference	Description	Date	Shelf Mark
EST/1/2/15/33	Photograph of the side exterior of Ravelin House from the garden from between two bushes Col 178mm x 126mm (1 photograph)	[2000]	BM09-RR1
EST/1/2/15/34	Photograph of the side exterior of Ravelin House from the garden with yellow flowers in foreground Col 178mm x 126mm (1 photograph)	[2000]	BM09-RR1
EST/1/2/15/35	Photograph of the side exterior of Ravelin House from the garden with yellow flowers in foreground Col 178mm x 126mm (1 photograph)	[2000]	BM09-RR1
EST/1/2/15/36	Photograph of the side exterior of Ravelin House from the garden with yellow flowers in foreground Col 178mm x 126mm (1 photograph)	[2000]	BM09-RR1
EST/1/2/15/37	Photograph of the side exterior of Ravelin House from the garden with yellow flowers in foreground Col 178mm x 126mm (2 copies of the photograph)	[2000]	BM09-RR1
EST/1/2/15/38	Photograph of the side exterior of Ravelin House from lawn under an overhanging tree Col 178mm x 126mm (1 photograph)	[2000]	BM09-RR1
EST/1/2/15/39	Photograph of the side exterior of Ravelin House from lawn under an overhanging tree Col 178mm x 126mm (1 photograph)	[2000]	BM09-RR1
EST/1/2/15/40	Photograph of the side exterior of Ravelin House from lawn under an overhanging tree Col 178mm x 126mm (1 photograph)	[2000]	BM09-RR1
EST/1/2/15/41	Photograph of the side exterior of Ravelin House from lawn with wooden bench on right side of image Col 178mm x 126mm (1 photograph)	[2000]	BM09-RR1

Reference	Description	Date	Shelf Mark
EST/1/2/15/42	<p>Photograph of a path in the garden of Ravelin House with railings and Museum Road in the background</p> <p>Col 178mm x 126mm</p> <p>(1 photograph)</p>	[2000]	BM09-RRA1
EST/1/2/15/43	<p>Photograph of side exterior of Ravelin House and garden looking towards Hampshire Terrace with long grass obscuring the foreground</p> <p>Col 177mm x 121mm</p> <p>(1 photograph)</p>	[2000]	BM09-RRA1

Reference	Description	Date	Shelf Mark
EST/1/2/16	Various Portsmouth Polytechnic Buildings	1980s	
EST/1/2/16/1	Contact sheet with images of 17 buildings [See also EST/1/2/16/2-12 for photographic prints of some of these images] with strip of photographic negatives Undated B/W 120mm x 230mm Former Ref: EST/1/4/1 (1 contact sheet; 1 strip of negatives)	1980s	BM06-RRB1
EST/1/2/16/2	Photograph of exterior of Cambridge Building with two cars parked outside Undated B/W 90mm x 140mm (1 photograph)	1980s	BM06-RRB1
EST/1/2/16/3	Photograph of exterior of an unidentified building taken from the car park Undated B/W 90mm x 140mm (1 photograph)	1980s	BM06-RRB1
EST/1/2/16/4	Photograph of side exterior of Wiltshire Building from Wiltshire Street – view from car park Undated B/W 90mm x 140mm (1 photograph)	1980s	BM06-RRB1
EST/1/2/16/5	Photograph of exterior of a building at Langstone Campus with a group of people standing in a line [playing sport?] Undated B/W 90mm x 140mm (1 photograph)	1980s	BM06-RRB1
EST/1/2/16/6	Photograph of front exterior of Trafalgar House, Edinburgh Road with neighbouring Park Tavern and Shipwrights Arms Public Houses Undated B/W 90mm x 140mm (1 photograph)	1980s	BM06-RRB1

Reference	Description	Date	Shelf Mark
EST/1/2/16/7	Photograph of front exterior of [old] Rees Hall taken from Duisberg Way Undated B/W 90mm x 140mm (1 photograph)	1980s	BM06-RRB1
EST/1/2/16/8	Photograph of front exterior of garages with a car on the wall on the left [future site of Richmond Building?] Undated B/W 90mm x 140mm (1 photograph)	1980s	BM06-RRB1
EST/1/2/16/9	Photograph of front and side exterior of building with street sign reading 'Purbeck Street' Undated B/W 90mm x 140mm (1 photograph)	1980s	BM06-RRB1
EST/1/2/16/10	Photograph of exterior of unidentified building [Portsea?] Undated B/W 90mm x 140mm (1 photograph)	1980s	BM06-RRB1
EST/1/2/16/11	Photograph of side exterior of Park Building taken from King Henry I Street with Guildhall Clock visible on right Undated B/W 90mm x 140mm (1 photograph)	1980s	BM06-RRB1
EST/1/2/16/12	Photograph of exterior of building adjacent to Park Building with cars parked in the foreground Undated B/W 90mm x 140mm (1 photograph)	1980s	BM06-RRB1
EST/1/2/16/13	Photograph of exterior of Cambridge building with Sign for Department of Land and Construction Management Undated B/W 90mm x 140mm (1 photograph)	1980s	BM06-RRB1

Reference	Description	Date	Shelf Mark
EST/1/2/17	Various University of Portsmouth Buildings 2	1998	
EST/1/2/17/1	Photographic negatives of various University of Portsmouth buildings [21-22 May 1998] B/W 40mmx150mm Former Ref: EST/1/4/40 (1 strip of negatives)	1998	BM06-RRB1
EST/1/2/17/2	Photograph of Cambridge Building with Mercantile House visible in the background 21 May 1998 100mmx150mm Former Ref: EST/1/4/48 [appears on negative EST/1/2/17/1] (1 photograph)	1998	BM06-RRB1
EST/1/2/17/3	Photograph of the side exterior of Cambridge Building with two windows open and Mercantile House visible in the background 21 May 1998 100mmx150mm Former Ref: EST/1/4/43 [appears on negative EST/1/2/17/1] (1 photograph)	1998	BM06-RRB1
EST/1/2/17/4	Photograph of the side exterior of The Stables part of Gun House in Ravelin Park with Mercantile House visible in the background 21 May 1998 100mmx150mm Former Ref: EST/1/4/45 [appears on negative EST/1/2/17/1] (1 photograph)	1998	BM06-RRB1
EST/1/2/17/5	Photograph of the Rotunda in Ravelin Park 21 May 1998 100mmx150mm Former Ref: EST/1/4/46 [appears on negative EST/1/2/17/1] (1 photograph)	1998	BM06-RRB1

Reference	Description	Date	Shelf Mark
EST/1/2/17/7	<p>Photograph of the side exterior of the former stables at Ravelin House with a black car parked on the right</p> <p>22 May 1998</p> <p>100mmx150mm</p> <p>Former Ref: EST/1/4/70</p> <p>[appears on negative EST/1/2/17/1]</p> <p>(1 photograph)</p>	1998	BM06-RRB1
EST/1/2/17/6	<p>Photograph of the exterior of the former stables at Ravelin House</p> <p>22 May 1998</p> <p>100mmx150mm</p> <p>Former Ref: EST/1/4/53</p> <p>[appears on negative EST/1/2/17/1]</p> <p>(1 photograph)</p>	1998	BM06-RRB1
EST/1/2/17/8	<p>Photograph of front exterior of Wiltshire Building with Charter House and side of St Andrews Court visible in the background</p> <p>22 May 1998</p> <p>100mmx150mm</p> <p>Former Ref: EST/1/4/51</p> <p>[appears on negative EST/1/2/17/1]</p> <p>(1 photograph)</p>	1998	BM06-RRB1

Reference	Description	Date	Shelf Mark
EST/1/2/18	Bikeabout scheme?	1990s?	
EST/1/2/18/1	Contact sheet with 12 photographs of people on bicycles at Anglesea Crossing and outside the Nuffield Centre Undated 200mmx250mm Former Ref: EST/1/4/34 (1 contact sheet)	1990s?	BM08-RRA1
EST/1/2/18/2	Photograph of four women with bicycles standing in the University of Portsmouth Nuffield Centre car park with Mercantile House in the background [Image appears on contact sheet EST/1/2/18/1] Undated 150mmx200mm (1 photograph)	1990s?	BM08-RRA1
EST/1/2/18/3	Photograph of two men on bicycles in the entrance to the Nuffield Centre with Mercantile House visible in the background with a note on the reverse of the photograph reading: 'Darryl Newton & Greg Brown (blue + white helmet)' [Image appears on contact sheet EST/1/2/18/1] Undated 150mmx200mm (1 photograph)	1990s?	BM08-RRA1
EST/1/2/18/4	Photograph of a large group of people on bicycles outside the University of Portsmouth Nuffield Centre [Image appears on contact sheet EST/1/2/18/1] Undated 150mmx200mm (1 photograph)	1990s?	BM08-RRA1
EST/1/2/18/5	Photograph of a large group people on bicycles outside the University of Portsmouth Nuffield Centre raising their arms [Image appears on contact sheet EST/1/2/18/1] Undated 150mmx200mm (1 photograph)	1990s?	BM08-RRA1

Reference	Description	Date	Shelf Mark
EST/1/2/19	Langstone Campus views	1990s	
EST/1/2/19/1	Photograph of view from Barnard Tower looking North towards Langstone Student Village and Trust Hall Undated 100mmx150mm Former Ref: EST/1/4/50 (1 photograph)	1990s	BM06-RRB1
EST/1/2/19/2	Photograph of view from Barnard Tower looking North East across playing fields and Langstone Harbour Undated 130mmx180mm Former Ref: EST/1/4/54 (1 photograph)	1990s	BM06-RRB1
EST/1/2/19/3	Photograph of view from Barnard Tower looking East across playing fields and Langstone Harbour Undated 130mmx180mm Former Ref: EST/1/4/58 (1 photograph)	1990s	BM06-RRB1
EST/1/2/19/4	Photograph of view from Barnard Tower looking South East towards playing fields, Langstone Harbour and Longshore Way Undated 180mmx130mm Former Ref: EST/1/4/55 (1 photograph)	1990s	BM06-RRB1
EST/1/2/19/5	Photograph of a view from Barnard Tower looking South East towards playing fields Langstone Harbour and Longshore Way Undated 130mmx180mm Former Ref: EST/1/4/60 (1 photograph)	1990s	BM06-RRB1

Reference	Description	Date	Shelf Mark
EST/1/2/19/6	Photograph of view from Barnard Tower at Langstone looking South across Portsmouth Undated 130mmx180mm Former Ref: EST/1/4/59 (1 photograph)	1990s	BM06-RRB1
EST/1/2/19/7	Photograph of view from Barnard Tower at Langstone looking South across Portsmouth Undated 130mmx180mm Former Ref: EST/1/4/61 (1 photograph)	1990s	BM06-RRB1
EST/1/2/19/8	Photograph of view from Barnard Tower at Langstone looking South West across playing fields and Portsmouth Undated 130mmx180mm Former Ref: EST/1/4/56 (1 photograph)	1990s	BM06-RRB1

Reference	Description	Date	Shelf Mark
EST/1/3	Albums	1990s	
EST/1/3/1	<p>Album [self-adhesive] containing photographs of various 1990s University of Portsmouth buildings [some duplication with images in PHOT Central Photographic Section Collection] All photographs in colour with printed captions</p> <p>1/ Aerial view of University buildings including Park Building, King Henry Building, St Michaels Building, Mercantile House, Nuffield, Cambridge Building, Anglesea Building, Burnaby Building and Portland Building</p> <p>2/ Front exterior view of University House</p> <p>3/ Front exterior view of St. Michael's Building</p> <p>4/ Front exterior view of King Henry Building</p> <p>5/ Front exterior view of Park Building</p> <p>6/ Aerial view of Ravelin Park including Alexandra House, Rotunda, Town Mount, Cambridge Building and Frewen Library</p> <p>7/ Front exterior view of Mercantile House with one man on a bike</p> <p>8/ Front exterior view of Town Mount</p> <p>9/ Front exterior of Gun House [elevated view]</p> <p>10/ Aerial view of Nuffield Centre covered in snow</p> <p>11/ Aerial view of Frewen Library taken at night</p> <p>12/ Front exterior view of Harry Law Hall</p> <p>13/ Front exterior view of Bateson Hall</p> <p>14/ Exterior view of 141 High Street [later St Georges Building] with the sea visible in the background - view from Mercantile House</p> <p>15/ Front exterior view of Milldam block taken from courtyard</p> <p>16/ Aerial view of University buildings with Portland Building in the centre of the photograph also including Burnaby Building, Anglesea Building, Lion Gate Building, King Henry Building, St Michael's Building and Park Building</p> <p>17/ Exterior view of Portland Building at night</p> <p>18/ Front exterior of Buckingham Building with students and Argonaut sculpture in the foreground</p> <p>19/ Front exterior of Lion Gate Building from courtyard</p> <p>20/ Elevated view of Anglesea Building with Burnaby Building visible in background</p>		AM01

Reference	Description	Date	Shelf Mark
	21/ Front exterior of Burnaby Building with Argonaut sculpture in foreground		
	22/ Front exterior of [new] Rees Hall		
	23/ Side exterior of Burrell House		
	24/ Aerial view of Milton site including former College of Education buildings		
	25/ Aerial view of Milton site including former College of Education buildings		
	26/ Aerial view of Langstone site with Langstone Student Village in the centre		
	27/ Front exterior of Langstone Centre with a sign reading 'Portsmouth Management Centre'		
	28/ Front exterior of Langstone Halls of Residence		
	29/ Front exterior of Langstone Halls of Residence		
	30/ Side/rear exterior of Langstone Halls of Residence		
	31/ Langstone Halls of Residence taken from across the water in Ferry Road, Eastney		
	Undated		
	(1 album)		

Reference	Description	Date	Shelf Mark
EST/1/3/2	<p>Album containing photographs of Park Building New Lecture Theatre compiled by Norwest Holst Construction Ltd.</p> <p>Copyright: Norwest Holst Construction Ltd.?</p> <p>All photographs in colour and glued to sheets of A4 headed notepaper</p> <p>1/ Exterior gate to car park outside Park Building - view from King Henry I Street</p> <p>2/ Interior room in Park Building with building materials and a dustbin on the floor</p> <p>3/ Interior Upper Hall in Park Building with a black wire running across the wall</p> <p>4/ Interior Upper Hall in Park Building with a wooden broom propped against the wall</p> <p>5/ Interior Upper Hall in Park Building with metal supports across the room</p> <p>6/ Interior Upper Hall Park Building with metal supports across ceiling</p> <p>7/ Interior Upper Hall in Park Building with metal supports across room</p> <p>8/ Interior Upper Hall in Park Building close up of metal supports across room</p> <p>9/ Interior Upper Hall in Park Building with a workman sat on [lockers?] under a metal frame</p> <p>10/ Interior Upper Hall in Park Building – area under metal frame</p> <p>11/ Interior Upper Hall in Park Building with two workmen standing under a metal frame</p> <p>12/ Interior Upper Hall in Park Building with two men working on a raised platform at far end of room</p> <p>13/ Interior Upper Hall in Park Building – close up of raised area of new lecture theatre under construction</p> <p>14/ Interior Upper Hall in Park Building – close up of raised area of new lecture theatre under construction</p> <p>15/ Interior Upper Hall in Park Building – close up of raised area of new lecture theatre under construction</p> <p>16/ Interior Upper Hall in Park Building with metal seating frame under construction</p> <p>17/ Interior Upper Hall in Park Building with metal seating frame under construction – view from raised end</p> <p>18/ Interior Upper Hall in Park Building – view from below stairs</p> <p>19/ Interior Upper Hall in Park Building – view from top of stairs with a cable trailing down</p>	Jun – Sep 1999	BM07-RRB1

Reference	Description	Date	Shelf Mark
	20/ Interior Upper Hall in Park Building – close up of metal seating frame		
	21/ Interior Upper Hall in Park Building – lobby area to new lecture theatre under construction		
	22 Interior Upper Hall in Park Building new stairs under construction		
	23/ Interior Upper Hall in Park Building – part of new lecture theatre construction site in close up		
	24/ Interior Upper Hall in Park Building – lobby area to new lecture theatre		
	25/ Interior Upper Hall in Park Building – lobby area to new lecture theatre		
	26/ Interior Upper Hall in Park Building – stairs in lobby to new lecture theatre in close up		
	27/ Interior Upper Hall in Park Building – stairs in lobby to new lecture theatre in close up		
	28/ Interior Upper Hall in Park Building - view from top of new seating towards front of room		
	29/ Interior Upper Hall in Park Building – area at front of new lecture theatre		
	30/ Interior Upper Hall in Park Building – area at front of new lecture theatre under construction		
	31/ Interior Upper Hall in Park Building - door at back of new lecture theatre on raised seating		
	32/ Interior Upper Hall in Park Building - view from seating towards raised back of room		
	33/ Interior Upper Hall in Park Building – view of front of new lecture theatre		
	34/ Interior Upper Hall in Park Building – view downwards from seating towards screen		
	35/ Interior landing in Park Building		
	36/ Interior stairwell in Park Building taken from top of the stairs looking through an archway		
	37/ Interior Upper Hall in Park Building – view of seating from front of new lecture theatre		
	38/ Interior Upper Hall in Park Building – podium in new lecture theatre		
	39/ Close up of two metal wheels [formerly part of lift?] in Park Building		
	40/ Close up of old part of lift in Park Building		
	41/ Interior staircase in Park Building looking down staircase		
	42/ Interior staircase in Park Building looking down		
	June 1999 – September 1999 (1 album)		

Reference	Description	Date	Shelf Mark
EST/1/4	Miscellaneous loose photographic prints	1970s-2000s	
	Untitled photographs found loose in the bottom of a box – including likely strays from other files and series in this collection.		
EST/1/4/1	Photograph of St Paul's Building looking North West down St Paul's Road with note on the reverse reading 'Polytechnic Drill Hall' 25 September 1972 Photographer: City of Portsmouth Engineer's Department B/W 170mm x 210mm Former Ref: EST/1/4/97 (1 photograph)	1972	BM08-RR1
EST/1/4/2	Photograph of an aerial view centring on Anglesea Building, Park Building and King Henry Building with Burnaby Building; Mercantile House; Nuffield Centre; Cambridge Buildings; Ravelin House; and Alexandra House [St Michaels Building and Central Library not yet constructed] B/W 200mm x 250mm Former Ref: EST/1/4/91 (1 photograph)	[early 1970s]	BM08-RR1
EST/1/4/3	Photograph of an aerial view of Portsmouth including Rees Hall; Frewen Library; Ravelin House; Town Mount; Cambridge Building; Alexandra House; Burrell House; Mercantile House; Park Building; Anglesea Building; and Burnaby Building 'Approx. 1983' written on reverse 130mm x 180mm Former Ref: EST/1/4/28 (1 photograph)	[1983]	BM08-RR1
EST/1/4/4	Photograph of aerial view of Portsmouth including Rees Hall; Frewen Library; Nuffield Centre; Mercantile House; St Michael's Building; King Henry Building and Anglesea Building with 'Approx. 1983' written on reverse 130mm x 170mm Former Ref: EST/1/4/33 (1 photograph)	[1983]	BM08-RR1

Reference	Description	Date	Shelf Mark
EST/1/4/5	<p>Photograph of an aerial view of Portsmouth including Rees Hall</p> <p>‘Approx. 1983’ written on reverse</p> <p>130mm x 180mm</p> <p>Former Ref: EST/1/4/30</p> <p>(1 photograph)</p>	[1983]	BM08-RR1
EST/1/4/6	<p>Photograph of an aerial view of Southsea showing Dartmouth Mews under construction behind Burrell House also including Rees Hall</p> <p>‘Approx. 1985’ written on reverse</p> <p>150mm x 210mm</p> <p>Former Ref: EST/1/4/23</p> <p>(1 photograph)</p>	[1985]	BM08-RR1
EST/1/4/7	<p>Photograph of the front exterior of the King’s Rooms, Bellevue Terrace with cars parked outside</p> <p>‘Approx. 1970s’ written on reverse</p> <p>B/W 130mm x 180mm</p> <p>Former Ref: EST/1/4/29</p> <p>(1 photograph)</p>	1970s	BM08-RR1
EST/1/4/8	<p>Photograph of the front exterior of Rees Hall</p> <p>August 1979</p> <p>110mm x 130mm</p> <p>Former Ref: EST/1/4/31</p> <p>(1 photograph)</p>	1979	BM08-RR1
EST/1/4/9	<p>Photograph of the front exterior of Rees Hall with cars parked outside</p> <p>1983</p> <p>B/W 150mm x 200mm</p> <p>Former Ref: EST/1/4/24</p> <p>(1 photograph)</p>	1983	BM08-RR1
EST/1/4/10	<p>Formal group photograph of residents of Rees Hall standing and seated on Southsea Common with ‘June 1989’ written on reverse</p> <p>200mm x 300mm</p> <p>Former Ref: EST/1/4/32</p> <p>(1 photograph)</p>	1989	BM08-RR1

Reference	Description	Date	Shelf Mark
EST/1/4/11	Photograph of the front exterior of Rees Hall with 'Southsea Terrace' street sign in the foreground 1991 B/W 150mm x 200mm Former Ref: EST/1/4/25 (1 photograph)	1991	BM08-RR1
EST/1/4/12	Photograph of a crane and Portland Building under construction Undated 170mm x 210mm Former Ref: EST/1/4/94 (1 photograph)	[1995]	BM08-RR1
EST/1/4/13	Photograph of exterior of Portland Building in the dark with exterior lights on and two trees in foreground Undated 200mm x 260mm Former Ref: EST/1/4/14 (1 photograph)	[1996]	BM08-RR1
EST/1/4/14	Photograph of men in hard hats stood in Portland Building looking upwards with Vice Chancellor Professor John Craven centre Undated 170mm x 210mm Former Ref: EST/1/4/93 (1 photograph)	[1996]	BM08-RR1
EST/1/4/15	Photograph of interior hall of Portland Building with wooden tables and chairs and grey display boards Undated 170mm x 210mm Former Ref: EST/1/4/15 (1 photograph)	[1996]	BM08-RR1
EST/1/4/16	Photograph of interior hallway of Portland Building - View towards upper floor and roof Undated 200mm x 260mm Former Ref: EST/1/4/18 (1 photograph)	[1996]	BM08-RR1

Reference	Description	Date	Shelf Mark
EST/1/4/17	<p>Photograph of an architectural model of Portland Building with 2/18 written on the back of the photograph</p> <p>Undated</p> <p>130mm x 180mm</p> <p>Former Ref: EST/1/4/75</p> <p>(1 photograph)</p>	1990s	BM08-RRA1
EST/1/4/18	<p>Photograph of aerial view of Portland Building</p> <p>Undated</p> <p>190mm x 240mm</p> <p>Former Ref: EST/1/4/41</p> <p>(1 photograph)</p>	1990s	BM08-RRA1
EST/1/4/19	<p>Photograph of rotten white wooden skirting with an orange screwdriver embedded in it</p> <p>unidentified building</p> <p>20 November 1997</p> <p>100mm x 150mm</p> <p>Former Ref: EST/1/4/47</p> <p>[Stray from EST/1/1/5 Poor Estate]</p> <p>(1 photograph)</p>	1997	BM08-RRA1
EST/1/4/20	<p>Photograph of the exterior of an unidentified wooden hut in close up</p> <p>20 November 1997</p> <p>130mm x 180mm</p> <p>Former Ref: EST/1/4/71</p> <p>[Stray from EST/1/1/5 Poor Estate]</p> <p>(1 photograph)</p>	1997	BM08-RRA1
EST/1/4/21	<p>Photograph of the exterior of an unidentified building with damaged paintwork</p> <p>20 November 1997</p> <p>100mm x 150mm</p> <p>Former Ref: EST/1/4/72</p> <p>[Stray from EST/1/1/5 Poor Estate]</p> <p>(1 photograph)</p>	1997	BM08-RRA1

Reference	Description	Date	Shelf Mark
EST/1/4/22	<p>Photograph of the front exterior of [Burnaby Huts?] with green double doors and skirting 21 November 1997 100mm x 150mm Former Ref: EST/1/4/74 [Stray from EST/1/1/5 Poor Estate] (1 photograph)</p>	1997	BM08-RR1
EST/1/4/23	<p>Photograph of the side exterior of [Burnaby Huts?] with a blue container on the left 21 Nov 1997 100mmx150mm Former Ref: EST/1/4/44 [Stray from EST/1/1/5 Poor Estate] (1 photograph)</p>	1997	BM08-RR1
EST/1/4/24	<p>Photograph of an orange screwdriver embedded in a white window frame 16 November 2002 100mm x 150mm Former Ref: EST/1/4/49 [Stray from EST/1/1/5 Poor Estate] (1 photograph)</p>	[1997]	BM08-RR1
EST/1/4/25	<p>Photograph of an orange screwdriver embedded in the wall of an unidentified building with white window frames Undated 100mm x 150mm Former Ref: EST/1/4/73 [Stray from EST/1/1/5 Poor Estate] (1 photograph)</p>	2002	BM08-RR1
EST/1/4/26	<p>Photograph of front and side exterior of an architectural model of St Michael's Building Undated 160mmx200mm Former Ref: EST/1/4/42 (1 photograph)</p>	1990s	BM08-RR1
EST/1/4/27	<p>Photograph of the front exterior of St Michael's Building and University of Portsmouth signage Undated 100mm x 150mm Former Ref: EST/1/4/17 (1 photograph)</p>	1990s	BM08-RR1

Reference	Description	Date	Shelf Mark
EST/1/4/28	<p>Photograph of an aerial view of site of Harry Law Hall prior to construction also including Eldon Building and 'Jimmyz' later the site of Trafalgar Halls</p> <p>Undated</p> <p>170mmx210mm</p> <p>Former Ref: EST/1/4/95</p> <p>(1 photograph)</p>	1990s	BM08-RR1
EST/1/4/29	<p>Photograph of Harry Law Hall with Bateson Hall visible on the left</p> <p>Undated</p> <p>200mm x 250mm</p> <p>Former Ref: EST/1/4/21</p> <p>(1 photograph)</p>	[1995]	BM08-RR1
EST/1/4/30	<p>Photograph of a lecture theatre with black seating [Portland Building?]</p> <p>Undated</p> <p>100mm x 150mm</p> <p>Former Ref: EST/1/4/22</p> <p>(1 photograph)</p>	1990s	BM08-RR1
EST/1/4/31	<p>Photograph of a sink with two white cabinets beneath and a mirror above in an unknown building [Langstone Campus?]</p> <p>Undated</p> <p>130mmx180mm</p> <p>Former Ref: EST/1/4/57</p> <p>(1 photograph)</p>	1990s	BM08-RR1
EST/1/4/32	<p>Photograph of a white stairwell in Ravelin House?</p> <p>Undated</p> <p>180mmx130mm</p> <p>Former Ref: EST/1/4/52</p> <p>(1 photograph)</p>	1990s	BM08-RR1
EST/1/4/33	<p>Photograph of an empty interior room in Ravelin House? with a white door on the right and [cardboard?] on the floor</p> <p>Undated</p> <p>130mmx180mm</p> <p>Former Ref: EST/1/4/62</p> <p>(1 photograph)</p>	1990s	BM08-RR1

Reference	Description	Date	Shelf Mark
EST/1/4/34	Photograph of an interior bathroom in Ravelin House? with yellow walls and a white sink Undated 130mmx180mm Former Ref: EST/1/4/63 (1 photograph)	1990s	BM08-RR1
EST/1/4/35	Photograph of an empty interior room in Ravelin House? with a fireplace Undated 130mmx180mm Former Ref: EST/1/4/64 (1 photograph)	1990s	BM08-RR1
EST/1/4/36	Photograph of an empty interior room in Ravelin House? with a fireplace and a white cabinet and bookshelf Undated 130mmx180mm Former Ref: EST/1/4/65 (1 photograph)	1990s	BM08-RR1
EST/1/4/37	Photograph of an interior room in Ravelin House? with two brown doors and lengths of white plastic on the floor Undated 130mmx180mm Former Ref: EST/1/4/66 (1 photograph)	1990s	BM08-RR1
EST/1/4/38	Photograph of an interior room in Ravelin House? with piles of cables on the floor Undated 130mmx180mm Former Ref: EST/1/4/67 (1 photograph)	1990s	BM08-RR1
EST/1/4/39	Photograph of an interior room in Ravelin House? with a torn out brick fireplace Undated 130mmx180mm Former Ref: EST/1/4/68 (1 photograph)	1990s	BM08-RR1

Reference	Description	Date	Shelf Mark
EST/1/4/40	<p>Photograph of an interior hallway in Ravelin House taken from the stairs with double yellow doors marked 'Institute of Police and Criminological Studies'</p> <p>Undated</p> <p>130mmx180mm</p> <p>Former Ref: EST/1/4/69</p> <p>(1 photograph)</p>	1990s	BM08-RR1
EST/1/4/41	<p>Photograph of three unidentified men stood outside a shower room with a seat in it</p> <p>Undated</p> <p>170mmx210mm</p> <p>Former Ref: EST/1/4/76</p> <p>(1 photograph)</p>	1990s	BM08-RR1
EST/1/4/42	<p>Photograph of the 'Argonaut' sculpture partially covered in protective plastic being lowered in place by a crane outside Buckingham Building with a man stood next to it holding a camera</p> <p>Undated</p> <p>B/W 200mmx250mm</p> <p>Former Ref: EST/1/4/92</p> <p>(1 photograph)</p>	1990s	BM08-RR1
EST/1/4/43	<p>Photograph of the exterior of Portland Building, Buckingham Building covered in scaffolding and 'Argonaut' sculpture</p> <p>Undated</p> <p>B/W 170mmx210mm</p> <p>Former Ref: EST/1/4/83</p> <p>(1 photograph)</p>	1990s	BM08-RR1
EST/1/4/44	<p>Photograph of St Georges Way and junction with Kent Street, Portland Street, and St James Street with Portland Building visible on the left [prior to building of Richmond Building]</p> <p>Undated</p> <p>B/W 170mmx210mm</p> <p>Former Ref: EST/1/4/84</p> <p>(1 photograph)</p>	1990s	BM08-RR1

Reference	Description	Date	Shelf Mark
EST/1/4/45	<p>Photograph of Lion Terrace prior to development of Richmond Building looking down Richmond Place with Milldam visible on left</p> <p>Undated</p> <p>B/W 200mmx240mm</p> <p>Former Ref: EST/1/4/85</p> <p>(1 photograph)</p>	1990s	BM08-RRA1
EST/1/4/46	<p>Photograph of St Georges Way with Portland Building visible on the right prior to the development of Richmond Building [garages appear on the future Richmond Building site]</p> <p>Undated</p> <p>B/W 170mmx210mm</p> <p>Former Ref: EST/1/4/86</p> <p>(1 photograph)</p>	1990s	BM08-RRA1
EST/1/4/47	<p>Photograph of the exterior of Buckingham Building from Hay Street</p> <p>Undated</p> <p>B/W 170mmx210mm</p> <p>Former Ref: EST/1/4/87</p> <p>(1 photograph)</p>	1990s	BM08-RRA1
EST/1/4/48	<p>Photograph of the 'Argonaut' sculpture with Burnaby Building in the background</p> <p>Undated</p> <p>170mmx210mm</p> <p>Former Ref: EST/1/4/89</p> <p>(1 photograph)</p>	1990s	BM08-RRA1
EST/1/4/49	<p>Photograph of the front exterior of Buckingham Building with the 'Argonaut' sculpture</p> <p>Undated</p> <p>170mmx210mm</p> <p>Former Ref: EST/1/4/90</p> <p>(1 photograph)</p>	1990s	BM08-RRA1
EST/1/4/50	<p>Photograph of 'Argonaut' sculpture and Richmond House later the site of Richmond Building</p> <p>Undated</p> <p>200mmx300mm</p> <p>Former Ref: EST/1/4/96</p> <p>(1 photograph)</p>	1990s	BM08-RRA1

Reference	Description	Date	Shelf Mark
EST/1/4/51	<p>Photograph of a woman standing at a computer in a room with red and blue lighting</p> <p>Undated</p> <p>170mmx210mm</p> <p>Former Ref: EST/1/4/77</p> <p>(1 photograph)</p>	1990s	BM08-RR1
EST/1/4/52	<p>Photograph of a man looking at a see through sheet of plastic with the University of Portsmouth logo on with red, blue and green lighting to image</p> <p>Undated</p> <p>170mmx210mm</p> <p>Former Ref: EST/1/4/78</p> <p>(1 photograph)</p>	c1992	BM08-RR1
EST/1/4/53	<p>Photograph of a woman sat at a desk in an office with aerial photographs of Portsmouth and photographs of Portland Building on the wall behind her</p> <p>Undated</p> <p>170mmx210mm</p> <p>Former Ref: EST/1/4/79</p> <p>(1 photograph)</p>	1990s	BM08-RR1
EST/1/4/54	<p>Photograph of a woman using a computer at a desk [same photograph also appears in PHOT collection]</p> <p>Undated</p> <p>170mmx210mm</p> <p>Former Ref: EST/1/4/80</p> <p>(1 photograph)</p>	1990s	BM08-RR1
EST/1/4/55	<p>Photograph of a man using machinery and looking at a document entitled 'University Circular: Information Strategy' with yellow and green lighting</p> <p>Undated</p> <p>170mmx210mm</p> <p>Former Ref: EST/1/4/81</p> <p>(1 photograph)</p>	1990s	BM08-RR1
EST/1/4/56	<p>Photograph of a man holding a telephone standing next to a woman sat at a desk using a computer</p> <p>Undated</p> <p>170mmx210mm</p> <p>Former Ref: EST/1/4/82</p> <p>(1 photograph)</p>	1990s	BM08-RR1

Reference	Description	Date	Shelf Mark
EST/1/4/57	<p>Photograph of HMS Victory with a figurehead in the foreground</p> <p>Undated</p> <p>200mm x 250mm</p> <p>Former Ref: EST/1/4/19</p> <p>(1 photograph)</p>	1990s	BM08-RR1
EST/1/4/58	<p>Photograph of the figurehead of HMS Victory</p> <p>Undated</p> <p>150mm x 290mm</p> <p>Former Ref: EST/1/4/20</p> <p>(1 photograph)</p>	1990s	BM08-RR1
EST/1/4/59	<p>Photograph of H.M.S. Warrior figurehead</p> <p>Undated</p> <p>100mm x 150mm</p> <p>Former Ref: EST/1/4/16</p> <p>(1 photograph)</p>	1990s	BM08-RR1
EST/1/4/60	<p>Photographic reproduction of an illustration [from a postcard?] of Southsea Common with Royal Pier Hotel [later Rees Hall] visible in the background</p> <p>Undated</p> <p>Original source unknown</p> <p>B/W 150mmx210mm</p> <p>Former Ref: EST/1/4/26</p> <p>(1 photograph)</p>	[original 19 th century]	BM08-RR1
EST/1/4/61	<p>Photographic reproduction of an illustration of Government House later the site of the University Library with caption 'Government House: Residence of H.R.H. the Duke of Connaught'</p> <p>Undated</p> <p>Original source unknown</p> <p>B/W 150mmx210mm</p> <p>Former Ref: EST/1/4/27</p> <p>(1 photograph)</p>	n.d.	BM08-RR1

Reference	Description	Date	Shelf Mark
EST/1/5	Slides	1990s	
EST/1/5/1	Slide of PowerPoint presentation with University of Portsmouth Logo Undated (1 colour slide)	1990s	AM02-RR1
EST/1/5/2	Slide of PowerPoint presentation with explanation about Bikeabout scheme Undated (1 colour slide)	1990s	AM02-RR1
EST/1/5/3	Slide of PowerPoint presentation with history of Bikeabout scheme Undated (1 colour slide)	1990s	AM02-RR1
EST/1/5/4	Slide of PowerPoint presentation with questions about why Bikeabout is coming to University of Portsmouth Undated (1 colour slide)	1990s	AM02-RR1
EST/1/5/5	Slide of PowerPoint presentation with aerial view of Portsea Island Undated (1 colour slide)	1990s	AM02-RR1
EST/1/5/6	Slide of PowerPoint presentation with a photograph of Tour De France Undated (1 colour slide)	1990s	AM02-RR1
EST/1/5/7	Slide of PowerPoint presentation with a map of Portsea Island with Guildhall Square, Milton Campus and Langstone Campus in red squares Undated (1 colour slide)	1990s	AM02-RR1
EST/1/5/8	Slide of old photograph of Clarence Esplanade including a cyclist Undated (1 black and white slide)	[1920s]	AM02-RR1

Reference	Description	Date	Shelf Mark
EST/1/5/9	Slide of PowerPoint with a photograph of Clarence Esplanade with traffic [same view as EST/1/5/8] Undated (1 colour slide)	1990s	AM02-RR1
EST/1/5/10	Slide of PowerPoint presentation explaining how Bikeabout works Undated (1 colour slide)	1990s	AM02-RR1
EST/1/5/11	Slide of PowerPoint presentation explaining how Bikeabout works Undated (1 colour slide)	1990s	AM02-RR1
EST/1/5/12	Slide of PowerPoint explaining presentation how Bikeabout works Undated (1 colour slide)	1990s	AM02-RR1
EST/1/5/13	Slide of PowerPoint presentation with a photograph of the Bikeabout bicycle sheds Undated (1 colour slide)	1990s	AM02-RR1
EST/1/5/14	Slide of PowerPoint presentation with a photograph of someone using the Bikeabout system Undated (1 colour slide)	1990s	AM02-RR1
EST/1/5/15	Slide of PowerPoint presentation with a photograph of someone retrieving a bicycle from Bikeabout Undated (1 colour slide)	1990s	AM02-RR1
EST/1/5/16	Slide of PowerPoint presentation explaining how Bikeabout is used using statistics Undated (1 colour slide)	1990s	AM02-RR1
EST/1/5/17	Slide of PowerPoint presentation with photograph of someone riding a bicycle in Guildhall Square Undated (1 colour slide)	1990s	AM02-RR1

Reference	Description	Date	Shelf Mark
EST/1/5/18	Slide of PowerPoint presentation explaining how much Bikeabout costs to run Undated (1 colour slide)	1990s	AM02-RR1
EST/1/5/19	Slide of PowerPoint presentation explaining the potential problems with using Bikeabout Undated (1 colour slide)	1990s	AM02-RR1
EST/1/5/20	Slide of PowerPoint presentation with photograph showing cars parked in front of Bikeabout sheds Undated (1 colour slide)	1990s	AM02-RR1
EST/1/5/21	Slide of PowerPoint presentation with photograph of bicycles chained up outside of Langstone Student Village Undated (1 colour slide)	1990s	AM02-RR1
EST/1/5/22	Slide of PowerPoint presentation discussing the progression of Bikeabout in the future Undated (1 colour slide)	1990s	AM02-RR1
EST/1/5/23	Slide of PowerPoint presentation with photograph of people on bicycles using a cycle lane Undated (1 colour slide)	1990s	AM02-RR1
EST/1/5/24	Slide of PowerPoint presentation discussing what still needs to be done [in relation to Bikeabout?] Undated (1 colour slide)	1990s	AM02-RR1
EST/1/5/25	Slide of PowerPoint presentation outlining the achievements to date [in relation to Bikeabout?] Undated (1 colour slide)	1990s	AM02-RR1
EST/1/5/26	Slide of PowerPoint presentation outlining the achievements to date [in relation to Bikeabout?] Undated (1 colour slide)	1990s	AM02-RR1

Reference	Description	Date	Shelf Mark
EST/1/5/27	Slide of PowerPoint presentation discussing space utilisation and maintenance [in relation to Bikeabout?] Undated (1 colour slide)	1990s	AM02-RR1
EST/1/5/28	Slide of PowerPoint presentation discussing space Management [in relation to Bikeabout?] Undated (1 colour slide)	1990s	AM02-RR1
EST/1/5/29	Slide of PowerPoint presentation with the names 'Dr. Mike Bateman' and 'Patrick Finch' Undated (1 colour slide)	1990s	AM02-RR1
EST/1/5/30	Slide of PowerPoint presentation outlining the historical background of Bikeabout Undated (1 colour slide)	1990s	AM02-RR1
EST/1/5/31	Slide of PowerPoint presentation outlining sources of funding [for Bikeabout?] Undated (1 colour slide)	1990s	AM02-RR1
EST/1/5/32	Slide of PowerPoint presentation listing the benefits and risks of using Bikeabout Undated (1 colour slide)	1990s	AM02-RR1
EST/1/5/33	Slide of PowerPoint presentation outlining the parameters of the estate Undated (1 colour slide)	1990s	AM02-RR1
EST/1/5/34	Slide of PowerPoint presentation outlining the condition of the estate Undated (1 colour slide)	1990s	AM02-RR1
EST/1/5/35	Slide of PowerPoint presentation discussing the expenditure parameters Undated (1 colour slide)	1990s	AM02-RR1

Reference	Description	Date	Shelf Mark
EST/1/5/36	Slide of PowerPoint presentation setting priorities Undated (1 colour slide)	1990s	AM02-RR1
EST/1/5/37	Slide of PowerPoint outlining the development programme from 1992 to 1996 Undated (1 colour slide)	1990s	AM02-RR1
EST/1/5/38	Slide of interior of lecture theatre Undated (1 colour slide)	1990s	AM02-RR1
EST/1/5/39	Slide of interior Park Building Upper Hall with chandeliers hanging from the ceiling and stairs going up to a stage Undated (1 colour slide)	1990s	AM02-RR1
EST/1/5/40	Slide of front exterior of Gun House with trees on the right of the photograph Undated (1 colour slide)	1990s	AM02-RR1
EST/1/5/41	Slide of side exterior of Milldam Building with a tree at the top and left of the photograph Undated (1 colour slide)	1990s	AM02-RR1
EST/1/5/42	Slide of Barnard Tower at Langstone At night Undated (1 colour slide)	1990s	AM02-RR1
EST/1/5/43	Slide of Milldam building taken from the grass outside with trees in front Undated (1 colour slide)	1990s	AM02-RR1
EST/1/5/44	Slide of interior lecture theatre with one person speaking to students Undated (1 black and white slide)	[1980s?]	AM02-RR1

Reference	Description	Date	Shelf Mark
EST/1/5/45	Slide of front exterior of Barnard Tower at Langstone with tree on the right Undated (1 colour slide)	1990s	AM02-RR1
EST/1/5/46	Slide of Park Building Upper Hall with chandeliers hanging from the ceiling and stairs leading to a stage Undated (1 colour slide)	1990s	AM02-RR1
EST/1/5/47	Slide of interior entrance hall of Park Building with double doors on the left and stairs in centre Undated (1 colour slide)	1990s	AM02-RR1
EST/1/5/48	Slide of interior office with two people sat talking at a desk Undated (1 colour slide)	1990s	AM02-RR1
EST/1/5/49	Slide of view of Park Building, King Henry, St Michael's Building etc from height Undated (1 colour slide)	1990s	AM02-RR1
EST/1/5/50	Slide of view of St George's Building from height Undated (1 colour slide)	1990s	AM02-RR1
EST/1/5/51	Slide of interior office with two people working at desks Undated (1 colour slide)	1990s	AM02-RR1
EST/1/5/52	Slide of side exterior Barnard Tower at Langstone Undated (1 colour slide)	1990s	AM02-RR1

Reference	Description	Date	Shelf Mark
EST/1/5/53	Slide of view of Ravelin Park from Mercantile House Including University Library, Cambridge Building and St George's Building Undated (1 colour slide)	1990s	AM02-RR1
EST/1/5/54	Slide of interior bedroom with three windows looking out onto the sea Undated (1 colour slide)	1990s	AM02-RR1
EST/1/5/55	Slide of interior room with wooden tables and brown chairs with three red noticeboards Undated (1 colour slide)	1990s	AM02-RR1
EST/1/5/56	Slide of Learning Resources Centre in Park Building Undated (1 colour slide)	1990s	AM02-RR1
EST/1/5/57	Slide of exterior of Ravelin House Undated (1 colour slide)	1990s	AM02-RR1
EST/1/5/58	Slide of exterior of Trafalgar House with cars parked outside Undated (1 colour slide)	1990s	AM02-RR1
EST/1/5/59	Slide of interior room with someone working at a round table and windows on the right Undated (1 colour slide)	1990s	AM02-RR1
EST/1/5/60	Slide of Learning Resources Centre in Park Building Undated (1 colour slide)	1990s	AM02-RR1
EST/1/5/61	Slide of computer room with one person working Undated (1 colour slide)	1990s	AM02-RR1

Reference	Description	Date	Shelf Mark
EST/1/5/62	Slide of laboratory Undated (1 black and white slide)	[1970s]	AM02-RR1
EST/1/5/63	Slide of interior room with red noticeboards Undated (1 colour slide)	1990s	AM02-RR1
EST/1/5/64	Slide of exterior view of Barnard Tower in Langstone Student Village Undated (1 colour slide)	1990s	AM02-RR1
EST/1/5/65	Slide of interior lecture theatre with a computer on the desk on the bottom left Undated (1 colour slide)	1990s	AM02-RR1
EST/1/5/66	Slide of front exterior of Park Building with people standing outside Undated (1 colour slide)	1990s	AM02-RR1
EST/1/5/67	Slide of front exterior of Park Building with people standing outside Undated (1 black and white slide)	1990s	AM02-RR1
EST/1/5/68	Slide of laying of foundation stone of Park Building [reproduced from postcard – original NOT in University Archive] Undated (1 black and white slide)	1990s	AM02-RR1
EST/1/5/69	Slide of exterior side of Cambridge Building? with trees on the left hand side Undated (1 colour slide)	1990s	AM02-RR1
EST/1/5/70	Slide of front exterior of Gun House with trees on the left Undated (1 colour slide)	1990s	AM02-RR1

Reference	Description	Date	Shelf Mark
EST/1/5/71	Slide of front exterior of Ravelin House Undated (1 colour slide)	1990s	AM02-RR1
EST/1/5/72	Slide of exterior of Barnard Tower in Langstone Student Village Undated (1 colour slide)	1990s	AM02-RR1
EST/1/5/73	Slide of front exterior of Barnard Tower in Langstone Student Village Undated (1 colour slide)	1990s	AM02-RR1
EST/1/5/74	Slide of side exterior of Mercantile House Undated (1 colour slide)	1990s	AM02-RR1
EST/1/5/75	Slide of front exterior of Ravelin House with trees on the top right Undated (1 colour slide)	1990s	AM02-RR1
EST/1/5/76	Slide of front exterior of Ravelin House with trees on the top right Undated (1 colour slide)	1990s	AM02-RR1
EST/1/5/77	Slide of Portsmouth Municipal Technical Institute - reproduction of postcard NOT in University Archive Undated (1 colour slide)	[1900s]	AM02-RR1
EST/1/5/78	Slide of side exterior of Ravelin House Undated (1 colour slide)	1990s	AM02-RR1
EST/1/5/79	Slide of map of Portsmouth with Guildhall campus in a blue square Undated (1 colour slide)	1990s	AM02-RR1

Reference	Description	Date	Shelf Mark
EST/1/5/80	Slide of computer room with a woman with headphones on looking at the computer in front Undated (1 colour slide)	1990s	AM02-RR1
EST/1/5/81	Slide of Mercantile House with cars driving past outside Undated (1 colour slide)	1990s	AM02-RR1
EST/1/1/5/82	Slide of a science laboratory Undated (1 colour slide)	[1970s]	AM02-RR1
EST/1/5/83	Slide of the top of Park Building with Guildhall Clock visible in the background Undated (1 colour slide)	1990s	AM02-RR1
EST/1/5/84	Slide of Milldam taken from the grass outside Undated (1 colour slide)	1990s	AM02-RR1
EST/1/5/85	Slide of Milldam taken from the grass outside Undated (1 colour slide)	1990s	AM02-RR1
EST/1/5/86	Slide of an aerial view of Langstone Undated (1 colour slide)	1990s	AM02-RR1
EST/1/5/87	Slide of a crowded lecture theatre with one person lecturing Undated (1 black and white slide)	[1980s]	AM02-RR1
EST/1/5/88	Slide of an aerial view of Langstone Campus Undated (1 colour slide)	1990s	AM02-RR1

Reference	Description	Date	Shelf Mark
EST/1/5/89	Slide of view of Langstone Campus from Barnard Tower Undated (1 colour slide)	1990s	AM02-RR1
EST/1/5/90	Slide of exterior of Langstone Campus buildings Undated (1 colour slide)	1990s	AM02-RR1
EST/1/5/91	Slide of unidentified room with people sat on chairs at wooden coffee tables talking [St Georges?] Undated (1 colour slide)	1990s	AM02-RR1
EST/1/5/92	Slide of unidentified lecture theatre with padded chairs in rows and a podium on the centre right of the slide Undated (1 black and white slide)	1990s	AM02-RR1
EST/1/5/93	Slide of grounds of Milldam with people sitting on benches talking outside Undated (1 colour slide)	1990s	AM02-RR1
EST/1/5/94	Slide of people sat in the courtyard outside Milldam Undated (1 colour slide)	1990s	AM02-RR1
EST/1/5/95	Slide of a map of Portsmouth with Guildhall Campus in a red square Undated (1 colour slide)	1990s	AM02-RR1
EST/1/5/96	Slide of exterior side view of Mercantile House with a van driving past Undated (1 colour slide)	1990s	AM02-RR1
EST/1/5/97	Slide of front exterior of Park Building with people standing outside Undated (1 colour slide)	1990s	AM02-RR1

Reference	Description	Date	Shelf Mark
EST/1/5/98	Slide of front exterior of King Henry Building with Undated (1 colour slide)	1990s	AM02-RR1

Reference	Description	Date	Shelf Mark
EST/1/6	Photocopies		
EST/1/6/1	Set of b/w photocopied images of photographs of Nuffield United Services Club later the Nuffield Centre under construction [1951?] source/photographer unknown with two images of 'Twilfit House' Farlington May 1950 [Same architect?] with two pages from Evening News 20 July 1951 including an advert for R. J. Winnicott Ltd, Copnor Road 'Builders of Nuffield United Services Club' (27 photocopies)	[originals 1950s]	AM01-RR1
EST/1/6/2	Set of colour photocopies of images of St Michael's Building some of which duplicate photographic images (8 photocopies)	1997	AM01-RR1
EST/1/6/3	Set of colour photocopies of contact sheets of images of Portland Building from top of Sarah Robinson House (2 photocopies)	1990s	AM01-RR1
EST/1/6/4	Set of colour photocopies of RIBA journal article on student union building Nov 2002 (2 photocopies)	2002	AM01-RR1